

TOWNSHIP 24 SOUTH, RANGE 1 WEST, OF THE WILLAMETTE MERIDIAN, OREGON.
DEPENDENT RESURVEY

This plat represents a retracement and reestablishment of the line between sections 5 and 8, designed to restore the corners in their true original locations according to the best available evidence. The resurvey was based on the plat approved August 10, 1897.

The township was subdivided by W. S. Chapman and C. S. Nicklin in 1896.

Dependent resurvey of the line between sections 5 and 8, T. 24 S., R. 1 W., Willamette Meridian, Oregon, executed by William W. Glenn and Rollin D. Aanrud, October 25 to 31, 1963, under Special Instructions dated October 8, 1963, which provide for the surveys included under Group No. 533, Oregon.



Mean
Magnetic
Declination
20° East

Sec. 6 Sec. 5 Sec. 4

$S. 89^{\circ} 43' W.$ $N. 88^{\circ} 41' W.$
 $12.825'$ $19.825'$ $40.81'$ Latitude $43^{\circ} 30.5' N.$
 $39.25'$ Longitude $122^{\circ} 49.1' W.$

Sec. 7 Sec. 8 Sec. 9



UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
Washington, D. C. August 14, 1964

This plat is strictly conformable to the approved field notes, and the survey, having been correctly executed in accordance with the requirements of law and the regulations of this Bureau, is hereby accepted.

For the Director

A handwritten signature in cursive script, appearing to read "E. E. Huntington".

Chief, Division of Engineering

Timber in this area consists of Douglas fir, cedar, white fir, hemlock, alder, maple, chinquapin, yew, and dogwood.