

T24S R6W.

(Ren. #1) June 1915

1/4 Cor bet Secs 27-28 Renew corner from original trees Find Laurel standing and chop marks on stump of oak B.T.

Set Rock 6x14x16 inkt #16 from which A B Oak 12 in dia S 3° W 143 li

Cor to Secs 22-23-26-27. no evidence of B.T.

Set a Rock 8x16x20 for Cor from which

An ash 14 N 17° E 20.3 li.

" " 9. N 5° W 240 "

" " 10 S 82 1/2° E 134

Maple 20 S 20 1/2° W 424.

1/4 Cor bet Secs 23 & 26. no evidence

of old trees. Set rock for corner 6x8x12 no trees near.

Cor Secs 16 17, 20 & 21 Renew Corner from

two original trees other two missing mark. A fir 60 in N 88 1/2° W 53 ft.

" " " 8 " S 7 1/2° W 28 "

1/4 Cor bet 22 & 27. Renew cor from orig.

B.T.s Tree S 18 1/2° W standing other tree down

Set a Cedar post from which

A B Oak 16 " S 32 3/4° E 59 li

" W " 24 " N 87° W 43 "

Fir " 36 " S 42 1/2° W 77 "

Floyd J. Leale Deputy  
M. J. Reggs  
J. Adams  
H. Larkin

(Ren. #2)  
(Ren. #3)

(Ren. #4)

(Ren. #5)

F.C. Frear Dep. Co. Surveyor  
H. L. Epstein  
H. C. Crocker

Oct. 2-19  
(Ren. #6)

Cor. 13-14-23-24 - I set a 6"x12"x24" Sandstone Rock as per old B.T.s all standing except the one in Sec. 14.

I remark old B.T.s. and also 3 new ones as follows:-  
a 10" Fir Bas. West. 1.11 ch C.S.B.T.

a 10" " " North 0.84 ch C.S.B.T.

a 6" " " S. 19 1/2° E. 0.38 ch. C.S.B.T.

F.C. Frear Deputy County Surveyor

J.C. Fear Deputy County Surveyor

Oct. 1-2-1919

✓  $\frac{1}{4}$  Cor. Secs 13 & 24 - Re-established as per  
 ✓ Old B.T.s both standing but badly decayed  
 ✓ Set a 4"x4"x36" Oak Stake from which  
 a 5" W. Oak brs. N.  $55\frac{3}{4}^\circ$  E. 0.17 ch C.S.B.T.  
 a 36" B. " " S.  $17^\circ$  W. 0.105 ch. C.S.B.T.

✓ N.E. Cor. Sec. 24 or Cor. Common to 13-18-19-24  
 ✓ Re-established as per Old B.T.s by setting  
 a 6"x6"x12" Rock & 3"x36" Oak Stake from which  
 a 48" B. Oak brs. N.  $62\frac{1}{4}^\circ$  E. - 0.49 ch. Old B.T.  
 a 48" W. " " S.  $89^\circ$  W. - 1.21 " " B.T.  
 a 10" W. " " N.  $54^\circ$  W. - 0.455 " C.S.B.T.  
 a 12" B. " " S.  $41^\circ$  E. - 0.65 " C.S.B.T.

✓ Cor. 23-24-25-26 - Re-established as per  
 ✓ Old B.T.s by setting a 6"x12"x30" Sandstone  
 from which a 36" W.O. brs S.  $48-55^\circ$  W. 7.03 ch O.B.T.  
 a 36" W.O. brs S.  $11-25^\circ$  E 7.75 ch. Old B.T.

G.G. Spear D.C.S.

Leather wood  
Baird; Barton  
M.S. dug it out  
(REN. #11)

✓  $\frac{1}{4}$  Cor bet. 33 & 34.  
 ✓ Reestablish midway between  $\frac{27-28}{33-34}$  &  $\frac{3-4}{33-34}$   
 ✓ Set Iron Pipe. Marked 74" W. Fir N  $42^\circ$  W  $63^\circ$  ft. 30" Fir S  $66^\circ$  W  $63^\circ$  ft.

✓  $\frac{1}{4}$  Cor bet 34 & 35.  
 ✓ Reset from 1 O.B.T. other tree gone.  
 Set Rock for cor: 16" B.O. N  $25^\circ$  W  $742^\circ$  ft ; 18" Fir N  $6^\circ$  S  $53^\circ$  ft.

U. Baird.  
Barton  
C.C. Shook witness  
(REN. #12)  
3/27/20

✓ Sec. Cor bet 4-5 T 25 S; + 32-33 T 24 S. R 6 W  
 ✓ Reset from one O.B.T. + Stump of O.B.T.  
 ✓ Set steel gun barrel for cor. Marked a 8" Fir N  $69^\circ$  E  $59^\circ$  ft. 12" Fir S  $77^\circ$  E  $58^\circ$  ft.  
 18" barrel S  $22^\circ$  W  $154^\circ$  ft. No other tree suitable

✓  $\frac{1}{4}$  Cor bet. Set, T 24 S R 6 W + 33 T. 25 S R 6 W.  
 ✓ Reestablish midway between section corners.  
 Set Iron Pipe for cor. Marked 30" Fir S  $26^\circ$  E  $12\frac{1}{2}$  ft  
 48" Fir N  $17^\circ$  E  $50^\circ$  ft.

(REN. #13)  
7-29-16