

27-5

Section corner 11, 12, 13 & 14.

Location identified from one original B.T. a 30" W. Oak S 61 1/2° E 450 lks, Also ^{old} stump hole N 86 1/2° E 137 1/16. Set a rock 6" x 12" x 24" in ground for corner marked with x on top, 11 on N.W. face, 13 on S.E face & 14 on S.W. face. Also 4 notches on the South & 1 notch on East

Corners & from which.

- White Oak 6" diam. bears S 37° W 10 ft.
- " " 14" " " N 30 1/2° W 43 ft.
- " " 20" " " N 45° E 89.3 "
- " " 30" " " S 61 1/2° E. 297 " (original B.T.)

1/4 Section Corner Sections 13 & 14.

Location identified from an original tree which was chopped out & found to be in excellent shape S 68° E 173 lks & the stump of a Oak B.T. S 6° W 36 lks. Showing the reverse of the original scribe marks B.T. Drove an iron pipe 3/4" dia. & 36" long 30" in the ground from which an oak 9" dia. bears South 24.3 ft. & an Oak 9" dia. bears N 10° E 33.6 ft.

Ben B Irving D.C.S. with N.E. Richardson R.L. Irving H.L. Epstein Jr. Sept. 30 1939.

SAME

A Boyer D.C.S. Ivan Norris "Bud" Criteser

T27S R6W 3-20-43 (see #50)

SE Cor DLC 56 - This ^{T27S R6W} was previously set for "Bud" Criteser who says it is N 40 1/2° E 77.5 ft. from a 12" Ash tree which is scribed - Set a 3/4" steel bar here & pile rocks - Note: flood has bent ash tree down stream

1/4 Cor. Bet. 18-17

Renewed from B.T. 7" B.Oak N. 38° W. 71 3/4 ft. Set 2" Iron Pipe from which, A B.Oak 8" bears S. 87° E. 140 3/4 ft. slope meas. " " " 14" " S. 76° W. 73 3/4 ft. level

June 8, 1944 A Boyer D.C.S. Darley ware Gordon ware

Sec Cor 3-4-9-10 Set oak Post for Cor - found all B.T.'s except one in Sec 3 - marked New B.T. 8" B.O. N 7° E 79 Links

1/4 Cor Bet 3 & 4

Set oak Post for Cor from O.B.T. to S.V. New B.T. 12" Fir N 80° E 212 Lks.

Same as above