

Cor. of Secs. 20-21-28-29

✓ Renewed this corner from the original Fir
 ✓ Bearing trees. also Cedar line tree North
 25 lbs the stump of which still existed
 I set a cedar post 4" x 4" x 36" from
 which Orig fir bearing scribe marks N 22° E 50 lbs
 " " did not open S 27° E 48 lbs
 Marked New trees 26" Fir S 49° 15' W 41° ft
 30" Chinquapin S 66° E 47° ft.

Cor. to Secs 19-20-29-30.

✓ Set Iron pipe 1 1/4" x 36" - 16" below surface
 ✓ of ground. from which
 #2 Pine tree 24" dia (In SE Cor. of Cemetery)
 N 32° E 537° ft, A. Pear tree 10" dia N 31° 30' W
 1646 ft, A. fir 20" dia S 41° 45' E 730°
 An Iron Pipe 1 1/4" x 40" N 89° 07' E 453° on Sec line
 and West. bdy. Highway to Coast.

1/4 Corner between Secs. 20-29

✓ Set a steel mower pitman from
 ✓ which a Fir 18" in dia. S 77° 20' E 743° ft.
 #3 a Sugar Pine 26" N 62° 40' E 150° ft.
 No evidence of original corner to be found.
 this corner was set by proportionate meas.

Cor to Sec 29-30-31-32.

Renewed this corner from the original bearing
 trees and set a Pitch limb post 3" x 3" x 36"
 #4 also an Iron Pipe 1 1/4" x 30" from which
 Orig B.T. A. fir 20" dead, standing bearing scribe
 marks. bs. N 60° W 48 lbs. net page

Jesse W. Cole C.S.
 N.E. Richardson - chain
 J.B. Blodie - axe #1

April 23, 1923

April 25, 1923
 Jesse W. Cole C.S.
 N.E. Richardson - chain
 J.B. Blodie - axe #4

✓ a 15" Oak. nearly dead showing scribe marks
 N 77° E 106 lbs A. Fir 30" showing scars
 bears S 8° W 115½ ft. or 175 lbs.
 Marked new trees a Fir 18" in dia S 49° 30' E 29° ft.
 a Fir 30" N 60° 30' W 53° ft.

S.E. Cor. D.L.C. #43 - - - This corner was renewed from
 ✓ the original BT, a W Oak 14" N 11° W 59 lbs.
 ✓ tree had been opened previously and scribe
 marks had rotted off. Line trees called for
 in the Government field notes both North
 #5 and west at proper distances I set
 an Iron Pipe 1¼" x 36" from which
 A. Fir 40" S 50° E 267 ft.
 A. Fir 48" N 43° 30' E 69.9 ft.

S.W. Cor. D.L.C. No. ⁴³ ~~44~~ - - - This corner was renewed
 ✓ from line trees called for in Gov. field notes
 ✓ East of the corner and on the south side of it.
 I set an Iron Pipe 1¼" x 36" from which
 a Maple 12" N 0° 20' W 55½ ft. a Maple 10"
 #6 in dia N. 32° 15' E. 73½ ft. No evidence
 of Bearing tree found

S.E. Cor. of D.L.C. 44 - - - This corner was renewed
 ✓ from the original BT which was a W Oak instead
 ✓ of W Ash as called in the field notes.
 I set an Iron pipe 1¼" x 36" in dia from
 #7 which W Oak 14" in dia N. 70° W 83 lbs
 a Fir line tree called for in field notes bears
 west 267½ ft.

3-20-28 - Located this corner. OBT as described by Cole in place.

#8 Both Line tree still in place. Both trees killed when slashing was burned.
 Set new BT 12" Fir 52° W 96½ ft scribed CI 44 CS BT.