

T29-7

Continued From Page 134

March 6 1901
Ed. Eppstein & Son
#31 N.E. Richardson
#32 W.F. Briggs
#33 W.F. Briggs
#34
#35
May 11, 1913
Frank Cain
Field Book 9-63 P52-56

SE Cor D.L.C. No 43, Standard Govt. Corner. Old W.T.
Namely W.O. 30" N 75° W 283 & ft. Marked #

Corner of Sec 687 Standard Govt Corner from which
48" B.O. N 13° E 161 feet
12" B.O. S 68° E 73 feet

Witness Corner to Sec 687 119 feet West of corner
a standard Govt Corner Marked from which
36" W.O. N 57° E 89 feet.

Cor. Secs. 4-5-32 & 33 on Township line between T. 29 & 30

S. R. 7 W. Laurel 12 in. S. 20 1/2° E. 29 Lks.
Pine 36 " N. 72 1/2° W. 140 "
" 40 " S. 41 1/2° W. 105 "
Cedar 12 " N. 45° E. 16 "

1/4 Sec. Cor. Bet. Secs. 22 & 27 T. 29 S. R. 7 W.

Set post marked 1/4 S. Made new B.T. original B.T. gone
R. Fir 24 in. S. 66° E. 31 Lks.
W. " 8 " N. 78° W. 63 "

1/4 Cor. Sec. 8-17 T. 29 S. R. 7 W.

Set an Oak stake 4"x4"x36", 18" in the ground
A Fir 8" Dia. N 20° 30' E 30 Links
A.W. Oak 36" Dia. S 61° 45' W 84 Links

Cor. Sec's 8-9-16-17 T. 29 S. R. 7 W.

Set post 3"x3"x36", 16" in the ground
A B. Oak 36" Dia. N. 79° 30' E. 368 Links
A W. Oak 20" Dia. S. 12° 15' E. 262 Links
A B. Oak 30" Dia. N. 89° 15' W. 232 Links
A B. Oak 20" Dia. S. 70° 45' W. 249 Links

May 11 1913

T 29-7

May 11, 1913
Frank Cain
Field Book 9

1/4 Cor. Sec. 8-9 T 29 S. R. 7 W
A Red Fir. 24" Dia. S 65° 30' E. 95 Links
A Red Fir. 12" Dia. S 40° W 10 Links

S.E. Cor. D.L.C. N° 39 Daniel Wells
A B. Oak 20" Dia. S. 46° 30' E 99 Links
A Ash 8" Dia. N. 47° 30' E 17 Links

H. Eppstein
Geo. Spar
Falbe
Ed Jenning
March 1916

Cor. Section's 9-10-15-16
A Laurel N 65° E 24 5/2 Feet
A Fir S 43° E 33° Feet
A Fir N 53° W 16 3/4 Feet
A Fir S 55° W 27 3/4 Feet

Ben D Irving Deputy Co. Surveyor
N.E. Richardson
Frank Rayer
Robinette
Bill Weighman
May 1934

1/4 Sec. Cor 24-25. Original BTs. as described in gout field notes. Set Yew Wood post 4'x4'x36" - 1/4 5-24-25-C.S.

1/4 Sec. Cor 25-26. Original BTs as described in gout field notes. Set Fir Post 4'x4'x36" 1/4 5-25-26-C.S.

1/4 Sec Cor 25/30 - Original tree for corner in place but badly Rotted- Original BTs as described in gout field Notes. Set 4'x4'x36" Fir Post.

1/4 Sec Cor 25-30 Rock as described in gout field notes knocked out. One Original BT down other OK. Reset original Rock Remarkd OBT 14" Fir S 60° E 18 lks.

New BT 36" Fir S 78° W 23 lks.
Closing Cor. Sec. Cor 24/25 Rock as described in gout field notes.

#43 One OBT stump remains no new trees suitable for marking close.

1/4 Cor Sec 25/26 Post rotted off Original BTs as described original field notes. Set Fir Post 4'x4'x36"

NW Cor. Jno. Byron DLC 38. Found 1 old B.T., marked new trees & drove a 1" x 30" I. Bar for cor. fr. wh. a 12" Fir brs. S 56° 45' E 5.0 ft., 12" Fir brs.

N 83° W 8.9 ft., 36" Cedar brs. S 26° 30' W 18 ft. - old B.T., 14" W.O. N. 20° W 101.6 ft remarked.

F.C. Frear Admaster.
P.D. Wolford
J.H. Wolford
N.E. Richardson
4-15-1936