

Douglas County Surveyor's Record of
Government Corners Renewed

T 25 T. S. R 1 E E
R/W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

45

Jim Landrum, U.S.F.S.
Deputy, Doug. Co.
Surveyors Office
Leonard Herzstein,
Witness.
May 10, 1983
C.S. 62/10

Section corner for Secs. 13 and 24; and Secs. 18, 19 of T.25-2E
Found - 1927 GLO brass cap, properly marked, on 2" diam. iron post,
firmly set, projecting 6" above ground, leaning westerly.
Used the point where the I.P. comes out of the ground as the
corner point.
Orig. 26" D. fir stump, N.31° E., 31.9 ft. (Rec. 32.3 ft.)
with healed blaze.
Orig. 44" D. Fir, S.28°E., 9.9 ft. with healed blaze.
A roothole, N.38°W., 51.5 ft. with 14" D. fir log alongside
with fragmentary scribe marks visible on partially healed
blaze.
New BT's- 12" maple, N.78°E., 29/2 ft. scribed "T25S R2E S18 CS BT" on
single blaze.
5" W. fir, S.73°W., 26.8 ft. scribed "T25S R1E S24 CS BT" on
single blaze.
40" D. fir, N.70°W., 38.3 ft. scribed "T25S R1E S13 CS BT" on
single blaze. (Blaze is on old logging scar.)
Note: Corner is approx. 250 ft. south of USFS Rd. #3811-100 in the NW
corner of clearcut unit #25-2E-19-5. Corner is about 66 ft.
north of creek.

5/10/83

46

Jim Landrum, U.S.F.S.
Deputy, Doug. Co.
Surveyors Office
Witness: Leonard
Herzstein
May 12, 1983
C.S. 62/10

Section corner for sections 25 and 36; and secs. 30 & 31 of T.25-2E.
Found - 1927 GLO brass cap, properly mkd., on 2" iron post, firmly set,
projecting 6" above the ground.
A 20" D. fir, N.32°E., 40.9 ft. with healed blaze.
A 21" R. cedar, S.42°E., 29.6 ft. (Rec. 30.4 ft.) with healed
blaze.
A 17" W. fir, S.56°W., 21.5 ft. (Rec. 22.4 ft.) with healed blaze.
A roothole, N.86°W., 21.1 ft. with decayed log, size indeterminate
~~INDETERMINATE~~, alongside with fragmentary scribe marks visible on decayed
blaze.
No new monument set.
New BT - A 20" D. fir, N.34°W., 23.1 ft. scribed "T25S R1E S25 CS BT" on
a single blaze.
Note - Corner is located on a steep NW slope, approx. 300 ft. east of
the end of U.S.F.S. Road #4760-400.

5/12/83

47

Douglas County
Surveyors Office
Larry E. Monrean,
Deputy
J.R. Lundeen
R.W. Smith
S.J. Flause
Sept. 21, 1984
C.S. 62/21

Section corner for Secs. 33 and 34 only of T.24S Range 1 East.
Found - Original stone monument searched for and NOT FOUND.
Orig. 12" now 19" fir bears N.14°E., 15.2 ft. We opened a
portion of well healed blaze and found a scribed "4" at the
proper growth ring count.
12" now 29" fir bears S.31 1/2°E., 30.8 ft. (Rec. 35.6 ft.) Found
fragmentary scribe marks in the previously opened and
obliterated blaze.
A 16" now 28" fir bears S.11 1/2°W., 13.2 ft. (Rec. S.8°W.)
Tree has well healed overlapping blazes.
The original 8" madrone BT NOT FOUND.
CC S3 and Sec. 4 of T25S bears N.89 1/4°E., 86.8 ft. (Rec.
N.89 3/4°E., 84.5 ft.)
Set - At the location determined by holding the record bearing and
distance (N.14°E., 15.2 ft.) to the N.E. BT and corroborated
with the noted measurements, We chisel a 2" + into the bedrock
~~BEDROCK~~ 6" below ground surface. Over this point, We set a 1" x
" 1" x 3/8" iron pipe with brass cap in mound of stone and earth. Ca
marked "Douglas Co. Surveyor" T24S R1E S33 S34 S4 T25S" Corner
lies on steep SSE slope.
New BTs - 11" diam., pistol butt D. fir bears N.67°E., 19.2 ft. to center
of root crown is double blazed and scribed "T24S R1E S34 CS BT"
11" diam. maple scribed "T24S R1E S33 CSBT" on a double blaze
bears N.67 1/2°W., 48.2 ft. to center of root crown.
Not of record:
A tagged 28" fir snag bears N.50°W., 34.5 ft.
A tagged 32" Fir bears S.68°E., 43.4 ft.

9/21/84