

Douglas County Surveyor's Record of
Government Corners Renewed

20 T. S. 6 R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

24

Section Corner to Sections 25 - 26 - 35 - 36.

Found - 1/2" I. P. at Corner. Orig. 12", now 18" Fir Snag S.40°E. 13.2 ft., shows good scribing S36.

Orig. 8", now 14" Down Fir S.88°W. 33.0 ft., not 29.4 ft.

No trace of Orig. N.W. & N.E. BT's, found. We opened

S.W. BT. & Found good scribing.

Set - Brass Cap alongside 1/2" Pipe and Mkd:

S26	S25
S35	S36

 T20S R6W
County Surveyor's Office, 1961

New BT's: 16" R.Fir bears S.21°E. 54.0 ft. scribed S36 T20S R6W CS BT.

5" R.Fir bears S.79°W. 28.3 ft. scribed S35 CS BT.

22" R.Fir bears N.48°W. 29.6 ft. scribed S26 T20S R6W CS BT.

No trees near to N. E.

James W. Byron, Deputy
Milo Godfrey
Clete Putnam
June 5, 1961
C.S. 49/89

RE-RENEWED, GOVERNMENT CORNER NO. #68

FD. 11/83
Largo Smith
M 95-49

25

Section Corner to Sections 34 and 35 only, T20S R6W.

Found - Brass Cap, Co. Surveyor's Office, set by Irving, 1954. 20" Cedar N.41°W. 67.0 ft., not 78.0 ft., scribing visible.

10" Cedar S.83°E., not N.83°E. 48.5 ft., scribing visible.

Blaze & Scribe 10" Fir N.31 1/2°E. 57.9 ft. Mkd: T20S R6W S35 CS BT.

Corner in fence corner. Fences run North & West from Corner.

Original Bearing Trees all dead or dying.

Milo E. Godfrey & Crew
V.T. & C.P.
December 1961
C.S. File No. 49/143

Closing Corner Sections 3 and 2 only. T21-6

Found - Remnant of Fir Stump N.59°W. 31.7 ft., part of old face showing portion of scribed "BT" still intact.

Remnant of old Fir Stump S.60°E. 62.0 ft., no marking fd.

No trace of S.W. BT. found.

Set - Brass Cap At Cor. Mkd: County Surveyor's Office, 1961

S35	CC
S3/S2	T21S

 R6W

New BT's: 42" Cedar S.72 1/2°W. 152.7 ft. Mkd: T21S R6W CC S 3 CS BT.

10" D.Fir S.20 1/2°E. 109.7 ft. Mkd: T21S R6W CC S 2 CS BT.

Haines "T" Iron bears S.66°E. 2.7 ft. Haines BT., 18" Fir bears

N.70°E. 106.9 ft., pitched over, scribing not visible.

Note - Corner sections 34/35 T20S R6W bears West 238.4 ft., record 233.6 ft.

SEE
NEXT
PAGE

26

Section Cor. to

R6W	S 36	S 31	T20S
	S 1	S 6	T21S

Found - Orig. 30", now 54" Cedar N.36°E. 69.9 ft. Do not open.

Orig. 20", now 40" Stump N.87°W. 79.2 ft., good scrbing. vis.

Orig. 20", now 42" Stump S.82°W., shows scar. Do not open.

Orig. S. E. BT. would be in Roadway. R6W R5W

Set - Brass Cap at Cor. Mkd: Doug. Co. Surv. Office, 1958

S 36	S 31
S 1	S 6

 T20S T21S

New BT's: 18" Laurel N.18°W. 105.0 ft. scribed S36 T20SR6W CS BT.

14" R.Fir S.78°E. 24. 5 ft. scribed S 6 T21SR5W CS BT.

19" Cedar S.75°W. 97.0 ft. scribed S 1 T21S R6W CS BT.

14" R.Fir N.45°E. 32.4 ft. scribed S31 T20S R5W CS BT.

June 18, 1958

James W. Byron, Deputy
S. Bilow & M. Godfrey
June 1958
C. S. File No. 49/89

RE-RENEWED, GOVERNMENT CORNER NO. #59 26-A