

**Douglas County Surveyor's Record of
Government Corners Renewed**

T 20 T. S. R 9 R. W. W. M.

HOKE-CHAPMAN CO., EUGENE, ORE. 21881

48

Stephen Swinehart
For: International
F er Company
Nc mber 1983
M - 53

Center 1/4 corner for Section 16.
Set - 2 1/2" brass cap in concrete on rock face. Cap marked "T20S R9W S16 LS 2013 1983".
New BTs-62" fir bears S.17°E., (magnetic) 72.0 ft. scribed "C 1/4 S16 BT" on one lower blaze.
34" fir, bears S.86 3/4°E., 110.0 ft. scribed "C 1/4 S16" BT".
We set a steel fence post with BT tag, N.11°W., 22.3 ft.

11/83

CC at SW corner of Sec. 31, T. 19 S., R. 9 W. (Tnsp. corner) Ren #28
CORNER REPORT ONLY.

49

History - This corner was originally established in 1899 by Chandler. The corner mon. was a 6" chittum - BTs were: 6" chittum N. 20° E., 40 lks., and 20" fir S. 26 3/4° E., 26 lks.
In 1921, Mensch fnd.the corner & scribed a 4" chittum S. 38° E., 10 lks., as the orig fir BT was dead.
In 1978 (See Co. Surv. file # M71-62) Forrest Hales fnd an up-rooted chittum & set a 5/8" Iron Rod for the closing corner mon., holding the position of the fnd chittum as the orig. northeast bearing tree.

Mon. Fd. - 5/8" I.R. (Set by Hales).

Accessories Fd. - BTs described by Hales survey:

48" D. Fir, single blazed w/scribing bears N. 32 1/2° E., 51.1 ft. (Rec. 49.0 ft.)

40" D. Fir (Rec. 44") single blazed w/visible scribing "S6 T20S R9W BT" bears S. 50° E., 21.4 ft. (Rec. S. 53 1/2° E., 18.2 ft.)

NOTE - I visited this corner with Ernesto Alvarado of the Siuslaw Nat. Forest, who produced a copy (see file) of a Forest Service "CORNER RECORD" card dated 1968. According to the info. on the card, the cor. had been visited by J. Deaton & D. Thrall 10 years prior to the Hales survey. The card shows that a 16" fir stub w/scribing was located & that blazed lines ran E. & S. from the cor. position. This evidently was accepted as the Orig. fir BT reported by Mensch to be dead in 1921 (47 years earlier). Mr. Alvarado indicated that he had set a temporary stake at the Orig. bearing & dist. from a decayed fir stump (stump bears S. 26 3/4° E., 26 lks. from stake)
From the Hales 5/8" I.R. we measure to the temp. stake set by Alvarado N. 22° E., 16.9 ft., & we measure to the 30" fir stump S. 89 1/2° E., 11.3 ft. We did not find any scribing on the fir stump. We fnd blazed line running E. and N. from the general area of the closing cor. (the blazed line to the North was East of the line mkd. by Hales).
Without performing a survey it would not be practical to distinguish if an intersection point could be determined from the found blazed lines.
Bearing Tree tags with no info. (Name, Date, Bearings or Distances) scribed were found. One tag was found on the 48" Hales BT & faced a South Southwest direction. The other was found on a maple stump (approx. 8 ft. Easterly of Hales Monument) & faced North Northwest.

This is a report only -- No monuments or BTs were set or scribed.

No Orig. evidence of the corner mon. or its accessories could be ascertained at this time.

Sketch - See file for sketch and additional documentation.

1/84

50

1/4 Corner for Sections 26 and 27

Found - 1" I.P. with U.S. GLO brass cap protruding 6" above ground from 1953 resurvey. Cap properly marked.
A 10" hemlock now 18" dia. stump 20" high with a well healed blaze bears N.69°W., 32.3 ft. 1953 dependent re-survey
40" fir, now a 33" dia. stump 7 ft. high with protective alum. sheeting on top and a visible scar showing, bears S.33°E., 24.4' (1953 rec. S.31 1/2°E.)

New BT - 14" hemlock double blazed and scribed "1/4 S27 CS BT" bears S.60 1/2°W., 12.6 ft.

Note: See L.D. Roberts PLS 1039, survey, M 96 - 20 for condition report. Corner is located on a newly logged flat. Reproduction is 3 or 4 yrs. old.

Larry (Ed) Monrean,
Deputy
Douglas County Surveyors Office
R. W. Smith, S. J. Flause
January 5, 1984
C.S. 62/16

L.E. Monrean, Deputy
Doug. Co. Surveyors
Randall Smith
Stephen Flause
March 22, 1984
C.S. 62/16

925