

Douglas County Surveyor's Record of
Government Corners Renewed

T. 20 S. T. S. R. 9 W. R. W. W. M.

ROBE-CHAPMAN CO., EUGENE, ORE. 97501

55

SE Corner of Sec. 35.
Found - 1954 GLO BC, properly mkd., on a 2" I.P. protruding 12" above grnd.
BTs - Orig. 36", now 38" burned & rotted fir stump bears N.82°E.,
153.5-ft. per M 96-26. (Rec.N.81-1/2°E.,153.1-ft.-1967BLM Resurvey)
Orig. 36", now 45", 4-ft. high fir stump with a burned out center
bears S.81°E.,118.0-ft. per M 96-26. (Rec.S.81-1/2°E.,116.8-ft.-
-1967 B.L.M. Resurvey).

No other orig. evidence found.

1954 B.L.M. BT, a 12", now 13" hemlock stump, 1-1/2-ft. high,
w/partial scribing visible bears N.14°W.,8.8-ft. per M 96-26
(Rec.N.18°W.,9.2-ft. per 1967 BLM Resurvey).

1954 B.L.M. BT, a 14", now 18" hemlock stump, 1-ft. high, with
downed BT, with scribing visible: "T20S R9W" , bears N.55°E.,
22.1-ft. per M 96-26. (Rec. N.53-1/2°E.,21.8-ft. per 1967
B.L.M. Resurvey).

New BTs- 7" D.Fir dbl.blazed & scribed: "T20S R9W S36 CSBT" bears
N.84-1/2°E.,22.8-ft.

5" D.Fir dbl.blazed & scribed: "T20S R9W S35 CSBT" bears
N.21°W.,32.1-ft.

Note - See file for sketch.

4/84

56

South 1/4 Section Corner for Sec. 35 only.

Found - 1954 GLO BC, properly mkd., on a 1" I.P. protruding 4" above grnd.
NO Orig. evidence found.

NO evidence of 1954 Resurvey found.

SEE ALSO # 54

BTs - a 1967 BLM Resurvey BT, 67", now a 63", 3-ft. high fir stump
with scribing visible: "1/4 S35 BT", bears N.65°E.,78.5-ft.
(Rec. N.62°E.,79.2-ft.).

a 1967 BLM Resurvey BT, 20", now a 17", 4-ft. high maple stump,
bears N.58°W.,26.6-ft. per M 96-26 (Rec. N.58-1/4°W.,25.7-ft.

New BTs- 6" D.Fir dbl.blazed & scribed: "1/4 S35 CSBT" bears N.71-1/2°E.,
7.1-ft.

4" D.Fir dbl.blazed & scribed: "X BT" bears N.21°W.,5.9-ft.

Note - See file for sketch.

4/84

57

Center 1/4 Corner for Section 34.

Set - 3 1/2" brass cap in drill hole in solid rock. Cap stamped with
S-T-R, date and PLS #1039.

New BTs-23" hemlock, N.47°W., 31.0 ft., scribed/painted red/brass washer.

New Accessories:

R.R. spike in side of 24" fir stump, S.01°W., 17.1 ft. to spike.

Metal fence post beside alum. cap. Wired land survey monument to
fence post.

Corner lies on NE slope about 70 ft. east of ridge. Ridge bears N.10°W.

Corner is also about 140 ft. west of small creek. Creek bears N.10°W.

58

1/4 Corner for Sections 1 and 12.

Found : A 1" pipe with B.L.M. cap marked "T20S R9W, 1/4 S1,S12, 1954.

BT's : A 22" Fir snag bears N 37°W, 6.7 ft.

21" Fir snag bears S 16°W, 23.5 ft. With bark scribing and tag.

New BT's : 8" Douglas Fir bears N5°E, 14.0 ft. Scribed "1/4 S1 BT".

8" Douglas Fir bears S8°E, 3.1 ft. Scribed "1/4S 12 BT".

Note : Set a 6' Aluminum post with attention sign next to monument.

59

1/4 Section Corner for Sections 12 and 13.

Found : A Standard B.L.M. 2 1/2" Dia. cap on pipe. B.L.M. Survey in
1954.

BT's : A 26" Cedar stump bears N61°E, 15.46 ft. with visible scribing
" 1/4 BT".

Other stump not looked for.

New BT's: A 24" Fir stump bears N/1°W, 24.80 ft. With tag attached.

48" x 6" high stump bears S74°W, 57.31 ft. With spike
nail and L.S. cap in center top of stump.

Note; Monument lies 100 ft. ± East of creek.

Larry (Ed) Monrean, L.S. #1830
Deputy County Surveyors Office
Randall W. Smith
Stephen Flause
April 4, 1984
C.S. 62/18

Les Roberts LS 1039
For: International
Paper Co.
March 21, 1984
M 90- 53

BY FDOK
Don Wayne
5/19/83
C.S. 63/153

Donald Branch
International Paper Co
2-3-87
M 101 - 14
C.S.63/48