

Douglas County Surveyor's Record of  
Government Corners Renewed

20 T. S. 10 R. W. W. M.

Eppstein  
County Surveyor  
J. A. Dailey  
Claude Dailey  
Emery Dailey  
Witness  
July 24, 1926  
Ren. Cor. Vol. 1  
Pg. 7

CORNER OF SECTION 32-33-5-4.  
Iron pipe with Copper Cap Standard U. S. corner Marked thus:  
P. 203.  
R. 10W.  
S. 32E 3.33  
S. 51S. 4  
E. 213.  
New Bearings Trees:  
14" Alder S. 88W. 8.6 links  
15" Fir W. 45° 30' W. 44 links  
12" Fir N. 30 E. 36 links  
12" Alder S. 5 W. 6.0 links

**RE-RENEWED, SEE CORNER NO. # 71**

1

Jan. 25, 1929  
Frank Cole  
Will Dailey  
T. I. Eppstein  
County Surveyor  
Ren. Cor. Vol. 1  
Pg. 7

COR. SECS. 31-36-1-6 TOWNSHIP COR. ON T. 20 & 21 S: R. 10 & 11 W.  
Set corner from old witness tree in Sec. 31 Maple, setting  
x 4" Galv. Iron pipe, Marked new trees as follows: 25  
Fir 4" Brs. S. 77° 15' E. 65 links;  
Maple 10" Brs. S. 27W. 17 links;  
Maple 20" Brs. N. 14° W. 23 links.  
No trees near in Sec. 31.

**RE-RENEWED, SEE CORNER NO. # 25**

2

July 12, 1929  
T. Berberso  
W. Knefke  
T. A. J. Epp-  
stein C. S.  
County Surveyor  
Ren. Cor. Vol. 1  
Pg. 7

COR. BET. SECS. 5-6  
Set 4" x 36" Fir limb for corner from Maple Witness Tree  
Marked new R. 7.  
18" Maple N. 21.8 E. 8 ft.  
28" Fir S. 13E. 25 ft.

**RE-RENEWED, SEE CORNER NO. # 44**

3

Arthur Poyer D. C. S.  
Jno. Wroe. Witness  
Henry Wroe  
Dec. 12, 1929  
Ren. Cor. Vol. 1  
Pg. 7  
C.S. 16/32

CORNER BET. SECS. 17 & 20.  
Set 3" pipe for corner on true line & midway between the  
section corner 1/2 mile to East & West. from which  
A Fir 36" dia, bears N. 83 1/2° E. 261.5 feet on bank of N. Fork  
Smith-river.  
Barked blazed & scribed 1/2 S. 17 E. 203. R. 10W. S. S. E. T.  
Alder 24" dia., bears S. 32° W. 100.5 feet.  
Marked 1/2 S. 20 T. 203. R. 10W. S. S. E. T.  
About 54' N. of this corner there is a 3" pipe set at the point  
that looks like the original corner. from which the stump of  
18" Maple Brs. N. 70° E. 15 ft. & the snag 4' high of a 50"  
I Maple bears S. 40° W. 10 feet. In 1874 Byars ran the W 1/2  
of the line bet. 17 & 20 & set the 1/2 Cor. between 17 & 20  
without running the full mile, about 4 yrs. later Thiel continue  
tinned running 1/2 mile. W. from Byars corner. This corner above  
looks like the corner. The 50" maple shows the round for the  
blaze but was burned out inside the blaze, from this corner  
is a 3" iron pipe the above B. T. shows as follows:

**RE-RENEWED, SEE CORNER NO. 30**

4

36" fir S. 81E. 175 ft.  
24" Alder S. 46° W. 198 ft.  
See letter Feb. 7, 1940, from Jos. A. Gonong.  
Dist. Cadastral Engr and notation of opinion by  
Dist. Atty. in V. 16, P. 58. Arthur Poyer 2/8/40

Section corner to secs. 19, 20, 29 and 30.  
No trace of original corner was found; corner set by double proportionate  
measurement.

Set a 4 x 4 post at point for corner,  
from which:

32 inch Fir bears N15W 19.5 feet.  
16 inch Hem bears N64E 15.5 feet.  
24 inch Fir bears S82E 24.0 feet.  
32 inch Fir bears S59W 41.5 feet.

**RE-RENEWED, SEE CORNER NO. # 79**

5

Roy C. Gibson  
June, 1957  
C. S. File No. 42/275.

Section corner to secs. 20, 21, 28 and 29.  
Found original B. T. - bears N34E 75 lks.  
Set post at corner,  
from which:

20 inch Alder bears S36W 35.4 feet.  
14 inch Maple bears N34W 27.4 feet.  
42 inch Fir bears N35E 46.4 feet.  
12 inch Maple bears S82E 11.7 feet.

**RE-RENEWED, SEE CORNER NO. 40**

6

5/8/68 - FOUND BUT NOT ENOUGH EVIDENCE  
TO RENEW - See C.S. 53/66 V.R.T.