

Douglas County Surveyor's Record of  
Government Corners Renewed

20 T. S. 10 R. W. W. M.

Section corner to secs. 28, 29, 32 and 33.  
No trace of original corner was found. Corner set by double proportional measurement.

At corner point made an X on East face of 4 foot sandstone outcrop,  
from which:

- 38 inch Fir bears N45 $\frac{1}{2}$ W 35.8 feet.
- 14 inch Maple bears N88E 48.6 feet.
- 6 inch Fir bears S21W 4.2 feet.

RENEWED, SEE CORNER NO. 39 7

Roy C. Gibson  
June, 1957.  
C. S. File No. 42/275.

$\frac{1}{4}$  corner to secs. 29 and 32.  
No trace of original corner was found. Corner set by proportional measurement.

Set a post,  
from which:

- 40 inch Fir bears N17W 37.0 feet.
- 8 inch Maple bears S43E 14.8 feet.

RENEWED, SEE CORNER NO. 33 8

$\frac{1}{4}$  corner to secs. 21 and 28.  
No trace of original corner was found. Corner set by proportional measurement.

Set a post,  
from which:

- 14 inch Maple bears S76E 7.4 feet.
- 18 inch bears N60W 38.6 feet.

NOT FOUND - FEB. 1970 - V.R.T.  
C.S. 53/66  
RENEWED, SEE CORNER NO. 41 9

Section Corner common to Secs. 25, 30, 31, & 36. (REGS. 11 & 10) 10

Found - 3 Orig. BT's. as follows:

- A Maple 24" in diam. bears N.29°W. 25.0 ft. (old face at base of tree. New face approx. 4 ft. above the ground line. Has been re-scribed in unrecorded survey.
- A Maple stump 24" in diam. bears S.35°W. 39.6 ft. (remains of tree & old face still visible.)
- A Maple 22" in diam. bears N.45°E. approx. 55.0 ft. (uprooted & down). -

SEE REN #1 T20-11

New BT.: A Fir 60" in diam. bears S.18°W. 70.3 ft. (Scribed) 38

Set 5/8" re-enforcing rod for the corner & Post. Set distances from BT'S. as called for. The orig. bearings did not check. - Cor. Fo. 5/1964 - M 28-19

NOT ABLE TO RENEW - 4/1968 V.R.T. ?  
C.S. 53/66

Clifford A. Stephens  
For Coos Head Timber Co.  
Filed April, 1958  
C. S. File No. 42/362  
Map File M 10 - 3

$\frac{1}{4}$  Section Corner to Sections 30 & 31. 11

By proportion I set the  $\frac{1}{4}$  Corner 2618.88 ft. West of the Northeast corner of Sec. 31. The West  $\frac{1}{2}$  of the section receiving 2646.20 ft. to close in on the Range line.

For the  $\frac{1}{4}$  Corner I set  $\frac{1}{2}$ " Iron Pipe & Post from which:

- A Cedar 8" in diam. bears N.13°W. 14.0 ft.
- A Fir 12" in diam. bears S.34°W. 12.0 ft.

RENEWED, SEE CORNER NO. #111  
See also M 99-51 for Cor. FD.

Cl. Corner to Sec. 6, T20-10W. & Sec. 1, T20-11W. 12

Set - Iron Pipe with Brass Cap Mkd: RS239 C.C. Sec. 1, T20S R11W  
Sec. 6, T20S R10W

Scribed New BT's: 14" Fir S. 46° E. 34.5 ft.  
30" Fir S. 24° W. 65.7 ft.

W. 1/16 to Sec. 6, T20-10W. & Sec. 31, T19-10W. 13

Set - Iron Pipe with Brass Cap Mkd: RS239 S 1/16 S 31 T19-10W  
S 6 T20-10W

New BT's: 24" Fir N.12° E. 23.7 ft.  
28" Fir S. 76° E. 31.0 ft.

$\frac{1}{4}$  Cor. to Sec. 6, T20-10W. & Sec. 31, T19-10W. 14

Set - Iron Pipe with Brass Cap Mkd: RS 239  $\frac{1}{4}$  S 31 T19S R10W  
S 6 T20S R10W

New BT's: 22" Fir South 4.1 ft. ) Scribed  
24" Fir N. 15° W. 36.5 ft.)

Sec. Cor. - Secs. 5 & 6, T20-10W. & Secs. 31 & 32, T19-10W. 15

Set - Iron Pipe with Brass Cap Mkd: RS239 S 31 S 32 T19S R10W  
S 6 S 5

(con't. next page)

Wilford N. Haines  
For - U.S.F.S. - U.S. Plywood - Int. Paper  
November 1965  
Map File M 31 - 6