

**Douglas County Surveyor's Record of
Government Corners Renewed**

20 T. S. 10 R. W. W. M.

FOKE-CHAPMAN CO., EUGENE, ORE. 97501

James W. Prochnau
For: Siuslaw National
Forest M 104 - 51 A&B
June 30, 1987

*FDOK BY
Clyde Huikins for: JP
David Craven
5/19/84 M120-13*

Section Corner to sections 5 and 4, also sections 32 and 33 of T19-10 **119**
Found - GLO 2 1/2" brass cap on a 1 1/2" galvanized iron pipe set in 1952.
BT's - A 24" douglas fir stub bears S86°W, 10.7 ft. (rec. S85°W, 15 lks.) Healed. (BLM 1892)
34" douglas fir bears S 20°E, 66.7 ft. (rec. S 20°E, 101 lks) healed. (BLM 1952).
26" douglas fir bears N 40°E, 34.9 ft. (rec. N 40°E, 53 lks) healed (BLM 1979)
33" Alder bears N 12°W, 8.6 ft. (rec. N 16°W, 8.5 ft.) ✓ (1982 RLS 752).

1/4 Corner for sections 5 and 4. **120**
Found - A 2 1/2" Brass cap on a 1" galvanized iron pipe stamped " 1/4 S5/S4, 1952" Also a 2" iron cap on a 1 1/2" iron pipe mkd. "1/4 S5/S4" Reset by new monument.
BT's - A 28" douglas fir bears N 58°E, 33.7 ft. (rec. N 58 3/4°E, 51 lks.). healed. 1952 BLM Bt.
36" douglas fir stump bears N 75°W, 19.1 ft. (rec. N 75°W, 29 lks.). Healed.
Ref mon.- A U.S.F.S. 2 1/2" x 30" aluminum pipe with 3 1/4" aluminum cap bears S 89°24'W, 44.5 ft. marked "T20S R10W RM 1/4 S5 1987 PLS 1305".

Section corner for sections 5, 4, 8 and 9. **121**
Found - A 2 1/2" brass cap on a 2" galvanized iron pipe set by GLO 1952, stamped " T20S R10W S5 S4 S8 S9 1952".
BT's - 60" Douglas fir stump bears S 30°E, 56.1 ft. (rec. S 30°E, 85 lks.) healed. (1878 BT.)
Alder stump bears N 67°W, 36.7 ft. (rec. N 69°W, 53 lks) 1952 BT.
38" Douglas fir stump bears S 45°W, 91.7 ft, (rec. S 45°15'W, 139 lks) healed.
14" Alder bears N 9°E, 30.3 ft. Healed. (Unrecorded BT)
New - 4" Alder bears N 82°W, 43.1 ft. Scribed " X BT".
BT's 7" Hemlock bears S 57 1/2°W, 23.2 ft. scribed "T20S R10W S8 BT".
Ref - A U.S.F.S. 2 1/2" x 30" aluminum pipe with 3 1/4" aluminum cap mon set stamped "T20S R10W RM S9 1987 PLS 1305".

1/4 Corner section 5 and 8. **122**
Found - A 2 1/2" brass cap on a 2 1/2" galvanized iron pipe set by J. Prochnau in 1971.
BT's - 24" Douglas fir bears S 78°W, 92.5 ft., healed.
15" Douglas fir bears N 36°W, 90.7 ft. healed. See Ren#52
Set - A 8" Douglas fir Corner Tree replaces the brass cap on pipe. tree mkd. " SC 1/4 S5" on North side of tree.
Set - The found 2 1/2" brass cap on a 2 1/2" galvanized iron pipe has RM's been modified and used as a RM, bearing: S 25°23'W, 10.8 ft. marked "RM 1/4 S8".
NOTE : Removed tags and signs from 1971 BT's.

Center 1/4 Corner for section 5. **123**
Set - A 3 1/4" aluminum cap with magnet on a 2 1/2" x 30" aluminum pipe stamped " T20S R10W C 1/4 S5 1987 PLS 1305".
BT's - A 23" Douglas fir bears S 40°E, 7.2 ft. scribed "C 1/4 S5 BT".
Scibed 15" Douglas fir bears S 87 1/2°E, 17.7 ft. Scribed "C 1/4 S5 BT".

Section Corner for Secs. 23, 24, 25 and 26 **124**
Found - 56" Fir stump with scribing, S.13°E., 64.02 ft.
49" Fir stump with face seam showing at cut, N.57 1/4°W., 22.44 ft.
BTs from 1951 dependent resurvey. (See County Surveyors records, Vol. 27 Pgs. 11689-90 BLM records)
The BLM monument and other 2 BTs were removed by a road cut.
Set - 2" alum. cap on a 3/4" x 30" iron rod at record bearing and dist! from the 2 found BTs. Cap stamped: "Stuntzner Engineering T20S R10W S23 S24 S26 S25 1990 LS 2244".
New Accessories:
Scribed an "X" in the rock cut bank, N.50°E., 23.90 ft.
Set a spike in the top of a 17" alder stump, S.47°W., 43.85 ft.
East fork of Spencer Creek, a tributary of Smith River. Corner falls in a dirt cat road about 30 ft. south of a ridge. This corner falls in a freshly burned clear cut.

6/21/90

J. Prochnau
For: Siuslaw National
Forest M 104 - 51 A&B
June 30, 1987

Harvey Wilcox
Stuntzner Eng.
L.S. 2244
June 21, 1990
C.S. 63/104