

Douglas County Surveyor's Record of
Government Corners Renewed

20 T. S. 11 R. W. W. M.

ROBE-CHAPMAN CO., EUGENE, ORE. 21881

103

1/4 Corner to Section 7 only. T 20 S R 10W.
Original Corner ever established.
At the properly proportioned position I placed a 2" x 36" galv. I.P.
flanged at the bottom and capped with a bronze disk welded on top.
The monument projects 6" above ground. I filled in around the pipe
monument with stone and packed earth.
I stamped the disk:

1/4 S7
1971
4185
#179

I established new bearing trees as follows. Each bearing tree has a
scribed face and a U.S.F.S. bearing tree sign breast high and facing
the monument.
Set: 22" fir bears N. 29° E 49.4 feet.
15" fir bears N 78° E 75.54 feet.

James W. Ironman
For U.S. Forest Service
May-1971 Rev. Aug. 1971
C.S. File 55/201
Map File 41 - 77 -
Rev. M 43 - 56

104

1/4 Corner for Secs. 4 and 9.
Found - No evidence of orig. 1/4 corner.
Set - 2" Brass cap and I.P. at proportionate distance, mkd. "T20S
R11W 1/4 S4 S9, PE 6245, 1975"
New BT's - 42" Fir, N.63°E., 18.8 ft. mkd. 1/4 S4 BT"
20" Fir, S.9°E., 12.0 ft. mkd. 1/4 S9 BT.

105

Section Corner for Secs. 4, 3, 9 and 10.
Found - Orig. 30" Fir, now 44", N.3 1/2°E., 70.2 ft.
Orig. 36" Fir, now 52", N.7°W., 69.7 ft.
Set - 2" BC and I.P. for corner mkd. "T20S R11W S4, 3, 9, 10, PE 6245
New BT's - 26" Fir, S.31°E., 3.8 ft. mkd. T20S R11W S10 BT.
26" Fir, S.15°W., 26.1 ft. mkd. T20S R11W S9 BT.

106

1/4 Corner for Secs. 9 and 10.
Found - Orig. 14" Hemlock of Gov. 1906 Survey (now 26", face open &
scribe plain), N.3°E., 168 lks. (110.88')
Set - 2" Brass cap and I.P. for corner mkd. "T20S R11W, 1/4 S9 S10
PE 6245, 1975.
New BT's - 60" Fir, N.78°E., 90.0 ft. mkd. "1/4 S10 BT."
10" Hemlock, N.1°40'W., 118.2 ft. mkd. "1/4 S9 BT"
1/2" pipe, N.15°53'E., 6.63 ft.

Howard E. Stuntzner
For U.S. Forest Service
April, 1975
M 55 - 76

107

1/4 Corner for Sections 9 and 16.
Found - Orig. 8" Hemlock now 26" stump with 1/4 scribe mark, S.70 1/2°W 25.7 ft.
Set - 2" Brass cap and I.P. for 1/4 corner mkd. "T20S R11W 1/4 S9 S16,
PE 6245, 1975.
New BT's - 10" Fir, S.73°E., 36.2 ft. mkd. 1/4 S16 BT.
10" Hemlock, N.45°W., 52.8 ft. mkd. 1/4 S9 BT.

108

Center 1/4 corner for Section 9.
Set - 2" Brass cap and I.P. mkd. T20S R11W C 1/4 S9 PE 6245, 1975
New BT's - 20" Fir, N.40°W., 39.7 ft. mkd. "C 1/4 S9 BT."
18" WRC, S.14°E., 13.9 ft. mkd. C 1/4 S9 BT.
Metal fence post S & E, 5 ft. April, 1975

JAN 76

109

Section Corner for Secs. 32 and 33; and Secs. 4 and 5 of T.21-11.
Found - 1964 D.C.S.O. brass cap. Cap is firmly in place, 4 inches above
ground. On south edge of a 5" Hemlock stump. Ren. #39
Orig. 33" now 58" Fir stump bears N.75°E., 28.4 ft. (to face)
Tree has opened blaze, scribing no longer legible, fragmentary
reverse scribing found.
7" Hemlock bears S.79 1/2°E., (Rec. S.83°E.) 12.7 ft. Tree double
blazed partially healed, scribing visible "R11W S4 CS". This
tree is now a dead snag.
16" now 21" Hemlock, bears S.87°W., (Rec. S.85°W.) 30.8 ft. Tree
double blazed, partially healed, scribing visible "2sR8"
18" now 22" D.Fir, bears N.57°W., (Rec. N.58°W.) 30.3 ft. Tree
has a well healed double blaze.

FD. OK 5/17/80
E. ALVARADO
C.S. 6/1/86

L.E. Monrean
Pete Earle
Mike Tompkins
Douglas Co. Surveyors
Office
Dec. 15, 1976 C.S. 54/26