

Douglas County Surveyor's Record of
Government Corners Renewed

T 20 S T. S. R 11 W R. W. W. M.

KORE-CHAPMAN CO., EUGENE, ORE. 97401

122

Frank M Pumphrey
LS # 1677
For: International
Paper Co.
Aug. 1980
M 85 - 37
FD. OK 12/90
M 111-47 A-F

1/4 Corner to Sec. 36, T.20S. R.11W.; and Sec. 31, T.20S. R.10W.
Set - 5/8" x 30" rebar with alum. cap mkd. "1/4 Sec. 36 31", set 4"
below surface.
B.O.'s - 3/4" Iron pipe bears N.82°11'30"E., 298.22 ft.
3/4" Iron pipe bears S.55°46'56"E., 287.06 ft.
Fence post with 16P nail in top of post bears N.56°E., 33. t.
Fence post with 16P nail in top of post bears S.33°E., 36. t.
Fence posts are tagged and corner lies in middle of field.

123

Perry Fox
For: Davidson Indust.
June 1981
M 88 - 13
C.S. 58 / 238 (N)

East 1/4 corner for Sec. 1 of T. 20 R. 12.
Set - 2 1/2 " Brass Cap.
BT's - 12" Fir bears N.81°E., 32.5-ft.
14" Spruce bears S.35°E., 28.6-ft.

6/81

124

Sec. corner for Sec's. 34, 35, and Sec's. 2, 3 of T.21-R.11.
Set - Brass Cap marked T20S R11W WM S34 S35 S2 S3 T21S RLS 430 1981
BT's - 26" W. Red Cedar, I scribed T20S R11W S35 BT , bears
N.89 1/2 °E., 146.0-ft.
28" Spruce, I scribe T21S R11W S2 BT , bears S.41°E., 136.6-ft.
12" Alder, I bark scribe T21S R11W S3 BT , bears S.70°W.,
27.4-ft.
18" Alder, I bark scribe T20S R11W S34 BT , bears N.59°W.,
85.3-ft.
County Monument "S-7" bears N.75°33'26.8"W., 996.92-ft.
Steel fence post along side the set B.C.

7/81

12

FD. OK 12/90 M 111-47 A-F
1/4 corner for Sec. 35, and Sec. 2 of T.21-R.11.
Set - Brass Cap marked T20S R11W WM 1/4 S35 S2 T21S RLS 430 1981
I reset the fd. 3/4" I.P. along side. Renewal # 40
BT's - 56" W. Red Cedar (Orig. BT), with scribes visible, bears
S10°W., 12.0-ft.
24" W. Red Cedar, with scribes visible, bears N.58°E., 34.5-ft.
7/81

126

1/4 corner for Sec. 34, and Sec. 3 of T.21-R.11.
Set - Brass Cap marked T20S R11W WM 1/4 S34 S3 T21S RLS 430 1981
BT's - 14" Spruce, I scribed 1/4 S3 BT , bears ~~S.75°W., 9.3-ft.~~
76" W. Red Cedar, I scribed 1/4 S34 BT bears N.79°W., ~~69.8-ft.~~
72.2
FD. OK 7/92 BY STUNTNER
M 115-41

7/81

127

1/4 Corner common to Secs. 14 & 23.
Found - No trace of original corner.
Set - 2 1/2 " B.C. on a 2 1/2 " x 30" I.P. at point of prop-
ortionate measure, from which;
New BTs - 27" Fir bears S.0° 15'W., 45.8-ft. (1981) scribed "1/4S23 BT
51" Fir bears N.53°15'E., 27.2-ft. (1981) scribed "1/4S14 BT
9/81

1 3

W.C. for Secs. 13, 14, 23, & 24.
Found - No trace of original corner.
Set - 2 1/2 " B.C. on a 2 1/2 " x 30" I.P. on line as witness to the
section corner, from which;
New BTs - 36" Fir stump bears N.4°0'W., 4.2-ft.(1981) scribed X BT.
42" Fir stump bears N.33°30'W., 51.4-ft.(1981) bark scribed
X BT.
8" Fir bears S.10°0'W., 21.0-ft.(1981) scribed X BT.
BO - 6' Steel fence post with sign 54-3 attached bears S.28°E., 10.9-ft.
9/81

Bruce A. Shaner RLS # 430
For: Moore Mill & Lumber Co.
RM 3 - 48
March - July 1981

Change Fee
B. SHANER
2/22/82

Robert B. Ward
Oregon P.L.S. #1091
For: Champion International
Sept. 1981
M 89 - 58 & C.S. 58/260