

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 21 S. T. S. R. 5 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Section Corner to Sections 8 - 9 - 16 - 17.

125

Found - Haines "T" Iron at Corner & BT's. as recorded Ren. #33,  
36" D.Fir N.17°W. 40.5 ft., shows "T21S R5W S8 BT",  
bark scribe & Haines' button on face.

Orig. 18", now 48" Fir Stump S.17°W. 40.3 ft., no  
scribe visible on open face. Open higher on stump  
& find "S17" scribe.

No trace other Orig. Bearing Trees.

New BT's: 7" D.Fir N.47°E. 7.4 ft. Mkd: T21S R5W S9 CS BT.

8" D.Fir S.86°E. 19.5 ft. Mkd: T21S R5W S16 CS BT.

7" D.Fir S.32°W. 14.1 ft. Mkd: T21S R5W S17 CS BT.

SEE D.F. Thiel info for BTs MKD IN 1903

126

1/4 Corner to Sections 19 & 20.  
Found - Orig. 6", now 26" Fir N.75°E. 25.1 ft., open shows scribe.  
N. W. BT., now turned out & out of position.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1965  
T21S R5W 1/4 S19/S20

New BT's: 17" D.Fir S.52°W. 8.0 ft. Mkd: 1/4 S19 CS BT.

18" D.Fir S.13°E. 13.7 ft. Mkd: 1/4 S20 CS BT.

This corner lies on hillside approx. 200 ft. N. of creek,  
flowing S.E.

Section Corner to Sections 16 - 17 - 20 - 21.

127

Found-Haines' "T" Iron & 2 BT's. as recorded in Ren. #80.

Orig. 60", now 62" Fir S.33°E. 6.6 ft., recorded as S.33°W.,  
shows faint orig. bark scribe "T21 R5W S21B",  
Rescribe "T21S R5W S21".

Orig. 12", now 42" Fir S.32°W. 21.8 ft., recorded as S.32°E.,  
shows scar. Do not open.

New BT's: 9" Laurel N. 78° W. 29.8 ft. Mkd: T21S R5W S17 CS BT.

No tree available to N. E.

This corner lies on south side, top of ridge, running N.W. & S. E.

1/4 Corner to Sections 16 and 21.

128

Found - Badly burned Cedar BT, as follows:

Orig. 9", now 12" Cedar S.11°W. 16.5 ft., "BT" reverse  
scribe and partial face of upper scar.

No trace of other Orig. BT.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1965  
T21S R5W 1/4 S 16  
S 21

New BT's: 18" D.Fir S.19°W. 38.5 ft. Mkd: 1/4 S21 CS BT.

20" D.Fir N.78°E. 96.0 ft. Mkd: 1/4 S16 CS BT.

This corner lies on west side of top of spur, ridge running S.W.

1/4 Corner to Sections 3 and 2.

129

Found - Orig. 10", now 21" Fir N.57°W. 13.9 ft., turned out, find  
"1/4 S" scribe in prev. opened scar.

Orig. 60" Fir N.88°E. 25.1 ft., badly burned & rotted stump,  
no scribe.

Set - Brass Cap at Corner Mkd: County Surveyor's Office, 1965  
T21S R 5 W 1/4 S 3/S 2

New BT's: 17" D.Fir N.33°W. 19.2 ft. Mkd: 1/4 S3 CS BT.

9" Hemlock N. 5° E. 21.7 ft. Mkd: 1/4 S2 CS BT.

This corner lies approx. 80 ft. North of small creek, flowing S.E.

1/4 Corner to Sections 9 and 10.

130

Found - Haines' "T" Iron at Cor. & BT's. as recorded Ren. #45.

20" Cedar N.61°E. 41.5 ft., now a shattered stump 6.0 ft.  
high, shows "1/4 SLOBT" and Haines' button.

30" Cedar Stub N.61°E. 12.0 ft., shows "1/4 SBT" & Haines' button.  
No trace of Orig. BT's.

New BT's: 30" D. Fir N.14°E. 39.8 ft. Mkd: 1/4 S10 CS BT.

10" D. Fir S.34°W. 37.7 ft. Mkd: 1/4 S19 CS BT.

This corner lies 20 ft. north of small creek flowing S. E.

Vernon "Ray" Tracy  
Mike Darby - Mike Stone - Terry Connell  
August and September 1965  
C. S. File No. 54/14

RE-RECORDED NO. #159