

**Douglas County Surveyor's Record of
Government Corners Renewed**

T. 21 S. T. S. R. 5 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97401

198

DOUGLAS COUNTY
RANDALL SMITH
STEPHEN FLAUSE
11/2/90
CS 64/58

Twship. SW cor. sec. 31

Monuments Fd. - 14"x14"x7" stone with a probable "+" mkd. on side, stone appears to have been tipped over and is in two pieces. stone was found 1 ft. below ground. (set by Haines in 1943 see Ren # 60.)

Accessories Fd. - 40" now 47" dia. D.Fir, with a fully healed single blaze, bears S.21°E. 31' (agrees w/ rec.) ren. # 60.
8" now 21" dia., D.Fir, with a fully healed double blaze, bears N.72°E. 56' (agrees w/ rec.) Ren. #60.
10" now 15" dia., B.Oak, with a fully healed double blaze, bears S.28°W. 18.8' (agrees w/ rec.).
8" now 12" dia., W.Oak, with a fully healed sing blaze, bears N.2°W. 10' (agrees w/ rec.) Ren. #60.
24" now 24" dia., 14" high rotted oak stump w/ axle marks visible, bears S.13°W 138.6' (agrees w/ rec.) OBT.
20" now 40" dia., W.Oak with a fully healed blaze, bears S.7½°E. 97.9' (rec. S.7½°E, 95.7') OBT.

RE-RENEWED.

Monument Set - A DCSSO 2 3/8" dia., brass cap on a 1½" O.D. by 31" long I.P. is set flush with ground, with corner stone reset upright along east edge of BC/IP 3" below ground.

DOUGLAS COUNTY SURVEYORS

R	T 21 S	R
6	S36 S31	5
W	S01 S06	W
	T 22 S	

OFFICE 1990

corner lies in middle of old gravel road at north - south fence crossing
Note: This renewal was lost from 11/2/90 to 1/95.

199

1/4 Corner for Sections 26 & 27 See renewal # 105.

Found - 1993 B.L.M iron pipe and brass cap.
- 24" Fir, N.10°E., 13.8 ft. (scar vis.) See ren. # 51
- 18" Fir, N.45°W., 18.7 ft. (scar vis.) 1964 BT

200

1/4 Corner for Sections 26 & 23

-No original evidence found.-
Set - 5/8" x 30" iron pin w/yellow plastic cap stamped "Roberts PLS 1039" by single proportionate measure.
New BT's- 6" Fir, N.52°E., 36.9 ft. (scribed/painted red)
- 14" Fir, S.07°W., 18.2 ft. (scribed/painted red)
- 18" Fir, S.62°E., 40.2 ft. (scribed/painted red)
- 42" Fir, N.01°E., 8.2 ft. (scribed/painted red)

201

Section Corner for Sections 23, 24, 25 & 26 See renewal # 151

Found - 1993 B.L.M. iron pipe and brass cap.
Found BT's -10" Fir, N.57°W., 29.0 ft. (scar vis.), 1977 BT.
-14" Fir, S.16°E., 11.8 ft. (scar vis.), 1977 BT.
-18" Fir, N.85°E., 18.7 ft. (scar vis.), 1977 BT.
-20" Fir, S.43°W., 48.1 ft. (scar vis.), 1977 BT.

202

1/4 Corner for Sections 25 & 26 See renewal # 158.

-No original evidence found.-
Set - 5/8" x 30" iron pin w/yellow plastic marked "Roberts PLS 1039" by single proportionate measure.
New BT's - 8" Fir, S.70°W., 31.1 ft. (scribed/painted red)
- 12" Fir, N.37°W., 2.3 ft. (scribed/painted red)
- 12" Fir, S.04°E., 4.5 ft. (scribed/painted red) (also Gerald Riley B.T. set in Nov. 1994)
- 12" Fir, N.74°E., 18.1 ft. (scribed/painted red) (Same B.T. as set in M79-69)
Found - Iron pipe and brass cap as set in M79-69, IP/BC bears N.86°21'45"W., 6.61 ft.
Found - 5/8" iron pin set by Gerald Riley in Nov. 1994. Iron pin bears S.11°25'30"W., 5.17 ft.

Les Roberts
For: Giustina Resources Inc.
Jan. 1996
M 123 - 29