

Douglas County Surveyor's Record of
Government Corners Renewed

T 21 T. S. R 6 R. W. W. M.

Douglas Co. Surveyors Office - Randall W. Smith, Deputy -
Stephen J. Flause - Sept 2001 - C.S. File 66/29-4 thru 6

KOKE-CHAPMAN CO. EUGENE, ORE. 97401

NW Cor. DLC 38

171

Fd - 1961 Haines "T" iron protrudes 6" above ground. (Ren #49)
18" now down & rotted Oak previously opened, no scribing
found. Roothole bears N.30°W., 83.2 ft. (OBT)
20" now 25" dia. D.Fir bark scribed "DLC # 38 BT" w/nail
& Haines cap in bark. Center of root crown bears
S.67°W., 15.2 ft. (1961) (Ren #49)
Orig. SE BT not found.
New- 26" dia., D.Fir double blazed & scribed "NW DLC 38 CS
BT" bears S.7°W., 30.8 ft.
5" dia., Maple double blazed & scribed "38 BT" bears
N.19°W. 6.2 ft. to center of root crown.
6" dia., W.Fir double blazed & scribed "NW DLC 38 CS BT"
bears N.54°E., 51.2 ft.
Compass decl. 17½°E. C.S. File 66/29-4 9/10/2001

NE Cor. DLC 38

172

Not Fd - 1961 Haines "T" iron not found at corner. (Ren #50)
Found - 12" now 16" dia., 6' high rotted Oak snag, no
scribing found on a rotted burnt blaze, bears
S.72°W., 44.2 ft. (OBT)
36" now 60" dia., 6 ft. high D.Fir stump with axe
marks, a bark scribe "L" and Haines washer with
nail in bark bears S.87°W., 39.6 ft. (OBT)
Bent Haines "T" iron found out of position horizontal
on top of ground, 20 ft. north of corner.
Set 2 3/8" dia., brass cap on a 1 3/8" O.D. by 32" long iron
pipe at a position determined by OBTs, protrudes 6" out of
ground. Haines "T" iron straightened & set along north edge of
BC/IP protrudes 4" out of ground. BC marked:

DOUGLAS COUNTY SURVEYORS

T 21 S	R
NE	6
DLC 38	W
2001	

Fence corner with fences running south & west bears
S.18°E., 7.5 ft.
12" dia., D.Fir double blazed & scribed "NE DLC 38 CS
BT" bears S.31°E., 7.2 ft.
13" dia., W.Oak double blazed & scribed "NE DLC 38 CS
BT" bears N.32°W., 10.5 ft.
15" dia., D.Fir double blazed & scribed "NE DLC 38 CS
BT" bears N.59°E., 33.9 ft.
Compass decl. 17½°E. C.S. File 66/29-5 9/11/2001

1/4 Cor. Secs. 25 & 36

173

Found - 1961 Haines "T" iron with top 10" broken off,
remainder is plumb in ground. (Ren. #47)
5" Oak now root hole bears N.72°E., 48.6 ft. (Rec.
N.75°E., 48.6 ft.) 1961
22" now 24" dia., down & rotted Oak with BT tag,
healed blaze, root hole bears S.71°W., 47.6 ft.
(rec. S.74°W., 47.6 ft.) 1961
Set a 2 3/8" dia., by 32" long iron pipe at plumb position of
"T" iron. BC/IP protrudes 4" out of ground. "T" irons set along
north edge of BC/IP protrudes 2" out of ground. BC marked:
DOUGLAS COUNTY SURVEYORS T21S ¼ S25/S36 R6W 2001.
New - 4" dia., D.Fir double blazed & scribed "X BT" bears
N.71½°W., 6.8 ft.
10" dia., D.Fir double blazed & scribed "¼ S36 CS BT"
bears S.58°W., 43.8 ft.
Set a metal witness post & sign 5 ft. east of corner.
No other scribe-able trees
Compass decl 17½°E. C.S. File 66/29-6 9/11/2001