

Douglas County Surveyor's Record of  
Government Corners Renewed

21 T. S. 6 R. W. W. M.

KOKE-CHAPMAN CO. EUGENE, ORE. 21881

33

James W. Hyron, Deputy  
Milo Godfrey & S. Bilow  
Done For W. E. Clevenger  
June 19, 1959  
C.S. File No. 49/158  
M 15 - 18

Renewed Corner 

S36	S31
S 1	S 6

 T21S  
R6W S 1 S 6 R5W T22S

Found - Orig. 20", now 40" W. Oak S. 7 $\frac{1}{2}$ °E. 95.7 ft., shows good scar, I do not open.  
Orig. 24", now 40" Oak Stump S. 13°W. 138.6 ft., I open near base & find good scribe marks "D 1".  
I also find Stone with on top at Corner Set by Haines, 1943.

GATE  
CORNER STONE

New BT's: 40" R. Fir bears S. 21°E. 31.0 ft. scribed S 6 T22S R5W CS BT.  
8" R. Fir bears N. 72°E. 56.0 ft. scribed S31 T21S R5W CS BT.  
10" B. Oak bears S. 28°W. 18.8 ft. scribed S 1 T22S R6W CS BT.  
8" W. Oak bears N. 2°W. 10.0 ft. scribed S36 T21S R6W CS BT.

RE-RENEWED, SEE CORNER NO. #145

34

Reset Sec. Cor. to Secs. 1 & 12, T21S R6W, & Secs. 6 & 7, T21S R5W.  
I find angle iron at true corner as recorded by Haines, from which the corner as renewed by Kerr bears S. 39°E. 7.2 ft. - REN. #1  
The 1855 original survey records 12" Fir N. 27°W. 9.9 ft.  
I find stump of this BT. previously opened, shows good scribing S1, #144  
checks for ring count & size. I find no 1855 BT's.  
I move Brass Cap set for Sec. Cor., 1953 renewal, N. 39°W. 7.2 ft. & reset alongside angle iron set by Haines.  
BT's, as follows, recorded by Kerr:  
28" R. Fir S. 87°E. 10.4 ft. scribed on SW face.  
22" R. Fir S. 48°E. 15.2 ft.  
14" R. Fir S. 17°W. 21.5 ft.

RE-RENEWED, SEE CORNER NO. #144

FOOK PER  
SEKLER  
M104-14  
MAY -87

Milo Godfrey  
Clete Putnam  
Dec. 22, 1959  
C.S. File No. 49/89

$\frac{1}{4}$  Corner to Sec. 6, T21S R6W, & Sec. 1, T21S R7W.  
Set 1" x 1" x 36" T. Iron from Orig. BT's. 35

Sec. Cor. to Sec. 6 & 7, T21S R6W, and Sec. 1 & 12, T21S R7W.  
Set 1" x 1" x 36" T. Iron from Orig. BT's. 36

$\frac{1}{4}$  Cor. to Sec. 7, T21S R6W, & Sec. 12, T21S R7W.  
Set 1" x 1" x 36" T. Iron from Orig. BT's. 37

$\frac{1}{4}$  Cor. To Secs. 19, T21S R6W. & Sec. 24, T21S R7W.  
Set 1" x 1" x 36" T. Iron. 38  
Scribed: 12" Fir N. 50°E. 18.6 feet.  
40" Fir N. 17°E. 41.1 feet.

Sec. Cor. to Secs. 19 & 30, T21S R6W, & Secs. 24 & 25, T21S R7W. 39  
Set 1" x 1" x 36" T. Iron.  
Scribed: 8" Fir N. 56°W. 11.7 feet.  
6" Fir N. 29°E. 7.4 feet.  
8" Fir S. 01°E. 1.7 feet.  
8" Fir S. 78°W. 17.8 feet.

$\frac{1}{4}$  Cor. to Secs. 30, T21S R6W & Sec. 25, T21S R7W. 40  
Set 1" x 1" x 36" T. Iron.  
Scribed: 10" Fir N. 08°W. 2.7 feet.  
10" Fir S. 46°E. 21.1 feet.

Sec. Cor. to Secs. 30 & 31, T21S R6W. & Secs. 25 & 36, T21S R7W. 41  
Set 1" x 1" x 36" T. Iron.  
Scribed: 36" Fir N. 72°W. 53.3 feet.  
30" Fir N. 40°W. 60.6 feet.  
6" Hem. N. 22°E. 41.7 feet.  
382°E N.E.E.

$\frac{1}{4}$  Cor. to Sec. 31, T21S R6W. & Sec. 36, T21S R7W. 42  
Found- Old BT's., very rotten.  
Scribed: 40" Fir N. 53°W. 28.4 feet.  
6" Hem. N. 31°W. 16.8 feet.

Twp. Corner to Sec. 31, T21S R6W, Sec. 36, T21S R7W, Sec. 6, T22S R6W and Sec. 1, T22S R7W. 43  
Set 1" x 1" x 36" T. Iron from old B. T. 's. 115

Renewed Corn  
By Wilford N. Haines  
Filed Feb. 17, 1960  
C. S. File No. 51/67

RE-RENEWED, SEE CORNER NO. 90

RE-RENEWED, SEE CORNER NO. 111

RE-RENEWED, SEE CORNER NO. 125

RE-RENEWED, SEE CORNER NO. 124

RE-RENEWED, SEE CORNER NO. 115