

Douglas County Surveyor's Record of
Government Corners Renewed

T. 21 S. T. S. R. 7 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Wilford N. Haines
FoR:
Int. Paper Co.
Long-Bell Div.
M 39 - 76

John M. Powell
W. Penley & J. Heritage
C. S. File No. 56/12

John M. Powell
J. Heritage & D. Schultze
C.S File 56/12
April, 1972

Wilford N. Haines
C.S. 51/309
Jan. 8, 1973

1/4 Corner to Section 16 and 17.
Set by Proportionate Measurement.
Set - 5/8" Steel Rod "Rebar" and Scribed:
5" Fir S. 29° E. 11.6 feet.
36" Fir N. 24 1/2° W. 23.4 feet.

April, 1970

90

Section Corner to Sections 23 - 24 - 25 - 26.

FD. OK 4/99 BY WARD M131-54 91

Found - 24" Corner Tree, now down, tree opened, earlier scribe visible,
"23" on burnt face. Also showed scars & notches.
50" D. Fir, now stump, N.45°E. 42.9 ft., found old axework.
14", now 28" D. Fir, N.40°W. 14.5 ft., shows scar.
No trace of S.W. - S. E. Bearing Trees.

Set - Brass Cap at Cor. Mkd: County Surveyor's T 21 S R 7 W
Office S 23 | S 24
1970 S 26 | S 25

New BT's: 5" D. Fir N.45°E. 23.1 ft. scribed "S24 CS BT".
9" D. Fir S.78°W. 12.9 ft. scribed "T21S R7W S26 CS BT".
24" D. Fir S.7° E. 40.2 ft. scribed "T21S R7W S25 CS BT".

Note - This corner lies on top of high ridge, running about E. & W.

12/21/70

1/4 Corner to Sections 18 and 17.

Found: 40" Cedar, now stump, N.77°E., (Rec.S.77°E.) 19.8 ft.
Scribe visible 1/4 S17 BT.
30" Cedar, now 30", S.88°W., (Rec.N.88°W.) 102.3 ft.
Scribe visible.

Note: Call on creek north of corner 21 lks. ok.
No trace of 1967 Brass Cap.

Set: Brass cap at 1/4 corner mkd: County Surveyor's T 21 S R 7 W
Office 1/4 S18 | S17
1972 1972

New BT's: 12" Hemlock, S.40°E., 26.5 ft. Scribed
1/4 S17 CS BT.

4/15/72

1/4 Corner to Sec. 36, T21S R7W & Sec. 31, T21S R6W.

Found: 40" D. Fir, (down), N.53°E., (Rec. N.53°W.) 28.4 ft.
Scribe visible.
6" Hemlock, now 10", N.31°W., 16.8 ft. Shows good scar.
Also: Haines T. Iron at 1/4 Cor. Ren. #44.
New BT' 7" Hemlock, S.54°E., 24.0 ft. Scribed 1/4 S31 CS BT.

4/12/72

Section Corner to Secs. 25 & 36, T21S R7W & Secs. 30 & 31, T21S R6W.

Found: 36" D. Fir, N.72°W., 53.3 ft. Bark Scribed.
30" D. Fir, N.40°W., 60.6 ft. Bark Scribed.
6" Hemlock, S82°E., 41.7 ft.

Also: Haines T. Iron at section corner. Ren. #43

New BT'S: 10" D. Fir, S.19°W., 12.5 ft. Scribed T21S R7W S36 CS BT.
5" D. Fir, S.28°E., 37.2 ft. Scribed S31 CS BT.

4/12/72

N 1/16 Corner, Sections 20 and 21.

Replaced original brass cap lost during road construction with
brass cap placed 1" above ground inscribed as follows:

T 21 S R 7 W
N 1/16
S 20 S 21
RS 239

Found - Orig. 15" D. Fir, now stump, 105 lks. S.67 1/2°W.
Good shape with yellow BT tag.
Orig. 15" Hemlock, Top out, 73 lks., N.3°E,
Good shape with yellow BT tag.

JAN 1973

95

93

94

92
MARCH 71