

Douglas County Surveyor's Record of
Government Corners Renewed

T 21

T. S.

R 7

R. W. W. M.

FOKE-CHAPMAN CO., EUGENE, ORE. 21881

116

FND. OK 9/92
L. ROBERTS M 115-63

1/4 Corner for Sections 23 and 26

Found - "T" iron with brass washer set by Haines. Ren. #48 and 51
(Original stone and post not found)

40" fir now a snag with bark scribing "BT /4" visible bears
S.1 1/2°W., 37.9 ft. (slope dist. 45.7 ft. at 34°) Rec. bearing
and distance south 42.2 ft. (Original BT)

12" now 23" maple with well healed blaze and Haines washer bears
N.14°E., 22.4 ft. (Rec. 24.4 ft.) Level chained. (Original)

12" fir now a decayed and dislodged stump with Haines washer and
scribing "BT" visible checks well with record S.37°W., 10.0 ft.

20" fir now a 28" stump 2 ft. high with single axe mark
visible bears N.11°W., 58.8 ft. Ren. #51

New BTs - 13" cedar double blazed and scribed "1/4 S26 CS BT" bears
S.57 1/2°E., 53.9 ft.

4" Fir double blazed and scribed "1/4 S23 CS BT" bears
N.54 1/2°W., 20.1 ft.

Due to steepness of slope that this monument is on, we did not set a brass
cap monument.

12/20/84

Center 1/4 for Section 36.

117

Daniel Baker
For: Seneca Sawmills
12/91
M 114 - 26

Set - 5/8" X 30" rebar w/aluminum cap marked T.21 R.7W C 1/2 S36 PLS 1978 1991.

BTs - 18" fir bears N.46°E., 21.3 ft. scribed 'C 1/2 S36 BT'

10" fir bears S.51°E., 22.7 ft. scribed 'C 1/2 S36 BT'

8" fir bears S.54°W., 25.7 ft. scribed 'C 1/2 S36 BT'

25" fir bears N.31°W., 20.9 ft. scribed 'C 1/2 S36 BT'

12/91

Section Corner for Secs. 4, 5, 8 and 9

118

Found - A 2 1/2" dia. DCSO brass cap on a 1 1/2" O.D. Iron pipe, protruding
5" above ground. Ren. No. 71

A Haines T-Iron protruding 9" above ground. T-Iron bears
S.16°W., 8.4 ft. from DCSO BC/IP. Haines T-Iron was set at an
intersection of original distances. Orig. BTs bear S.81°E.,
26.4 ft. and N.23 1/2°W., 19.1 ft. Ren. No. 26

Found BTs (Brg's and Dists. taken from 1962 DCSO BC/IP)

30" now 44" dia. Cedar with a previously opened orig. blaze.
scribing visible "T22R" and a partially healed rescribing
"SR7W S9". BT bears S.60°E., 26.4 ft. (agrees w/rec.)

30" now 50" dia. Cedar a partially healed rescribing illegible
scribing visible, bears N.50°W., 12.5 ft. (agrees w/Ren. No. 71)

12" now 18" dia. D.Fir with a fully healed single blaze, bears
N.79°E., 78.5 ft. (Rec. N.79°E., 79.1 ft., dist. is to
cut trunk) Ren. No. 71

Corner lies approx. 150 ft. East of Smith River.

4/7/92

Section Corner for 14, 15, 22 and 23

119

Found - A 2 1/2" dia. 1987 DCSO brass cap on a 1 1/2" O.D. iron pipe
protruding 13" above ground. Ren. No. 87

Haines T-Iron protrudes 17" above ground. Ren. No. 7

T-Iron bears S.25°E., 2.0 ft. from DCSO BC/IP. (agrees w/rec

Brg's & dists from DCSO BC/IP:

20" now 36" 10 ft. high D.Fir stump with gal. cap on top. NO
scribing visible in a previously opened blaze, BT bears N.25°W.,
18.5 ft. (Rec. N.25°W., 19.8 ft.) Orig. BT.

24" now 26" dia. 7 ft. high D.Fir stump with a fully healed
double blaze, bears N.81°W., 12.7 ft. (agrees w/rec) Ren. No. 87

30" now 36" D.Fir with a fully healed double blaze bears S.78°E.,
32.2 ft. (agrees w/rec) Ren. No. 87

10" now 15" dia. Hemlock with a fully healed double blaze, bears
N.58°E., 13.4 ft. (Rec. N.62°E., 13.4 ft., error in compass
reading) Ren. No. 87

No new accessories. No trees to the west. Stumps are in good shape.

4/14/92

120

Section Corner for 10, 11, 14 and 15

Found - Haines T-Iron, a 1" x 1" angle iron with a brass washer mkd.
Wilford N. Haines #239, is firmly set and protrudes approx. 10"
above ground Ren. #6

(Cont. Next Page)

Larry E. Monrean
Deputy, Doug. Co.
Surveyors Office
Dec. 20, 1984
C.S. 62/21

Doug. County
Surveyors Office
Randall Smith
Stephen Flause
Terrie Franssen
April 7, 1992
C.S. File 64/24

Douglas County
Surveyors Office
Randall Smith
Stephen Flause
John Pike
April, 1992
C.S. File 64/24

(4/8/92)