

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 21 S. T. S. R. 8 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 91881

046

1/4 cor. of secs. 9 & 16  
 Mon. Fd.- 1945 GLO 2 1/2" Brass cap  
 BT's Fd.- 1945 GLO W.Hem stump, with no marks, rec. 36" , bears N.16°W.,  
 106 lks., stump center indeterminate.  
 1945 GLO W.Hem rotted stump, rec. 50", bears S.89°E., 40 lks.,  
 stump center indeterminate.  
 32" D.Fir rotted stump of unknown origin, bears North 51',  
 visible scribed marks.  
 38" D.Fir of unknown origin (BLM TAG), bears S.50°W., 3.6', with  
 healed face.  
 6' steel post beside corner  
 New Bt's - 10" D.Fir, bears N.7 1/2°W., 27.4', scribed "1/4 S 9 BT".  
 9" D.Fir, bears N.48°E., 31.2', scribed "1/4 S 9 BT".  
 9" D.Fir, bears S.70°E., 35.8', scribed "1/4 S 16 BT".  
 6' alum post beside corner with "Land Survey Monument" sign

Clyde Mulkins  
 for: I.P. Timber  
 Aug. 20,95  
 M 122-77

047

Corner of secs. 9,10,15, & 16  
 Mon. Fd.- 1945 GLO 2 1/2" brass cap  
 Bt's Fd.- 72" Orig. D.Fir stump, with no marks, bears N.43°W., 18' to  
 face.  
 44" Orig. D.Fir stump, bears S.42°E., 20.1'  
 44" Orig. D.Fir stump, bears S.1°E., 40.2'  
 48" Orig. D.Fir stump, bears N.4°W., 161'  
 6' steel post beside corner  
 New Bt's- 22" D.Fir, bears N.48°E., 7.4', scribed "S 10 BT"  
 14" D.Fir, bears S.19°E., 11.2', scribed "S 15 BT"  
 13" Maple, bears S.40°W., 39.3', scribed "S 16 BT"  
 15" D.Fir, bears N.68°W., 26.5', scribed "S 9 BT"  
 6' alum post beside corner w/ "Land Survey Monument" sign

Clyde Mulkins,  
 L.S. #2006  
 For: IP Timber  
 Lands Operating  
 Co. LTD  
 Oct. 1995  
 M 123-22

048

Cor. for Secs. 19 & 30 T21-8 only  
 Found - 1945 GLO brass cap  
 52" D.Fir stump, badly burned, bears S.20°E., 135 lks. (1945)  
 54" D.Fir uprooted stump, bears N.17 1/2°E., 360 lks., no visible  
 marks. (1945)  
 13" D.Fir, bears N.54°E., 7.3, with a healed face, not tagged.  
 (REN. #22) 19  
 15" D.Fir, bears S.59°E., 19.1', with a healed face, not tagged.  
 (REN. #22) 19  
 New BTs- 14" D.Fir, bears N.6°E., 26.3', scribed "T21S R8W S19 BT"  
 12" D.Fir, bears S.62°E., 4.8', scribed "T21S R8W S30 BT"  
 15" D.Fir, bears S.4°E., 16.7', scribed "T21S R8W S30 BT"  
 12" D.Fir, bears N.59°W., 21.0', scribed "T21S R9W X BT"

49

1/4 Cor. for Sec. 19 T21-8 only  
 Found - 1945 GLO Brass Cap  
 13" D.Fir, bears S.56°E., 33.5', with healed face.  
 New BTs- 15" D.Fir, bears N.1°W., 12.1', scribed "1/4 X BT"  
 16" D.Fir, bears S.3°W., 9.5', scribed "1/4 X BT"  
 11" D.Fir, bears N.61°W., 10.7', scribed "1/4 X BT"

50

Cor. for Secs. 13 & 24, T21-9 only (amended)  
 Set - 3/4"x36" alum. rod with a 3 1/4" I.P.T.O. alum. cap with mag. insert.  
 15" D.Fir, bears N.44°E., 13.9', scribed "AM CC X BT".  
 From which the 1945 brass cap set by G.L.O. bears: S.89°53'E., 2.71, and at  
 the corner was found:  
 1945 GLO brass cap.  
 15" D.Fir, bears N.15°W., 45.4', w/healed face. (Orig. Unknown)  
 New BTs - 13" D.Fir, bears N.38°W., 13.8', scribed "T21S R9W S13 CC BT".  
 16" D.Fir, bears S.42°W., 9.4', scribed "T21S R9W S24 CC BT".  
 15" D.Fir, bears S.11°W., 16.8', scribed "T21S R9W S24 CC BT".