

**Douglas County Surveyor's Record of
Government Corners Renewed**

T 21 T. S. R 9 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

32

C O N T --- (1/4 cor. sec. 1 only, T.21-10)

L. E. Monrean,
Deputy, Doug. Co.
Surveyors Office
Witnesses: S.J. Flauser;
K.S: Mosely
April 2, 1981
C.S. 61/19

New Accessories:

- Set boat spke stamped "BO 1" in pitch ring of 30" D. Fir stump bears S.67°W., 23.1 ft. (1919 BT)
- Set boat spike stamped "BO 2" in pitch ring of 14" D. Fir stump bears N.78°W., 14.1 ft. (1919 BT)
- Set boat spike stamped "BO 3" in pitch ring of 16" diam. 16" high D. Fir stump bears N.48°W., 19.0 ft.
- A D. Fir 14" double blazed and scribed "1/4 S1 CS BT" bears N.15°W., 26.9 ft.

All bearing objects tagged. Corner lies about 25 ft. south of cutting line running along ridgetop E-W.

4/281

90-13

Center 1/4 Corner for Sec. 9

- Set - 1-1/2" x 36" I.P. with Brass Cap attached, mkd. PLS #1039.
- New BTs- 18" Fir bears N.10°E., 8.7-ft. (scribed).
- 20" Fir bears S.79°W., 38.4-ft. (scribed).

11/30/81

33

Sec. Corner common to Secs. 22, 23, 26, & 27.

- Found - 50" Fir bears S.41-1/2°W., 31.0-ft. (scribe visible) 1894 BT.
- Set - 1-1/2" x 40" I.P. with Brass Cap attached, mkd. LS #1039.
- New BTs- 10" Alder bears N.57°E., 21.5-ft. (scribed).
- 17" Fir bears S.32°E., 94.1-ft. (scribed).

11/30/81

34

Sec. Corner common to Secs. 26, 27, 34, & 35.

- Found - 30" Fir stump bears S.20°E., 52.1-ft. (no marks). 1894 BT.
- 24" Hemlock stump bears S.59°W., 31-ft. (no marks) 1894 BT
- Group of Maples bears N.4-1/2°E., 37.6-ft. (no marks) 1894 BT
- Set - 1-1/2" x 36" I.P. & Brass Cap.
- New BTs- 12" Fir bears N.63°E., 33.5-ft. (scribed)
- 14" Fir bears S.45°E., 39.4-ft. (scribed)
- 14" Fir bears S.73°W., 33.8-ft. (scribed)
- 15" Fir bears N.44°W., 35.3-ft. (scribed)

11/30/81

35

M

1/4 Corner common to Secs. 26 & 27.

- Found - No evidence found of orig. corner.
- Set - 1-1/2" x 36" I.P. & Brass Cap at proportionate distance.
- New BTs- 37" Fir bears N.81°W., 21.0-ft. (scribed)
- 44" Fir bears S.7°E., 44.4-ft. (scribed)

11/30/81

36

Section corner for 1 and 12 only for T.21-10

- Found - No monument found. Construction of a log landing directly above corner has destroyed evidence at corner position. Oreg. 36" D. fir now a charred stump bears N.10°W., 28.4 ft. (We do not open blaze for scribing.) See Ren. #8
- A bridge spike set in rock stamped "BO 2" bears S.57 1/2°W., 172.08 ft. (Rec. 172.10 ft.) Ren. #50 of T.21-10
- A 5/8" dia. I.R. with alum. cap stamped "BO 1" bears S.60°E., 102.42 ft. (level chained 93.52 ft. + slope chained 11.97 ft. @ 42° slope) Rec. information indicates a distance of 102.08 ft. for this line. A review of the field notes for Ren. #50 (T.21-10) indicates measurements on steep slopes, I assume this the most probable line for error.
- A PK nail set in 30" dia. stump bearing S.60°E., 53.8.87 ft. not used as fog has visibility blocked.
- Set - At corner position as determined by noted courses, SET a 1" x 30" I.P. with brass cap attached marked "Douglas County Surveyor T21S R10W S1 S12 R9W 1982". Monument is buried 28" deep.
- New BO - Set a railroad spike stamped BO 3 in a charred 40" stump bears N.3°E., 56.9 ft.
- Sketch on field notes in C.S. file.

1/13/82

37

Les Roberts
For: International Paper Co.
November 30, 1981
M 90-13, & M 89-74

Larry E. Monrean
Deputy, Doug. Co.
Surveyors Office
John M. Powell
Jan. 13, 1982
C.S. 61/30

RE-RENEWED SET CORNER NO. #51

RE-RENEWED SET CORNER NO. 83