

Douglas County Surveyor's Record of
Government Corners Renewed

T. 21 S. T. S. R. 11 W. R.W.W.M.

NO. CHAPMAN CO. EUBANK, OR. 1961

38

Township Corner - T 20 S R12W S 36 | R11W
T 21 S S 1

Found - Orig. 15", now 30" Fir shattered Stump, N. 52° E. 28.4 ft. with
"T20S 11W 31 BT" scribe revealed.
Orig. 15", now 30" Fir 20' high Snag, S. 85° W. 40.9 ft., # 242
shows faint scar.
Orig. 12", now 18" Fir, badly decayed stump with frag. reverse
scribe marks, N. 82° W., 31.7 ft. No trace SE BT.
Unrecorded 40" Fir Stump bears N. 48° E. 40.1 ft. mkd. "S31 BT".
New BT's: 24" Hemlock N. 152° E. 30.1 ft. mkd. T20S R11W S31 CS BT.
No other trees close.

Note - This corner lies on moderate SE slope approx. 100 ft. S. of top
of ridge, Cl. Cor., Ren. #37, bears S. 195 ft. This area logged recently.

39

1/4 Corner to Sections 4 and 5.
Found - 3/4" I.P. with 1 1/2" x 4' I.P. 36" above ground for 1/4 corner.
Orig. 24" Cedar Stump S. 88° E. 9.6 ft. (Record S. 60° E. 11.9 ft.)
shows old line blaze on south side. We open 55 years, no scribe.
No trace of any other BT's.
R.E. Kleiner found this pipe in 1947 & stumps of old BT's with
burned faces. Call on creek fits real good. #88

Set - Brass Cap at Cor. Mkd: County Surveyor's T 21 S R 11 W
(Reset I.P. alongside) Office, 1967 S 5 | S 4

New BT's: 12" Alder S. 75° E. 39.1 ft. mkd. S 4 CS BT.
19" Alder S. 18° W. 50.3 ft. mkd. S 5 CS BT.

Note - This corner lies 66 ft. N. of creek, course S.W.

40

Section Corner to Sections 5 - 6 - 7 - 8.
Found - Stump of Corner Tree with frag. reverse scribing. #87
Orig. 10", now 26" Cedar, N. 122° E. 15.2 ft., 13.2 ft. face to face,
shows fragmentary scribe on opened blaze. Rescribe "T21SR11WS5 CSBT".
Orig. 42", now 46" Fir Stump, N. 21° W. 18.5 ft. face to face,
shows good scar. Do not open. No trace of other BT's.

Set - Brass Cap on W. Side of Corner Tree Stump Mkd: T 21 S R 11 W
County Surveyor's S 6 | S 5
Office, 1967 S 7 | S 8

New BT's: 40" Cedar N. 462° W. 27.0 ft. mkd. T21S R11W S6 CS BT.
36" Cedar S. 18° W. 30.1 ft. mkd. T21S R11W S7 CS BT.
No suitable Tree to SE.

Note - This corner lies approx. 350 ft. W. of main creek, course S, on
steep, SE slope. State forestry tag on 12" Alder on E. side of Ck.

41

Section Corner to Sections 3 - 4 - 9 - 10.
Found - Unrecorded 3/4" I.P., 14" above ground, set from Orig. BT.
Orig. now 16" Fir (called for 30") S. 25° E. 11.9 ft. (face)
Ring count is 80+ years on "BT" face, now snag, scribe marks
visible "T21S R11W S10 BT".
Depressions approx. where Orig. SW. & NE BT's. should be.
DID NOT SET BRASS CAP.

New BT's: 14" Spruce N. 24° E. 37.5 ft. mkd. T21S R11W S 3 CS BT. #94
20" D. Fir S. 23° E. 14.2 ft. mkd. T21S R11W S10 CS BT.
28" Maple S. 56° W. 42.6 ft. mkd. T21S R11W S9 CS BT.
52" D. Fir W. 70° W. 24.5 ft. mkd. T21S R11W S 4 CS BT.

Find stump called for in Forest Appraisal notes, now sawed open,
base S. 86° W. 15.2 ft., 48" diam., no scribe found.

Note - This corner lies on steep SW. slope approx. 150 ft. W. of top
of spur ridge sloping south.

42

West 1/16 Corner line btwn. Sections 4 and 9.
From Hub #88, we go N. 20° 19' 20" E. 74.9 ft. to the prop. point for
West 1/16 corner of Sections 4 & 9. See sketch in file.

Set - Brass Cap at Cor. Mkd: County Surveyor's W 1/16 S 4 | T21S
Office, 1967 S 9 | R11W

New BT's: 20" Hemlock S. 38° E. 20.0 ft. mkd. W 1/16 S 9 CS BT.
7" Alder N. 1° W 18.6 ft. mkd. W 1/16 S 4 CS BT.

Note - This corner lies on top of spur ridge sloping S.W.

Vernon "Ray" Tracy
Jack Heritage and E. West
March, 1967

C. S. File No. 54/1

Vernon "Ray" Tracy
For Douglas County
With: J. Byron-J. Heritage & E. West
June 29, 1967
C.S. File No. 54/47 M 33 - 18