

**Douglas County Surveyor's Record of  
Government Corners Renewed**

T 22                      T. S.   R 4                      R. W. W. M.

158

Donald Peel, L.S. 752  
For: Weyerhaeuser  
Sept. 1992  
M 115-77

1/4 Corner for secs. 8 and 17  
Found - 1 1/4" iron pipe with 1965 DCSO brass cap. Ren. #112  
26" Fir N.81 1/4°E., 41.1 ft., closed face.  
32" Cedar S.18 1/2"W., 33.8 ft. closed face, BLM tag.  
16" Fir stub, N.21 3/4°W., 63.9 ft. visible scribe "BT". (Orig.)  
25" Fir S.53 3/4°W., 19.3 ft. closed face. No record of this BT

Steven P. Ness  
For: Weyerhaeuser Co.  
March 30, 1993  
M 116 - 66

West 1/4 Cor. Section 21  
Found - 2 1/2" DCSO brass cap on 1 1/4" Iron post. Ren. #53 & 72  
16" R.Alder S.6°16'E., 7.9 ft. small healed face. (No record.)  
24" W.R. Cedar S.88°21'E., 35.5 ft. healed face (Rec. S.88°E 53 lks.)  
20" W.R. Cedar S.26°53'W., 28.5 ft. healed face (Rec. S.27°W., 44 lks.)  
17" W.R. Cedar N.56°15'W., 20.7 ft. healed face (Rec. N.56 1/4°W., 32 1/2 lks.)

159

Center 1/4 Corner Section 21  
Set - 2 1/2" Brass cap on 2" x 40" Iron pipe marked: T22S R4W C 1/4 S21 "1993 RPLS 811".  
BTs - 8" D.Fir N.45 1/4°E., 32.4 ft. to center, 32.05 ft. to "W" nail, scribed "BT" on low face, blaze "X" chest high.  
4" D.Fir N.2°W., 24.9 ft. to center, 24.79 ft. to "W" nail, scribed "BT" on low face, blaze "X" chest high.  
No accessories available to the South.

160

3/93

Section corner for Sections 19, 20, 29 & 30.  
Found - 2 1/2" USBLM Brass cap dated 1963. See renewal # 12.  
48" Cut Fir stump remains at 1963 record, S.63°E., 91 lks - original BT Fir stump remains S.41 3/4°W., 55.1 ft. - deadfall has scribing (1963 record S.42°W., 86 lks. - orig. BT)  
24" stump remains at 1963 record N.73°W., 48 lks.  
9" Fir snag 1963 record N.60°E., 15.5 ft. - scribing visible on remains which are down and out of position.  
8" Fir stub, N.23°E., 36.4 ft. - scribing visible (1963 record N.22 1/4°E., 54 lks.)  
12" Fir, S.37°E., 44.9 ft. - closed face (1963 record S.33 1/4°E., 68 lks)  
8" Fir snag, S.76 3/4°W., 40.0 ft. scribing visible (1963 record S.77°W., 61 lks)  
14" Fir stub, N.20°W., 26.8 ft. - closed face (1963 record N.21°W., 41 lks)  
8" Oak, N.75°W., 4.3 ft. - closed face  
- unknown 3/4" iron pipe, N.20°W., 1.7 ft.

161

Daniel Baker  
For: Weyerhaeuser Co.  
Nov. 1994  
M 119 - 20

N.E. Corner DLC # 39.  
Found - Broken stone at base of fence corner post per M61-79.  
36" burnt stump, N.26°E., 61.0 ft. - no marks remain.  
Set - 2" x 42" iron pipe with brass cap marked "T22S R4W NE DLC 39 S20 PLS 1978 1993", stones placed alongside.  
New BTs -  
14" Fir, N.64°W., 7.8 ft. to "W" nail, scribed "NE DLC 39"  
20" Fir, S.6°E., 4.3 ft. to "W" nail, scribed "NE DLC 39"  
6 ft. fence post, 1 ft.

162

Les Roberts, LS1039

For: Seneca Jones  
Timber Co.

M 121-26  
Dec. 1994

1/4 Cor. Secs. 5 & 6  
Found - 24" Fir stump, S.75°W., 19.9', (scribe vis.) 1855 BT.  
24" Fir stump, N.37°E., 29.0', (scribe vis.) 1855 BT.  
Set - 5/8"x30" iron pin w/yellow plastic cap stamped "ROBERTS P.L.S. 1039"  
26" Fir, S.85°W., 34.5' (scribe vis), 1953 BT-Gardner (REN #14)  
36" I.Cedar, S.70°E., 30.3' (scribe vis), 1953 BT-Gardner

163

1/6/95