

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 22 S. T. S. R. 5 W. R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

Donald Peel  
For Weyerhaeuser Co.  
Feb. 1992  
M114 - 60

Section Corner for 4, 5 & 32, 33 of T.21-5. **RE-RENEWED SEE CORNER NO. #213** 209  
CONDITION REPORT ONLY See renewal #60.  
Found - 3/4" iron pipe  
48" Fir, N.41<sup>3</sup>/<sub>4</sub>°E., 12.2 ft. - closed face BLM tag.  
17" Fir stump, S.22<sup>1</sup>/<sub>4</sub>°E., 31.0 ft. - cut below scribing.  
15" Fir stump, S.37<sup>1</sup>/<sub>4</sub>°W., 39.1 ft. - cut below scribing.  
17" Fir, N.51<sup>1</sup>/<sub>2</sub>°W., 17.7 ft. - closed face.

Section Corner for 5, 6 & 31, 32 of T.21-5 (Ren #3) 210  
Set - By proportionate measurement a 2" x 41" iron pipe with brass cap.  
22" Cedar, N.48°E., 24.4 ft. - scribed "T21S R5W S32 BT"  
26" Fir, S.61°E., 19.7 ft. - scribed "T22S R5W S5 BT"  
8" Fir, S.8°W., 38.4 ft. - scribed "T22S R5W S6 BT"  
11" Fir, N.86°W., 13.1 ft. - scribed "T21S R5W S31 BT"

1/4 Corner for Sections 4 & 5. 211  
CONDITION REPORT ONLY See renewal #111.  
Found - 8" x 4" x 8" above ground stone - etched "1/4S" on north face and  
"CS" on top and "1/4" on south face.  
5/8" rebar on south edge of stone. (used center of stone for corner  
point)  
5' high, 20" Fir stump, N.27<sup>1</sup>/<sub>4</sub>°E., 14.2 ft. - closed face.  
27" Fir, S.41<sup>1</sup>/<sub>2</sub>°W., 29.2 ft. - closed face, BLM tag.

1/4 Cor Sec of 6 & 31 of T21-5 212  
Monument Set - 5/8" x 30" rebar w/ YPC "LS 2603"  
Accessories Set - 18" D.Fir, N.25°W. 7.7', blazed & scribed "S<sup>1</sup>/<sub>4</sub> SEC 31  
BT".  
12" D.Fir, N.46°E. 13.1'. blazed & scribed "S<sup>1</sup>/<sub>4</sub> SEC 31  
BT".  
9" D.Fir, S.53°E. 15.8', blazed & scribed "N<sup>1</sup>/<sub>4</sub> SEC 6 BT".  
13" D.Fir, S.15°W. 32.7', blazed & scribed "N<sup>1</sup>/<sub>4</sub> SEC 6  
BT".

Sec. Cor. to 4, 5, & 32, 33 of T21-5 213  
Monuments FD. - 1" OD I.P. (Ren # 209)  
Monuments SET - 6" fence post 1" west  
Accessories FD. - 50" D.Fir Stump, N.42°E. 12.2', healed face  
17" D.Fir, N.52°W. 17.7', healed face  
15" D.Fir Stump, (S37°W. 39.1'), missing  
17" D.Fir Stump, (S.22°E. 31'), missing

1/4 Corner Secs. 9 & 16 214  
Found - 42" B.Oak O.B.T., N.40°W., 26 lks with scribing .  
Other old BT destroyed.  
Set - 5/8"x24" rebar with cap [RILEY 705]  
12" Fir, N.28°E., 19.0' [<sup>1</sup>/<sub>4</sub> S9 BT]  
6" Fir, S.18°E., 2.4' [<sup>1</sup>/<sub>4</sub> S16 BT]  
7" Fir, S.30°W., 12.4' [<sup>1</sup>/<sub>4</sub> S16 BT]

NW  
Twship. ~~SE~~ cor. sec. 06 215  
Monuments Fd. - 14"x14"x7" stone with a probable "+" mkd. on side, stone  
appears to have been tipped over and is in two  
pieces. stone was found 1 ft. below ground. (set by  
Haines in 1943 see Ren # 60.)  
Accessories Fd. - 40" now 47" dia. D.Fir, with a fully healed single blaze,  
bears S.21°E. 31' (agrees w/ rec.) ren. # 60.  
8" now 21" dia., D.Fir, with a fully healed double blaze,  
bears N.72°E. 56' (agrees w/ rec.) Ren. #60.  
18" now 15" dia., B.Oak, with a fully healed double blaze,  
bears S.28°W. 18.8' (agrees w/ rec.).  
8" now 12" dia., W.Oak, with a fully healed sing blaze,  
bears N.2°W. 10' (agrees w/ rec.) Ren. #60.

Do Co. SURVEYOR  
RANDALL SMITH  
STEPHEN FLAUSE  
11/2/90  
C.S. 64/58

Gerald Riley  
Arlie Land &  
CATTLE Co.  
June 1994  
M 121-36

N.W. Timberland Cons.  
Harvey Christensen  
Nov. 10, 1994  
M 121 - 21

RE-RENEWED SEE CORNER NO. #213

BOOK  
M121-24  
11/10/94

RE-RENEWED SEE CORNER NO. #197