

Douglas County Surveyor's Record of  
Government Corners Renewed

T 22 T. S. R 6 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

162

Sec. Corner for 27 and 34 only (East)

Found - 3 1/4" dia. BLM brass cap on a 2 1/2" O.D. Iron pipe protruding 3" above ground. (1963 BLM)

Haines "T" iron is 0.4 ft. south east of BC/IP protruding 4" above ground. (Not filed, see Haines F.B. No. 107)

20" now down and rotted, no scribing visible, root hole bears S.36°W., 16.5 ft. (agrees w/rec) Orig. BT.

Orig. NW BT is gone.

6" now 11" dia. down D.Fir with a fully healed single blaze root hole bears S.80°W., 16.8 ft. (agrees w/rec) Haines

6" now 8" dead D.Fir with a fully healed single blaze, bears N.78°W., 22.8 ft. (agrees w/rec) Haines.

New BTs - 24" dia. 1 ft. tall G.Fir stump. A boat spike is driven through BT tag near center on top of stump. Boat Spike bears N.67°W., 24.0 ft.

14" dia. G.Fir, double blazed and scribed "CC T22S R6W S34 CS BT" bears S.3°W., 50.5 ft.

16" dia. G.Fir double blazed and scribed "CC T22S R6W S34 CS BT" bears S.43°W., 25.0 ft.

18" dia. G.Fir double blazed and scribed "CC T22S R6W S34 CS BT" bears S.78°W., 43.4 ft.

2/25/92

163

Section Corner for Secs. 33 and 34 (South)

Found - A 2 1/2" dia. GLO brass cap on a 1 1/2" O.D. Iron pipe flush with ground. (1955)

6" now 18" dia. D.Fir with a fully healed single blaze, bears N.67°W., 23.8 ft. (agrees w/rec) 1955 BT

7" now 19" dia. D.Fir with a fully healed single blaze, bears N.33°E., 16.5 ft. (agrees w/rec.) 1955 BLM BT

No evidence remaining of original NE BT.

36" now down and rotting D.Fir of indeterminable size, no blazes or scribing visible, possible root hole bears N.83°W. 66.0 ft. (agrees w/BLM record) Orig. BT.

New BTs - 15" dia. D.Fir double blazed and scribed "T22S R6W CC S33 CS BT" bears N.10°W., 15.8 ft.

11" dia. D.Fir double blazed and scribed "T22S R6W CC S34 CSBT" bears N.82°E., 30.3 ft.

Corner is approx. 30 ft. East of a West and North running cut line corner.

2/18/92

1/4 Corner for Sections 8 and 17

Found - A 3 1/4" dia. brass cap on a 2 1/2" dia. Iron pipe firmly set and protruding approx. 3" above ground. (1976)

A 2 1/2" dia. Iron pipe with 3 1/4" dia. brass cap stamped "1/4 S 8 RM 1976". Also stamped with an arrow pointing southwesterly toward corner position., is firmly set and protrudes 4" above ground. This reference monumnet bears N.6 1/2°E., 104.9 ft. (Rec. N.3 1/4°E., 104.9 ft.)

A Redwood 26" dia., now a 41" DBH Coast redwood with a fully healed double blaze bears S.51 1/2°W., 67.3 ft. (Rec. S.48°W., 67.3 ft.)

New Accessories:

The Southwest concrete block corner of storage shed bears S.25 1/2°W., 20.2 ft.

27" DBH W.Oak scribed 1/4 S8 CS BT on a double blaze bears N.58 1/2°W., 152.6 ft.

Monument is at entrance to private tree and shrub nursery. Nursery lies south across covered bridge.

2/25/92

165

South 1/4 Corner for Section 34 only

Set - 5/8" x 30" rebar with yellow plastic cap marked "Branch Eng. L.S. 1138". Corner was set on the North boundary of T.23S., R6W. at cardinal intersection from computed midpoint between SW and SE corners of Sec. 34.

New BTs - 12" Fir scribed "1/4 S34 BT" bears N.67°00'E., 57.7 ft.

& Access. Set 5/8" x 30" rebar marked "Ref Mon LS 1138", bears N.29°15'E., 36.9 ft.

Set 5/8" x 30" rebar mkd: "Ref Mon L.S. 1138" bears N.15°00'W., 34.7 ft.

5/8" x 30" rebar mkd. "Ref Mon LS 1138" bears N.68°30'W. 36.7 ft.

Douglas County  
Surveyors Office  
Randall Smith  
John Pike  
Feb. 25, 1992  
C.S. File 64/24

Douglas County  
Surveyors Office  
Randall Smith  
Stephen Flause  
Feb. 18, 1992  
C.S. File 64/24

Douglas County  
Surveyors Office  
Randall Smith  
Stephen Flause  
Feb. 25, 1992  
C.S. File 64/24

James W. Branch  
For: U.S. National  
Bank  
May 4, 1992  
M 115 - 23  
C.S. File 63/138

FD OK  
BY BENTZ  
M 115 - 23  
5/93