

Douglas County Surveyor's Record of
Government Corners Renewed

T 22 T. S. R 7 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

178

SE corner DLC #39
Found - Stone
New BT's- 14" B. Oak bears N.16°W., 9.25 ft. scribed SE DLC 39 BT.
10" B. Oak bears N.82°E., 23.1 ft. scribed SE DLC 39 BT.

9/79

Eugene A. Bloom
L.S. #492
For: Francis Mode
Sept. 1979
M 80 - 19A & B

179

1/4 Corner between Sec. 18 and Sec. 13 of T.22-8
Set - 1 1/2" Iron pipe with International Paper Co. brass cap.
BT's - 13" Fir, N.8°E., 8.4 ft.
7" Fir, N.88°W., 16.2 ft.

180

SW corner Lot 1, Sec. 18 and the SE corner, Lot 1, Sec. 13 T.22-8
Set - 1 1/2" Iron pipe with International Paper Co. brass cap.
BT's - 12" Alder, N.25°E., 29.2 ft.
17" Alder, N.60°W., 16.0 ft.

Les Roberts
For: International Paper Co.
June 1980
M 84 - 39

181

NW corner Lot 7, Section 18.
Set - 1 1/2" Iron pipe with International Paper Co. brass cap.
BT's - 22" Fir, N.1°E., 19.1 ft.
10" White Fir, N.78°E., 21.4 ft.

6/80

182

S. W. Corner for DLC #41
Found - No evidence found of original corner. See Ren. #6
Set - New corner set at proportionate distance. Set 1 1/2" x 33" I.P. with brass cap.

BT - 30" White Oak, bears N.81°E., 40.8 ft.
FD OK, Robert Dolan, Dec. 94, M121-42

Les Roberts, Triangle Engineering
For: Norman Rydell
Dec. 1980
M 86 - 29

183

N. E. Corner, DLC #42
Found - No evidence found of original corner.
Set - New corner set by "broken boundary method".
Set - 1 1/2" x 33" I.P. with brass cap.
BT's - 18" Black Oak, N.43°W., 74.0 ft.
28 " White Oak, S.12°W., 106.2 ft.

12/80

CC. FD. OK 2/94 BY HOFFINE, C.S. 63/154-5

184

Sec. corner for Sec's. 25 and 36.
Found - Brass Cap on a 1" Iron Pipe, properly marked, firmly set, protruding 12" above ground.
BT's - 31" Fir (orig. 20") bears N.71°W., 93.1-ft. rescribed Ren.#64. The scribed "S" visible in partially healed blaze. Tree is uprooted.
New BT's- 22" W. Fir scribed "T22S R7W S36 CS BT" on double blaze bears S.37°W., 22.2-ft.
16" D. Fir scribed XBO CS BT on double blaze bears S.30 1/2 °E., 38.0-ft.
16" D. Fir scribed "T22S R7W S25" on double blaze bears N.25 1/2 °W., 52.8-ft.

9/17/81

CC. FD. OK 2/94 BY HOFFINE, C.S. 63/154-5

185

Sec. corner for Sec's. 30 and 31 of T.22S.R.6W. only.
Found - Brass Cap on a 1" Iron Pipe, properly marked, firmly set, and protruding 8" above ground.
BT's - Orig. 36" Cedar, rescribed by Byron (Ren.#63): "T22S R6W S30 BT" legible. This tree now a badly decayed stump with debris piled against it. Stump bears N.83°E., 155.7-ft. to approx. center (Rec. N.83°E., 156.4-ft.).
The orig. 48 Fir, now a decayed stump with no scribing or blaze remaining bears S.29°E., 96.1-ft. to approx. center (Rec. S.30°E., 93.1-ft.)
Snag (orig. 55" Cedar) scribed "T22S R6W CS BT" bears S.76°E., 128.0-ft. (scribe visible).
New BT's-12" D. Fir scribed "T22S R6W S31 CS BT" on double blaze, bears S.28°E., 89.6-ft.
14" D. Fir scribed "T22S R6W S30 CS BT" on double blaze, bears N.88 1/2 °E., 46.5-ft.

Larry E. Monrean
Deputy Doug. County Surveyors Office
T.R. Plouff, witness
Sept. 21, 1981
C.S. 61 / 27