

Douglas County Surveyor's Record of  
Government Corners Renewed

22 T. S. 10 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

G. Robert Lecklider  
For General Const. Co.  
June 1960  
Map File M. 19 - 14

16

$\frac{1}{4}$  Section Corner to Sections 5 and 8.  
Found - Stone Marked "+"  
Fir Stump Hole - S.78°E. 99 ft.  
Set - Steel Tube with Survey Cap  
8" Fir East 18.6 ft.  
6" Fir S.45°E. 9.5 ft.

17

M. C. Section 5 and 8.  
Found - 56" Fir - N.1°E. - 19.8 ft., chopped open.  
Spruce Stump Hole - N.35°W. 66 ft.  
Set -  $\frac{3}{4}$  x 54" Pipe  
20" Fir - S.20°E. 86.0 ft.

18

M. C. Section 5 and 6.  
Found - 56" Fir - N.45°E. - 14.5 ft., chopped open.  
Set -  $\frac{3}{2}$ " x 54" Pipe  
18" Fir - N.10°W. - 22.3 ft.

19

Wilford N.  
Haines.  
M 13 - 63

Section Cor. to Secs. 13 & 24, T22-10W. & Secs. 18 & 19, T22-9W.  
Found - Original Corner and all Bearing Trees are Standing.  
Drove - 1" x 1" x 36" Iron Rod in Ground.

Nov. 12, 1958

20

James W. Byron  
D. McFarland  
J. Powell.  
Aug. 1, 1961  
C.S. File  
No. 52/86

Meander Corner Sections 23 and 24, Left Bank.  
Found - 24", now 30" Maple S.79°22'W. 40.5 ft., shows good scribe  
marks on old face.  
S. E. BT. down.  
Set - Brass Cap at Corner Mkd: County Surveyor's Office, 1961  
M. C. S23/S24 T22S R10W  
New BT: 12" Myrtle S.62°E. 48.9 ft. scribed MC S24 CS BT.

RE-RENEWED SEE CORNER NO. #82  
SEE REN. #1

21

East  $\frac{1}{4}$  Corner to Section 13.  
Found - Orig. 12", now 30" R.Fir N.61°W. 18.5 ft., not 14.5 ft. Shows  
good scar at base and old face, above previously opened &  
partly burned, no scribing found.  
Find Sandstone at Corner chisled  $\frac{1}{2}$ S on West Face.  
Set - Brass Cap alongside Corner Stone Mkd: County Surveyor's Office, 1961  
 $\frac{1}{4}$  S13 T22S R10W.  
New BT's: Rescribe O.B.T. N.61°W. 18.5 ft.  $\frac{1}{4}$  S13 CS BT.  
9" R.Fir bears N.29°E. 24.7 ft. scribed S18 CS BT.

Fd 7/89  
R-STUNTZNER  
M 108-41

22

Section Corner to Sections 14 - 13 - 23 - 24.  
Found -  $1\frac{1}{4}$ " I. P. at corner & Fir Snag, burned out face, S.18°W. 7.3 ft.  
Now 48" Fir Stump that checks for N.E. BT.  
No other BT's. found.

Fd. SEE M 88-68  
M 92-81

New BT's: 25" R.Fir bears N.75°E. 24.0 ft. scribed S13 T22S R10W CS BT.  
12" R.Fir bears S.47°E. 35.2 ft. scribed T22S R10W S24 CS BT.  
8" R.Fir bears N.27°W. 37.9 ft. scribed S14 CS BT.  
7" R.Fir bears S.44°W. 44.7 ft. scribed S23 CS BT.

FND. OK  
8-91 BY WILCOX  
M-113-76 AFB

James W. Byron, Deputy  
D. McFarland & J. Powell  
For Doug. Co. Park Dept.  
Sept - Oct. 1961  
C.S. File No. 52/86 M 22-16