

Douglas County Surveyor's Record of
Government Corners Renewed

T 22 S T. S. R 12 W R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

35

$\frac{1}{4}$ Section Corner between Secs. 11 & 14.
Find - 1" Iron Pipe for the $\frac{1}{4}$ Corner (See Ren. #13)
and one Orig. BT. stump, from which:
New BT's: 10" Fir bears S. 36° 30' W. 107.5 ft.
(From Ren. #13) 4" Hemlock bears N. 78° 30' E. 40.2 ft. (Orig. BT).

B. Holt 10/84
SEE M 97-63
FOR MORE INFO.

36

$\frac{1}{4}$ Section Corner between Secs. 12 & 13.
Found - 3" x 4 $\frac{1}{2}$ " Alder Post for the corner from which:
50" Fir Stump bears S. 61° 30' W. 72.6 ft.
50" Fir Stump bears N. 86° W. 31.6 ft.
(Orig. BT's, scribing visible.)
Set - New Red Cedar Post for the corner, from which:
New BT: 18" Red Cedar bears N. 61° 31' W. 52.9 ft.

#128

RE-RENEWED

37

West 1/16 corner btwn. Secs. 12 and 13.
Set - W. 1/16 corner equidistant between the Sec. Cor. to
Secs. 11-12-13-14 & the $\frac{1}{4}$ Sec. Cor. betwn. Secs. 12 & 13
at 1,297.55 feet from the above corners.
 $\frac{3}{4}$ " Iron Pipe for the corner, from which:
New BT's: 8" Fir bears S. 42° 30' E. 24.0 ft.
16" Red Cedar bears N. 48° W. 19.9 ft.

38

$\frac{1}{4}$ Section Corner between Sections 13 and 14.
Set - New Red Cedar Post for the $\frac{1}{4}$ Corner, from which:
26" Hemlock bears N. 65° E. 8.6 ft. is tipped over.
40" Fir bears N. 62° W. 23.1 ft. (scribing visible).

#127

RE-RENEWED

ED. BK. #176 - D. STUNTER M 60-22

39

North 1/16 corner between Sections 13 and 14.
Set - N.1/16 corner equidistant btwn. the section corner
and the $\frac{1}{4}$ corner.
 $\frac{1}{2}$ " Iron Pipe, 1,282.70 feet from the adjacent
corners, from which:
Red Cedar Stump 52" diam. bears S. 79° E. 37.0 ft.
scribed N 1/16 T22S R12W.

40

Section Corner to Sections 11 - 12 - 13 - 14.
Found - Old Cedar Limbpost for Corner.
Set - $\frac{3}{4}$ " Iron Pipe along the side of the old post, from which:
A Fir Stump, now 50", bears N. 79° W. 39.0 ft.
A Fir Stump, now 40", bears S. 62 $\frac{1}{2}$ ° W. 19.40 ft.
(Both Orig. BT's.)

#148

RE-RENEWED

May - June 1965

41

$\frac{1}{4}$ Corner to Sections 2 and 1.
Found - 38" Rotten Fir Stump S.45°E. 21.7 ft.
Set - $\frac{1}{2}$ " Iron Pipe
Tagged - 26" W. H. N. 23°W. 57.8 ft.

2/24/71 -(Set Steel Fence Post Alongside I. Pipe, See Co. Survey M 42 - 27)

42

$\frac{1}{4}$ Corner to Sections 2 and 11.
Set - $\frac{1}{2}$ " Iron Pipe in Creek.
Scribed Two Bearing Trees:
12" W. H. N. 76° 30' W. 19.3 feet.
40" W. H. N. 65° 00' E. 47.1 feet.

RE-RENEWED

63

43

Section Corner to Sections 2 - 11 - 3 - 10.
Found - 1 $\frac{1}{2}$ " I. Pipe with Brass Cap (See Ren. # 11)
Original BT. N. 25° W. 11.5 ft.
Scribed Two New Bearing Trees:
10" W. H. N. 38° W. 48.5 feet
38" W. R. C. S. 14° E. 83.2 feet.

Clifford A. Stephens
For J. Lightfoot
May - June 1965
C. S. File No. 51/321 Map File

M 22 - 72

By Clifford A. Stephens
For C.H.T. Co.
August 1965
Map File M 22 - 71