

Douglas County Surveyor's Record of
Government Corners Renewed

22 T. S. 12 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

John M. Powell, County Surv. Office
J. Heritage, L. Monrean,
G. Commons
April 19, 1973
C.S. File 56/25

103

Section Corner, Secs. 21-22-28-27.

Found - 1" I. Pipe at cor. badly rusted. Ren. No. 18
9" Spruce, now 10", S. 22°W., 5.8 ft. scribe visible. 257
8" Spruce, now 9", S. 68°E., 2.5 ft. scribe visible.
7" Hemlock, now 9", N. 30°E., 3.5 ft. scribe visible.
9" Spruce, now 10", N. 80°W., 15.1 ft. shows good scar.
Set - Brass cap at sec. cor. mkd. County Surveyor's T 22 S R 12 W
Office S 21 | S 22
1973 S 28 | S 27

Note - Tagged all bearing trees.

4/17/73

1/4 Corner, sections 22 and 27.

Found - 18" D. Fir, Now 22", S. 22°E., 18.0 ft. shows good scar. Ren. No. 19
16" D. Fir, now 19", S. 80°W., 14.5 ft. shows good scar.
Also cedar cor. tree, now snag.
Set - Brass cap on east side of cor tree mkd.
County Surveyor's T 22 S R 12 W
Office 1/4 S 22
1973 S 27

New BT - 14" Hemlock, N. 52°E., 26.2 ft. scribed 1/4 S22 CS BT.

4/19/73

1/4 Corner to Sec. 30, R12W. and Sec. 25, R13W. Found Only.

Found - 1/2" I. Pipe recorded in M 20 - 69, no other record.
2 unrecorded BT's., as follows:
6" Dead Fir N. 59°E. 21.2 ft., scribe visible, "S 0 T22R12 OS".
22" Dwarf Pine N. 30°W. 57.8 ft., scribe visible, "1/4 S25 T22SR13W",
scribed about 30 - 40 years ago.

Note: No "BT" scar or scribe on either tree, No Trace of Orig. BT's. Fd.
This corner lies approx. 250 ft. S. of Power Line Access Road at
South end of Clear Lake.

FD. OK 2/18/75 Co. Surveyors Office - L.E.M. C.S. 59/46 8/15/73

1/4 Corner to Sections 19 and 20.

Found - Orig. BT's., as follows:
15", now 50" Hemlock (10' high snag) N. 34°E. 14.5 ft., scribe vis. "1/4 S".
15", now 40" Hemlock, N. 62°W. 22.4 ft., alive, shows faint scars,
tagged in 1948.

Set - Brass Cap at Cor. Mkd: County Surveyor's T 22 S R 12 W
Office, 1972 1/4 S19 | S20

New BT's: 12" Spruce N. 84°W. 15.3 ft. mkd: "1/4 S19 CS BT".
18" Hemlock N. 87°W. 3.0 ft. mkd: "1/4 S20 CS BT".

This corner lies in very dense brush 16.5 ft. S. of dry Creek, course S.W.
FD. OK 2/19/75 L.E.M. C.S. 59/46 8/15/73

Meander Corner to Sections 19 and 30.

Found - 3/4" Iron Pipe, set by Menasha in March, 1973, at point for
most Easterly Meander Corner.

Orig. 8", now 16" Cedar S. 57°E. 11.9 ft., prev. opened, No scribe
found, blaze decayed, we rescribe:

"M.C. T22S R12W S30 CS BT" alongside old scribe.

DO NOT SET BRASS CAP - 3/4" I. P. set for corner lies about 6 ft.
from water's edge. 8/16/73

FD. OK - 2/20/75 Co. SURV. OFFICE L.E.M. C.S. 59/46

Meander Corner for Sec. 25, T22-13 & Sec. 30, T22-12.

Found - 34" Spruce, now down, S. 87°W. 13.9 ft., open
for scribing, "T22".

50" Spruce Snag 44.9 ft. North, tree given as call.
Set-Brass Cap at M.C. mkd: County Surveyor's Office
M. C. T 22 S

R13 S25 | S30 R12
1973

New BT! 6" Yellow Wood N. 16°E. 9.0 ft. scribed "M.C. S30 CS BT".

Note - Lies on S.E. Corner of ridge running, 10/2/73
Also at water's edge.

Vernon "Ray" Tracy, Co. Surv. Office
J. Heritage & J. Isgro (Land Dept.)
C. S. File No. 56/35

Ed Monrean
J. Powell
C.S.
File
No. 56/39

RE-RENEWED SECTION NO. #168 AND #163

104

105

106

107

108