

Douglas County Surveyor's Record of  
Government Corners Renewed

T 22 T. S. R 12 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

C O N T. - - -

170

Larry E. Monrean  
Deputy, Doug. Co.  
Surveyors Office  
J.M. Powell; T.R.  
Fransenn  
Oct. 18, 1982  
C.S. 62/1

(Sec. Cor. 8, 9, 16 and 17)  
Set - At the temporary point noted at record bearing and distance from the found NE bearing tree stump, WE SET a 1" x 30" iron pipe with a brass cap attached and stamped "Douglas Co. Surveyor T22S S8 S9 S17 S16 R12W 1982". Monument protrudes 10" above ground.  
New BTs - R. cedar 15" double blazed and scribed "T22S R12W S8 CS BT" bears N.31°W., 14.5 ft.  
Spruce 20", double blazed and scribed "T22S R12W S9 CS BT" bears N.85°E., 22.6 ft.  
R. cedar 14", double blazed and scribed "T22S R12W S16 CS BT" bears S.35 1/2°E., 18.8 ft.  
R cedar 14", double blazed and scribed "T22S R12W S17 CS BT" bears S.73°W., 22.3 ft.  
All new BTs tagged.

10/18/82

171

Section Corner common to Secs. 4,5,8, & 9.  
Set - 1-1/4" x 36" I.P. w/stamped brass cap (PLS 497).  
New BTs- 14" hemlock bears N.73°0'E.,25.5-ft.  
10" cedar bears S.77°0'E.,21.6-ft. (all BTs scribed)  
16" spruce bears S.74°0'W.,16.0-ft.  
12" hemlock bears N.2°15'W.,9.3-ft. 5/83

1/4 Section Corner common to Secs. 4, & 9.  
Set - 1-1/4" x 36" I.P. w/stamped brass cap (PLS 497).  
New BTs- 16" alder bears S.1°45'W.,16.0-ft. (scribed)  
16" spruce bears N.17°15'W.,11.5-ft. (scribed)  
note - Corner is 20-ft. south of creek, course east.

Feb 9/83  
M 117-64

5/83

172

1/4 Section Corner common to Secs. 5, & 8.  
Set - 1-1/4" x 36" I.P. w/stamped brass cap (PLS 497).  
New BTs- 18" spruce bears N.51°30'E.,11.8-ft. (scribed)  
22" fir bears S.21°0'E.,24.1-ft. 5/83

FOR CORNER  
REPORT, SEE  
C.S. 63/46

173

1/4 Section Corner common to Secs. 8, & 9.  
Set - 1-1/4" x 36" I.P. w/stamped brass cap (PLS 497)  
New BTs- 30" fir bears S.48°0'E.,10.4-ft. (scribed)  
20" fir bears S.30°30'W.,10.1-ft. 5/83

174

CE 1/16 Section 22  
Found - 1982 brass cap monument at gravel road intersection, 8" below surface. See M 92 - 58 and C.S. 58/290  
A 10" alder now a 12" dia. 6 ft. stump, bark scribed "CE 1/16 S22 BT" bears N.61 1/2°W., 24.1 ft. (Rec. N.58°W., 23.8 ft.)  
5/8" dia. iron rod 15" high bears South 42.7 ft. (Rec. 42.2 ft.)  
BTs from M 92 - 58 evidently destroyed during road construction not found.  
New Accessory:

Set 1/2" x 8" bridge spike into 48" dia. cedar stump. Spike bears N.13°E., 94.7 ft. stamped "B0" and is set through a County Surveyors bearing tree tag. Stump is 4 ft. high on uphill side.

175

L. E. Monrean, Deputy  
Deputy, Douglas Co.  
Surveyors Office  
R. W. Smith  
1/8/85  
C.S. 62/25

CN 1/16, Section 22  
Found - 1982 brass cap monument protrudes about 2" above ground. 5 ft. tall metal fence post along northerly side of monument. (M 92 - 58)  
23" hemlock with visible scribing "CN 1/16 S22 BT" on a double unhealed blaze bears N. 18 1/2°E., 9.6 ft. (Rec. N.20°30'E.)  
New BTs - 12" dia. hemlock double blazed and scribed "CN 1/16 S22 CS BT" bears S.20°W., 5.2 ft.  
8" dia. Alder bark scribed "CN 1/16 S22 CS BT" bears S.64°W., 23.8 ft.  
Both trees pistol butt measurements of bearing and distance taken to center of root crown.

176