

Douglas County Surveyor's Record of
Government Corners Renewed

T 22

T. S. R 12

R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

188

1/4 Corner for Section 4; and Sec. 33 of T.21-12
(Did not find original evidence)

Set by single proportion: 36" alum. rod 1" high by Spruce root in
draw with cap mkd. "1/4T21SR12WS33T22SS4".

New Accessories:

12" Sitka Spruce N.80°E., 2.8 ft. mkd. "BT"

16" D. fir S.46°E., 29.7 ft. mkd. "BT".

Edge of golf course green ± 40 ft. easterly.

Northmost corner of second story of large house overlooking
golf course bears S.46°W., 122 ft.

Note: Due to proximity to residences and golf course these trees were
only marked with lower faces and did not have back tags or red painted
bands.

10/86

189

Section Corner for Secs. 28, 29, 32 and 33

Found - 1977 Brass cap/iron pipe at orig. corner position as perpetuated
by Bruce Shaner. Ren. #131

Orig. BT, 46" D. fir stump S.46°E., 11.2 ft. (Rec. S.32°E)
(Remains of rotted face on bark)

Orig. BT, 50" D. fir stump S.34½°W., 22.0 ft. (visible axe cuts on
bark face)

18" hemlock, uprooted, S.15°W., 3.8 ft. (visible face)

8" hemlock remains S.79°E., 10.4 ft. (visible scribe face)

I tagged: 24" D. fir, N.71°E., (Rec. N.75°E.) 20.2 ft., healed face.

22" D. fir, S.68°E., (Rec. S.70°E.) 18.6 ft. healed face.

14" Spruce snag, S.50°W., 17.3 ft. visible face.

15" D. fir now uprooted, N.35°W., 10.0 ft. (Rec. N.19°W.12.6')

12" alder, East 6.0 ft., tagged only.

190

North 1/4 Corner, Section 5 only, T23-12.

Corner Report Only

Found - 3/4" Iron rod with 2" alum. cap at orig. corner position as
perpetuated by R.E. Stuntzner in July 1982 (Coos Co. Records
M 1B27)

Orig. 30" D. fir, remains only, N.43°W., 15.2 ft.

Orig. 24" Cedar windfall, S.76°E., 8.6 ft.

1982 BT, 22" D. fir S79°E., 38.3 ft. visible scribe

1982 BT, 20" D.fir, S.14°W., 41.8 ft. visible scribe.

191

Meander Corner, East arm of Eel Lake, between Sec. 32 and Sec. 5 of T23-12

Found - Orig. meander corner as noted by S.B. Cathcart, Nov. 1890 and
established by Wm. Thiel in Jan. 1889.

Orig. BT, 36" cedar now stump, uprooted into lake, S.64°W.,
21.6 ft. (orig. position S.64°W., 10 lks. fits existin bank
perfect.)

Orig. BT, 24" spruce, rotted remains, but identifiable, N.52°W.,
7.9 ft.

Set - 3/4" iron rod with 2" alum. cap at corner position, cap mkd.
T.22S R12W S32, S5 MC T23S 1986.

New BTs - 21" D. fir, N.58°E., 24.2 ft. scribed T22S R12W S32 W.C. BT.

32" Spruce, S.25°E., 34.4 ft. scribed T23S R12W S5 W.C. BT.

192

Meander Corner, East arm of Eel Lake, between Secs. 29 and 32.

Found - Orig. meander corner as established by W. Thiel dated 8/31/1889
Original corner tree, 18" D. fir, now 29", uprooted into Lake.

Corner tree has healed faces on north and southsides and
visible axed, opened face and found no marks.

Orig. BT, 36" D. fir, now 48" stump, S.27½°W., 8,6 ft. tagged
visible axed bark, no scribes found.

Orig. BT, 20" D. fir now rotted remains, N.30°W., 7.3 ft.
(Rec. N.40½°W., 11 lks.)

Set - 3/4" iron rod with 2" alum. cap in orig. position of uprooted
corner tree, cap mkd. T22S R12W MC S29 S32 1986 LS 2244.

New BT - 29" D. fir N.39°W., 39.6 ft. scribed T22S R12W S29 MC BT

Andrew Blachly
For: Cole & Hongell
Logging and Inter-
national Paper
Oct. 1986
M 102 - 71

*Fd 9/93
M 117-64*

*BOOK BY
John Minor
5/94 Fd
Margaret Coffey
4/20-10
Fd 7/90
M 112-9*

Ronald E. Stuntzner, L.S. No. 1342
Dec. 10, 1998 / 1986
M 103 - 31

*Fd 7/90
M 112-9*

*Fd & Used
7/90 M 112-9*

*Fd & Used 7/90
M 112-9*