

Douglas County Surveyor's Record of
Government Corners Renewed

T. 23 S. T. S. R. 4 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

117

$\frac{1}{4}$ Corner to Sec. 7, T23-4W. & Sec. 12, T23-5W.
Found - Haines' "T" Iron as recorded in Ren. #91.
Also, possible Orig. BT. to N. E.
New BT's: 10" Cedar S. 7° E. 92.5 ft. Mkd: $\frac{1}{4}$ S7 CS BT.
5" W. Fir N. 7° W. 90.4 ft. mdk: $\frac{1}{4}$ S12 CS BT.
Note - This corner lies on rolling east slope approx. 200.0 ft.
East of top of hill.

Vernon "Ray" Tracy
Mike Stone & J. Layne
October 1965
C. S. File No. 54/16

118

$\frac{1}{4}$ Corner to Sections 28 and 29.
Found - Brass Cap & BT. as recorded Ren. #24.
18", now 19" D. Fir S. 35° E. 6.9 ft. in good shape
with healed face.
Stump of S. W. BT. as recorded in Ren. #3.
New BT: 10" D. Fir N. 35° W: 30.8 ft. mkd: $\frac{1}{4}$ S29 CS BT.
Note - This corner lies about 70 ft. North of a spur ridge
on a steep, North slope in a N. - S. Fence and about
200 ft. South of a creek flowing East.

Fd. B. Cap
2/86
R.L. DOLAN
M/100-32
10/12/88
B. SHANER
C.S. 63/85

119

The standard corner of Tps. 22 and 23 S., Rs. 3 and 4 W.,
perpetuated with an aluminum pipe, $\frac{1}{2}$ in. diam., firmly set,
12 ins. above ground, at record bear. & dist. from the only
remaining original BT:

A fir, 59" diam., bears N. 65° E., 39 lks. dist. with
scribe mark S, and other illegible scribe marks visible
on partially open blaze.

At the corner point, Set iron post, 28" long, 2 $\frac{1}{2}$ ins. diam.,
24" in the ground, with brass cap mkd:

| |
|-------------|
| T 22 S |
| R 4 W R 3 W |
| S C |
| S 36 S 31 |
| S 1 S 6 |
| T 23 S |
| 1959 |

from which new bearing trees:

Madrone, 7" diam., bears N. 52 $\frac{1}{2}$ ° E., 72 lks. dist., mkd:
T22S R3W S31 SC BT.

Chinq., 6" diam., bears S. 29 $\frac{3}{4}$ ° E. 38 lks. dist., mkd:
T23S R3W S6 SC BT.

Madrone, 6", bears S. 36° W., 60 lks. dist., mkd:
T23S R4W S 1 SC BT.

Madrone, 6", bears N. 82 $\frac{1}{2}$ ° W. 21 lks. dist., mkd:
T22S R4W S36 SC BT.

Deposit local corner marker alongside the iron post.

U. S. Bureau of Land Management
Dependent Resurvey N. Bdry T23-3W.
Dated June 10, 1959
See notes C.S. File No. 54/16

120

$\frac{1}{4}$ Corner to Section 1, T23-4W. & Sec. 36, T22-4W.
Found - 1" Iron Pipe & 1" Alum. Pipe as recorded Ren. #43.
Stumps of Bearing Trees, as recorded, not scribed, "W" Nails only.
New BT's: 10" Hemlock N. 61° W. 68.3 ft. Mkd: $\frac{1}{4}$ S36 DCSBT.
7" Hemlock S. 7° E. 58.7 ft. Mkd: $\frac{1}{4}$ S 1 DCS BT.
Note - This corner is on Lane - Douglas County Line.

Vernon "Ray"
Tracy &
Crew
Nov. 1965
C.S. File
No. 54/16

Nov. 3, 1965

121

$\frac{1}{4}$ Corner to Sections 2 and 11.
Found - Haines' "T" Iron & BT's., as recorded in Ren. #57.
10" D. Fir, now dead, S. 45° W. 13.4 ft., scribe visible.
18" D. Fir, alive N. 81° W. 16.2 ft., scribe visible.
New BT: 14" D. Fir S. 21° E. 26.2 ft. Mkd: $\frac{1}{4}$ S11 CS BT.
Note - Corner lies 30 ft. South of small, dry creek, course West.

Nov. 5, 1965