

Douglas County Surveyor's Record of  
Government Corners Renewed

23

T. S.

5

R. W. W. M.

Section corner to secs. 11, 12, 13, and 14.

8

Found:

Stump of O. B. T., 16 inch Fir, S.49°W., 124 lks. (Face rotted - no scribe visible.)

Stump hole of O. B. T., 16 inch Fir, N.88°E., 56 lks.

Set 1/2 inch iron rod in md. of rock 3 feet by 2 feet high.

Blazed and scribed 4 B. T.s:

16 inch Fir, N.19°W., 46.9 feet.

6 inch Madrone, N.47°15'E., 47.0 feet.

16 inch Fir, S.66°30'E., 28.6 feet.

14 inch Madrone, S.36°W., 33.0 feet.

RE-RENEWED, SEE CORNER NO. #132

1/4 sec. corner to secs. 13 and 14.

9

Found two O. B. T.s:

18 inch W. O. (Now 28 inches), N.34°W., 62 lks.

16 inch W. O. (Now 26 inches), N.57°E., 71 lks.

Set 3/8 inch iron rod at corner point.

10/69 F.O.D.K. C.S. 04/16

Rescribe O. B. T. 24 inch W. O., N.34°W., 42.9 feet.

Blaze and scribe 10 inch Fir, N.33°45'E., 44.2 feet.

Section corner to secs. 13, 14, 23, and 24.

10

Found:

O. B. T., 14 inch Fir (Now 66 inches) S.51°W., 65 lks.

Down B. T., 28 inch Fir (Now 60 inches) N.81°W., 44 lks.

Set 2 inch galvanized iron pipe at corner point.

Blazed and scribed 4 B.T.s:

24 inch Fir, N.4°W., 65.8 feet.

18 inch Fir, N.14°45'E., 67.2 feet.

15 inch W. O., S.72°30'E., 21.1 feet.

20 inch B. O., S.32°30'W., 48.5 feet.

RE-RENEWED, SEE CORNER NO. 88

1/4 sec. corner to secs. 13 and 24.

11

Set 1/2 inch iron rod at corner point. (By proportional measurement)

Blazed and scribed 2 B. T.s:

16 inch Fir, S.11°30'W., 34.7 feet.

18 inch Fir, N.2°30'E., 58.0 feet.

Section corner to secs. 13 and 24, T23S, R5W., and secs. 18 & 19, T23S, R4W.

12

Found O. B. T. stump, 12 inch W. Fir, N.20°W.

Set 1 1/2 inch galvanized iron pipe.

Blaze and scribe 4 B. T.s and 4 inch fir stake.

40 inch Fir, N.60°30'W., 46.2 feet.

4 inch Cascara, N.30°30'E., 13.1 feet.

4 inch Cascara, S.8°E., 1.8 feet.

24 inch W. Fir, S.75°30'W., 20.4 feet.

RE-RENEWED, SEE CORNER NO. 70

1/4 sec. corner to secs. 12 and 13.

13

Set 1/2 inch iron rod in md. of rock 2 feet by 1 foot high.

Blazed and scribed 2 B. T. s and 3 inch by 6 inch Cedar stake.

22 inch Fir, N.15°W., 72.2 feet.

28 inch Fir, S.13°30'W., 245.9 feet.

(Corner set by proportional measurement)

OK 9/93 M119-5

Section corner to secs. 12 & 13, T23S, R5W., and secs. 7 & 18, T23S, R4W.

14

Found 4 O. B. T.s at corner in good condition.

Set 1/2 inch iron rod at corner point.

RE-RENEWED, SEE CORNER NO. 30

Southeast corner of the Robert Smith D. L. C. No. 47.

15

Found original stone for corner, 10" x 10" x 15", marked with "X" & "47".

Blazed and scribed new B. T.s:

18 inch Pine, N.7°W., 21.4 feet.

8 inch Fir, South, 16.2 feet.

OK by DON BENTE #117 MAR 1983

RE-RENEWED, SEE CORNER NO. #117

M 93-76A SEC

Gere E. Johnson, Registered Professional Engineer.  
October, 1954  
Survey for E. A. Hostetler.  
See file No. 41/318.

H. E. Richardson  
Milo Godfrey  
Sept. 25, 1950.  
C. S. File 44/63.