

Douglas County Surveyor's Record of
Government Corners Renewed

T 23

T. S.

R 5

R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

C ONT. - - - -

Doug. Co. Surveyors
Office
R.W. Smith
S.J. Flause
Sept. 7, 1984
C.S. 62/21

(Sec. cor. 20, 21, 29, 28)

119

13" now a 17" D. fir with a well healed single blaze bears
S.19°E., 7.9 ft. Ren. #83
14" now a 20" D. fir blow down with a well healed single blaze
bears S.49°W., 11.1 ft. (Rec. 21.1 ft.) Ren. #83
10" now a 13" D. fir with a well healed single blaze bears
N.62°W., 23.4 ft. (Rec. 23.8 ft.) Ren. #83
A DCSO disk stamped "T23S R5W NW Cor DLC 47 1984" bears South
268.1 ft. (Rec. 271.9 ft.) bearing taken with a hand compass
(Per orig. DLC notes of the NW cor DLC 47)
New BTs - 9" D. fir double blazed and scribed "T23S R5W S21 CSBT" bears
N.65°E., 27.7 ft.
9" D. fir double blazed and scribed "T23S R5W S29 CS BT"
bears S.72°W., 28.6 ft.
Corner lies on a gentle NE slope.

9/7/84

North 1/4 Corner for Section 1 only.

120

Found - A 2 3/8" Dia. County brass cap on a 1 1/4" O.D. I.P. is firmly
set and protrudes 12" from the ground. Ren. No. 59
Ren. No. 2 describes an iron bar 3/8" x 1 1/2" x 48" as the corner
monument. An iron bar measuring 1/2" x 1 5/8" firmly set and
protruding 11" above ground bears S.05 3/4°E., 1.8 ft. from the
brass cap monument.

(Both objects above are set in a north south fenceline.)

Orig. BT, a 28" Y. Oak, now a 39" DBH Black Oak previously
opened, now rotted, no clear evidence of blaze or scribing bears
S.37 1/2°W., 36.3 ft. (Rec. S.36°W., 36.3 ft.)

(Other Orig. BT removed by logging cat work)

A Black Oak, 10" dia. now a 12" DBH W. Oak bears S.35°W., 6.9 ft.
(Rec. B. Oak, S.39°W., 6.9 ft.) Tree has a fully healed double
blaze. Ren. No. 2

(Other BT per Ren. No. 2 not found due to logging cat work.)

A 6" R. fir now a 12" dia. 1 foot tall fir stump with partial
lower blaze remaining, no scribing found, bears S.15°W., 14.4 ft.
(as per rec.). Ren. No. 59

A 5" R. fir now a 25" dia. fir stump 6" tall with partial lower
blaze remaining, no scribing visible, bears S.60°E., 36.7 ft.
(as per record.) Ren. No. 59

No new monument set. Brass Cap monument agrees best with remaining
original evidence.)

New BTs - An 8" DBH D. fir scribed 1/4 S1 CSBT on a double blaze bears
S.83 3/4°E., 57.6 ft. distant.

A 7" DBH D. fir scribed 1/4 S1 CS BT on a double blaze bears
S.12°W., 40.6 ft. distant

Corner is located in a north-south fenceline on a north-west slope approx.
75 ft. east of a cat road.)

121

South 1/4 Corner for Section 36 only of T22-5

Found - 1960 Doug. Co. brass cap/I.P. bent and leaning 0.8 ft. northw
of plumb position, protrudes 7" above ground. Ren. No.67 of
T.22-5

Orig. BT, 24" now 40" B. Oak shows a single well healed face
bears N.60°W., 4.0 ft. (Rec. N.60°W., 2.6 ft. to face.)

17" now 22" D. fir with a fully healed double blaze bears
N.10°E., 17.5 ft. Ren. No. 67 of T.22-5

13" now 21" D. fir with a fully healed double blaze bears
N.31°W., 26.1 ft. (Rec. N.33°W., 26.1 ft. is to center of
trunk at level distance.) Ren. No. 67 of T.22-5

Set - Iron pipe straightened and returned to plumb position. I.P./BC
protrudes 3" above ground.

New BT - 8" dia. D. fir double blazed scribed "1/4 S36 CS BT bears
N.82 1/2°E., 24.0 ft.

Douglas County Surveyors Office
Randall Smith - Stephen Flause
Feb. 24, 1986
C.S. 62/31