

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 23 S. T. S. R. 8 W. R. W. W. M.

MOORE-CHAPMAN CO., EUGENE, ORE. 21851

FD OK 12/95 BY C. MULKINS M 123-32

118

Sec. Corner common to Secs. 4, 5, 8, & 9.

(Ref. notes C.S. 59/30 now attached to this Renewal.)

Found - 5/8" I.R. w/alum cap stamped "BO 2" along with PK nail in a 24" Fir for a backsight per Reference notes.

5/8" I.R. w/alum cap stamped "BO 1" per Ref. notes. PK nail used for backsight in 20" Fir, is gone.

B.C. per Ren.#51 was removed per Ref. notes.

The above mentioned Ref. monuments were used to re-establish Cor. position from which:

BT's - 42" Fir w/partially opened scar, bears N.67°W., 25.1-ft. Ref. notes

14" Fir w/good scar, bears S.18°E., 15.4-ft. as per Ref. notes.

10" Fir w/good scar, bears N.64°E., 5.7-ft., as per Ref. notes.

Note - All other BT's mentioned in Ref. notes, were taken out by Rd. Const.

Set - Using Ref. Mon."B02", along w/its backsight, I establish a position at Rec.dist.(per Ref.notes of 229.48-ft.). Since "BO 1" no longer has a backsight,I can't check line from it,but do confirm Rec.dist.(per Ref. notes of 62.4-ft.).

At this point, I set a 1" x 30" I.P. w/B.C. attached, stamped:

Douglas Co Surveyor T23S S5 S4 S8 S9 R8W 1981

Since I hit bedrock down about 12", I build a large mound of dirt & stones approx. 18" high around the B.C., which is on East shoulder of new road.

New BT - 10" Fir scribed "T23S R8W S8 CS BT" in dbl.blaze bears S.34°W.,62.0-ft.

11/30/81

119

1/4 corner to Secs. 25, & 36.

Found - 1964 BLM B.C.

BTs. - 14" hemlock bears S.15°E.,25.7-ft.(scar visible)-1964 BT.

New BT- 8" cedar bears N.73-1/2°W.,24.0-ft. (scribed).

3/30/82

120

South 1/4 corner to Sec. 36 only.

No evidence of original corner.

Set - 1-1/2" x 36" I.P. with B.C. at proportionate distance.

New BTs- 9" fir bears N.49°W.,12.8-ft.(scribed).

12" fir bears N.12°E.,10.8-ft.(scribed).

121

Section corner for Sections 33 and 34 only. (south boundary)

Found - Area completely covered by fill from new road construction.

Orig. 40" fir, now 45" (alive) with well healed blaze.

Orig. 60" fir,now 45" stump with no visible bark scribing remaining.

16" fir per Ren. #52, now 15" stump with good scar.

Set - Using record distances from the two remaining orig. BTs and near record dist. from the one remaining Ren. #52 BT, I set a 1" x 30"

Iron pipe with brass cap attached mkd. "Douglas Co Surveyor

T23S S33 S34 R8W 1982" for the sec. cor. to Sec. 33 & 34 only

Corner falls on a steep rocky road fill approx. 47 ft. (slope

distance) south of a new road. Bearing and dists. to found BTs are:

60" now 45" fir (stump) bears N.85°E., 19.1 ft. (rec. N.83°E.,)

40" now 45" fir (alive) bears S.63°W., 40.9 ft. (Rec. S.67°W.)

16" now 15" fir (stump) bears N.38°E., 22.9 ft. (Rec. N.34 1/2°E.,

22.7 ft.)

New BT - 36" fir scribed "T24S R8W S3 CS BT" in single blaze bears S.86°W.,

46.8 ft.

Douglas County Surveyor Office BT tags on all trees.

10/13/82

122

Closing Corner for Sections 3 and 4 only of T.24-8 (on township line)

Found - A 20" D. fir now 26" which bears S.78°E., 36.2 ft. (OBT)

A 36" D. fir now a stump which bears N.57°E., 36.6 ft.

A 36" D. fir now a stump which bears N.4°W., 30.5 ft. (OBT)

A 2" pipe and brass cap in proper position. Ren. #99

A new road was to be constructed near this corner and it appeared that the corner position could be obliterated, so I removed the pipe and brass cap from its original position and replaced with a 5/8" x 30" iron rod set one foot below the surface of the natural ground line. When construction was completed, I reset the pipe & brass cap in its original position and also left the iron rod in place.

New BTs- 37" D. fir bears S.23 1/2°E., 26.2 ft. marked T24S R8W S3 BT.

12" maple bears S.23°W., 38.6 ft. marked T24S R8W S4 BT.

Note: The newly constructed road bears North approx. 50 ft. and is approx.

30 ft. above the corner.

10/1/82

Gregory Quibell  
Deputy Douglas  
Cou. Surveyor  
Teresa Buley, mt.  
Nov.30,1981  
C.S. 61/29

Les Roberts L.S.#1039  
For: Int. Paper Co.  
March 30, 1982  
M 91 - 74

Gregory Quibell, Deputy  
Douglas Co Surveyors Office  
Karen Ree - John Powell  
October 13, 1982  
C.S. 62/1

Burt Holt, L.S. #418  
October 1, 1982  
C.S. 58/229