

Douglas County Surveyor's Record of
Government Corners Renewed

T 23 S T. S. R. 9 W. R. W. W. M.

104

FOKE-CHAPMAN CO., EUGENE, ORE. 97401

Mon. Set- Position of fence post and 5/8" I.R. is referenced and a 2 3/8" Dia. Brass cap on 1 3/8" O.D. by 32" long iron pipe is set at referenced position. BC/IP protrudes 10" above ground.
Fence post if reset along north edge of BC/IP protrudes 36" above ground. (5' long)
5/8" I.R. is set along south edge of BC I.P., protrudes 10" above ground (3' long).
Corner is surrounded by 1 1/2' dia. mound of sand stone.

New Accessories -

4" dia. D.Fir, double blazed and scribe "X BT", bears S.67°W., 15.9'.
11" dia. Hemlock, double blazed and scribed "1/4 S23 CS BT", bears N.89°E., 54.6'.

ren.#75

S.23, S.24, S.25, S.26 Sec. Cor.

Mon. Fd.- 2" Brass cap on a 1" O.D. Iron pipe 6" below ground.
No corner stone fd.

Accessories Fd. -

30" now 50" dia. 4' high D.Fir stump, with bark scribing visible "T23S R9W S23 CS BT", bears N.24°W., 8' to center.
20" now 24" dia. 1' high rotted D.Fir stump, no scribing visible, bears N.61°E., 13.5' to center.
(BT's noted in 1973 DCSO Ren #67 as being from an unrecorded renewal dated 8-13-69)
16" D.Fir now 25" dia. Hemlock with a fully healed double blaze, bears N.30°E., 18.9'.
30" now 39" dia. D.Fir, with a fully healed double blaze, bears S.74°W., 21.3'.
10" Fir now 13" dia. D.Fir down and fallen on blaze, root crown agrees well with rec., S.47°E., 16.3'.

New Accessories -

11" dia. Hemlock, double blazed and scribed "T23S R9W S25 CS BT", bears S.67 1/2°E., 18'.

ren. #67

1/4 cor. between sec. 23 & 24

Mon. Fd.- Rotted Hub and tack with flagging (1972 Hales?)

Bt's Fd.- 72" dia. 3' high rotted and burnt D.Fir stump, no blazing or scribing found, bears N.60°E., 33' (agrees w/ 1967 BLM?, orig rec. S.60°E., 33').

50" dia. D.Fir tipped out of ground and slid down hill, shows evidence of being previously opened possible by DCSO in ren # 74 position undeterminable as orig. rec of N.25°W., 37.6' falls in large slide.

20" dia. Hemlock with tag healed into bark is found tipped out of ground, root hole bears N.77°W., 18.4' (agrees with 1984 I.P.) (source unknown weyerhauser?)

25" dia. Hemlock with a partially healed single blaze no scribing visible, appears not to have been scribed, bears N.8 1/4°W., 9' (agrees with I.P. rec.) 1984 I.P. tag.

13" dia. Hemlock with a partially healed single blaze no scribing visible appears not to have been scribed, bears S.69 3/4°E., 35.5' (agrees with I.P. rec) 1984 I.P. tag.

Mon. SET- 2 3/8" dia. brass cap on a 1 3/8" O.D. by 32" long iron pipe is set at position of found H.T, BC/IP protrudes 7" above ground.

New Bt's- 25" I.P. Hemlock is single blazed high and scribed "1/4 S23 CS BT", bears N.8 1/4°W., 9'.

13" I.P. Hemlock is single blazed high and scribed "1/4 S24 CS BT", bears S.69 3/4° 35.5'.

Chiseled 8" "+" in sand stone rock out crop, bears S.9°W., 7.4'.

15" dia. Cedar double blaze and scribed "1/4 S24 CS BT", bears N.57 1/2°E., 23.7'.

NOTE: Perpetuated a point from unrecorded renewal info. obtained from Dave Friedlein.

ren. #74

Douglas County Surveyors Office
Randall Smith & Stephen Flause
10/3/95 C.S. 64/64

DOUGLAS COUNTY SURVEYORS OFFICE
RANDALL SMITH & STEPHEN FLAUSE
May 29, 1996 - C.S. 64/69-20

105

106