

Douglas County Surveyor's Record of
Government Corners Renewed

T 24

T. S.

R 1

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21891

140

Section corner for Secs. 21, 22, 27 and 28.

Found - 1966 County brass cap on iron pipe firmly set protruding about 14" above ground, properly marked. Ren. #49

Original post not found.

An 18" pine, now a 30" stump with well healed blaze bears N.20°E., 35.1 ft. (Rec. N.18°E., 35.6 ft.)

A 6" fir, now 11", (badly bowed with double top) has well healed double blaze with an "x" above upper blaze, bears S.42°E., (Rec. S.43°E.) 12.5 ft. to center of trunk at X blaze. Root crown bears S.20°E., 12.8 ft.

A 16" pine now a 30" diam. stump with well healed blaze bears S.25°W., 32.2 ft. (Rec. S.23°W., 35.0 ft.)

A pine 24", now 36" diam. with well healed blaze bears N.53°W., 54.9 ft. (Rec. 54.1 ft.)

New BTs - A hemlock, 8" dia. double blazed and scribed "T24S R1W S22 CS BT" bears N.12 1/2°E., 48.7 ft.

A hemlock, 10" dia. double blazed and scribed "T24S R1W S28 CS BT" bears S.20°W., 4.1 ft.

Note: Corner lies on a NNE slope approx. 55 ft. east of a spur ridge running northerly. Cutting lines run N-S-E and W, clear cut at NE and SW.

141

1/4 Corner for Secs. 28 and 33.

Found - 1962 County brass cap, properly marked, on iron pipe. Ren. #23

Original stone with portion of mark "1/4" remaining on easterly face. Stone is on southerly edge of brass cap monument.

Orig. 12" fir, now an 18" dia. 5 foot high stump, bears N.38°E., 11.9 ft. (Rec. per orig., N.41 1/2°E., 11.2 ft.) (Rec. per Ren. #23, N.41 1/2°W.) Stump has two healed blazes.

Orig. 12" fir now 22" dia. with well healed blaze bears S.7°W., 16.3 ft. (Orig. Rec. S.8°W., 17.8 ft.) (Rec. per Ren. #23 is 16.8 ft.)

New Accessory:

A 1/2" x 8" spike in top of an 18" dia. fir stump, bears N.52°W., 9.7 ft. Spike set through a "Douglas County Surveyors Office" bearing tree tag.

18" D. fir, double blazed and scribed "1/4 S33 CS BT" bears S.60°E., 16.0 ft.

Note: This corner lies on an east slope, in an E-W cutting line. Clear cut to the north. It appears the corner is approx. 50 ft above dry creek bed to the east and 200 ft. below ridge call to the west.

142

1/4 Corner for Secs. 21 and 28.

Found - 1966 County brass cap, properly marked on iron pipe firmly set. From original survey, possible corner stone noted per Ren. #51 out of ground.

Orig. fir, 42" now 52", with well healed blaze bears N.13°E., 21.9 ft. (Rec. 22.4 ft.)

Orig. 36" fir, now a stump with partially opened blaze and visible scribing bears S.43°W., 16.5 ft. (Rec. S.46°W., 17.2 ft.)

A 7" D. fir with scribing visible in a partially healed blaze bears N.18°E., 7.7 ft. to blaze (per rec.) and N.13 1/2°E., 8.5 ft. to root crown. Ren. #51

6" fir, S.70°E. is down.

New Accessory:

Set an 8" x 1/2" spike in a 34" fir stump, bears S.37°E., 35.0 ft spike set through a "Douglas County Surveyors Office" bearing tree tag in top of stump.

Note: Corner lies on steep southwest slope, in E-W cutting line. Clear cut to south.

9/83

Larry E. Monrean, Deputy, Douglas County Surveyors Office
Witness: John M. Powell ; Janet R. Lundeen
Sept. 27-28, 1983
C.S. 62/9