

Douglas County Surveyor's Record of  
Government Corners Renewed

T 24 T. S. R 2 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21001

96

Section Corner for Secs. 21, 22, 27 and 28.

- Found - A 3" squared wooden post, not original.  
 A 24" now 41" Hemlock stump bears N.39°E., (Rec. N.84°E.)  
 40.2 ft. with a well healed blaze.  
 A 24" now 30" Cedar bears S.20°E., 14.6 ft. (Rec. 16.5 ft.) with  
 scribing "2W 2" in a partly healed single blaze.  
 A 5" now 16" Cedar bears S.68 1/2°W., (Rec. S.66°30'W.) 20.5 ft.  
 with an almost healed single blaze.  
 A 60" now 63" Fir stump bears N.35°W., 21.8 ft. with a well healed  
 single blaze.

Set - A 1" x 36" Iron pipe with a brass cap set 6" above ground  
 marked: "Douglas County Surveyor" 1978

T 24 S R 2 W  
S 21 | S 22  
 S 28 | S 27

R. B. Kimberling  
 P.L. Earle  
 F.C. Silagy  
 Doug. Co. Survey-  
 ors Office  
 March 14, 1978  
 C.S. 59/46

- New BT's- A 11" Hemlock bears N.84 1/2°E., 40.9 ft. double blazed and  
 marked "T24S R2W S22 CS BT".  
 A 6" Hemlock bears N.14°W., 98.9 ft. double blazed and marked  
 "T24S R2W S21 CS BT".

3/14/78

97

1/4 Corner for Secs. 20 and 29.

- Found - A 1/2" I.P. the top 3" above ground in a 24" mound of stone.  
 (Ref. to Weherhauser Ren. 1976). I use as a bearing object.  
 A 10" now 16" Cedar bears N.7 1/2°W., (Rec. N.10°W.) 25.1 ft.  
 with a well healed blaze and "B" carved on west face.  
 A 10" now 13" Cedar bears S.31°W., (Rec. S.40°W) 5.9 ft. with  
 very old scribing "1/4 S" in dead section of tree (east side  
 of tree is dead.)

Set - A 1" x 36" I.P. with a brass cap set at ground level in a dug  
 pit 24" dia. 24" deep filled with stone. I mark brass cap:  
 "Douglas County Surveyor" 1978

T 24 S R 2 W  
S 20  
 S 29

R. B. Kimberling  
 P.L. Earle  
 Douglas Co. Surveyor  
 Office  
 March 15, 1978  
 C.S. 59/46

New Accessory: A 1/2" Found iron pipe bears N.53°W., 0.6 ft.

Note: Corner is 200 ft. S.W. of North edge of virgin timber and small  
 creek which bears N.20°W., slope is 72% N.40°E.

3/15/78

98

Section Corner for Secs. 32 and 33; and 5 & 4 of T25-2.

Found - 1951 GLO Survey brass cap & 1 1/2" I.P. set by Calder & Watson  
 (Weyerhaeuser). Both monuments are out of position, displaced  
 by logging activity.

- A 48" D.Fir, now a 54" stump (OBT, 1883) with rescribing "24S  
 R2W S33 B" visible on unhealed blaze bears N.65°E., 2.8 ft.  
 (Rec. N.65°E., 16.5 ft.)  
 An orig. 12" now 22" Yew (OBT, 1883) alive with rescribing "T25S R2W  
 S5 BT" visible on unhealed blaze. (no orig. scribing found.)  
 bears S.20°W., 31.7 ft. (Rec. S.15°E., 33.0 ft.)  
 An orig. 24" D.Fir now a 37" snag (OBT 1883) no scribing found  
 bears S.42°W., 49.5 ft. (Rec. S.40°W., 49.5 ft.)

An orig. 14" now 20" Yew (OBT 1883) alive with faint scribing "B" visible on  
 orig. blaze and rescribing "T24S R2W S32 BT" visible on un-  
 healed blaze bears N.26 1/2°W., 16.5 ft. (Rec. N.40°W., 16.5 ft)

Set - We do not find the SE bearing tree marked in 1963, a 40" Fir.  
 At a location which agrees with the previously described BT,  
 WE RESET the 1951 GLO monument, a 2" x 36" I.P. 30" in the  
 ground, with brass cap attached marked as described in the  
 official record. WE ADD the markings "CS 1978" to the brass  
 cap and place the 1 1/2" I.P. alongside the brass cap, ex-  
 tending 18" above ground.

Gary Langlitz  
 S. Flaue  
 F. Silagy  
 Doug. Co. Surveyors Office  
 March 1978  
 C.S. 59/46

We confirm the bearings and distances to the accessories referenced by  
 Weyerhaeuser Co. as shown on Page 3 of the notes filed in C.S. 59/46 with  
 the following exception:

- A 20" Yew, "W" Nail bears S.20°W., 30.1 ft. (Weyerhaeuser record  
 S.20°W., 30.5 ft.)

4/3/78

COPY  
 ATTACHED TO  
 FIELD NOTES  
 C.S. 59/46

1-79