

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 24 S. T. S. R. 3 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

44

1/4 Corner to Sections 24 and 25.  
Found - 24" Fir, now 28", face not cut out but "face line visible on top of stump.  
36" Fir S.60°E. 16.5 ft., now Fir Stub, 10' high, face not grown, scribing visible. (This information placed on the Orig. BT's. by the 1944 Weyerhaeuser Co. survey didn't agree with the Orig. 1883 survey. I accepted the Orig. BT's. disregarded the 1944 data & set the corner on the basis of the Orig. "call" distances.)  
Set - 1" x 30" Aluminum Pipe, from which:  
Orig. 28" Fir Stump N. 32° E. 21.8 ft. "W" Nail & Plate.  
Orig. 36" Fir Stub S. 64° E. 16.5 ft. "W" Nail & Plate.  
Logged 1963 Dec. 2, 1965

Weyerhaeuser Company  
Donald H. Jordan, Surveyor  
March 1966, filed  
C. S. File No. 53/111

45

Sec. Cor. to Secs. 13 & 24, T24-3W. & Secs. 18 & 19, T24-2W.  
Found - 30", now 44" Cedar S.29°W. 24.8 ft., face grown over, no scribing.  
10", now 13" Hemlock N.45°W. 6.6 ft., face open, rotten, scrbing. vis.  
20", now 42" Cedar N.82°E. 15.2 ft., face grown over, no scribing.  
20", now 32" Hemlock S.70°E. 23.1 ft. tree windthrown, face closed.  
Set - 1" x 30" Alum. Pipe, from which:  
Orig. 42" Cedar N.83°E. 13.6 ft., "W" Nail & Plate.  
Orig. 44" Cedar S.29°W. 24.0 ft., "W" Nail & Plate.  
36" Hemlock N. 88° W. 25.3 ft. "W" Nail & Plate.  
68" Fir N. 28° E. 35.9 ft. "W" Nail & Plate.  
Oct. 8, 1965

46

Sec. Cor. to Secs. 12 & 13, T24-3W. & Sec. 7 & 18, T24-2W.  
Found - 38" Fir N. 40° W. 24.4 ft., slide, no evidence.  
14" Maple N. 15° E. 27.2 ft. Stub 5' high, "W" nail, but no scribing.  
52" Fir S.77°E. 47.5 ft., windthrow root wad & dist., no reference.  
34" Fir S. 59° W. 33.0 ft., slide, no evidence.  
Set - 1 1/2" x 42" Iron Pipe, from which:  
14" Maple Stub N. 15° E. 27.2 ft. (Orig. BT) "W" Nail & Plate.  
36" Fir Stump N. 56° W. 37.2 ft. "W" Nail & Plate  
Dec. 2, 1965

47

Township Corner: 

R	3	S 36	S 31	2	T 24 S
W	S 1	S 6	W	T 25 S.	

  
 Found - 1943 GLO Brass Cap at Cor. Mkd:  
Orig. 48", now 50" Fir Stump N. 50 1/2° W. 42.2 ft., shows fragmentary scribe on burned face. Rescribe T25S R3W S1 CS BT.  
All other BT's. gone or out of place, due to logging.  
New BT: 54" D. Fir Stump 8' High, N. 37° E. 26.4 ft. mkd. T24S R2WS31CSBT.  
No other trees available - Corner lies in greasewood thicket 20 ft. E. of Cat Road & 20' W. of bottom of small draw.  
Note - See Alson GLO notes, Vol. 32, Pg. 13284.

Vernon "Ray" Tracy  
Joe Brady & Jack Heritage  
July & August, 1966  
C. S. File No. 54/27

48

1/4 Corner to Sec. 36, T24-3W. & Sec. 1, T25-3W.  
Found - 1944 GLO Brass Cap mkd.  
42", now 38" Fir Stump N. 46° W. 9.2 ft., face burned, we rescribe 1/4 S36 CS BT".  
46", now 48" Fir Stump S. 81° W. 34.3 ft., burned, no scribe, we rescribe 1/4 S 1 CS BT".  
Set - 1/2" I. Pipe alongside Brass Cap 6 ft. above ground.  
Note - Corner lies approx. 125 ft. W. of Log. Rd. on slight S. W. slope in logged off area. Mt. Scott L.O. bears S. 40° W.

49

1/4 Corner to Sec. 35, T24-3W. & Sec. 2, T25-3W.  
Found - 1944 GLO Brass Cap mkd., with steel fence post alongside.  
S.W. BT., now stump & N.W. BT. down, scribe visible.  
New BT's: 12" Hemlock N. 51° W. 39.6 ft. mkd. 1/4 S35 CS BT.  
Rescribe: 44" D. Fir Stump S. 5° W. 34.3 ft. mkd. 1/4 S 2 CS BT.  
Note - Corner lies approx. 200 ft. E. of road, course N. & E., curving to East passing approx. 100 ft. North of corner.

9-11-67 - Coc. Fo. O.K. J.M.P.