

Douglas County Surveyor's Record of
Government Corners Renewed

T 24 S T. S. R. 7 W. R. W. W. M.

KORE-CHAPMAN CO., EUGENE, ORE. 2181

177

SOUTH $\frac{1}{4}$ CORNER SEC. 10

Mon. Set- $\frac{3}{4}$ " X 24" Alum. Rod/ $\frac{3}{4}$ " Alum. Cap (buried purple M.M. under 24" Alum. Rod)

New Bt's- 6" Fir, S.6°W., 18.2' (scribed/painted red)
12" Fir, N.36°E., 39.5' (scribed/painted red)
18" Fir, N.73°E., 21.1' (scribed/painted red)
26" Fir, S.78°E., 6.1' (scribed/painted red)

Les Roberts
I.P. Timberlands
April 20, 1996
M 123-73

178

NORTH $\frac{1}{4}$ CORNER SEC. 10

Mon. Set- $\frac{3}{4}$ " X 40" Alum. rod/ $\frac{3}{4}$ " Alum. cap (buried purple M.M. beside 40" Alum. rod)

New Bt's- 5" Maple, S.13°E., 19.1' (scribed/painted red)
12" Fir, S.68°E., 10.5' (scribed/painted red)
14" Fir, N.51°E., 34.2' (scribed/painted red)
18" Fir, North, 20' (scribed/painted red)

Bruce Shaner
For: Woodward &
Dickerson
June 1996
M 125-20
C.S. 65/2-12 A-C

179

Cor. Secs. 9, 10, 15, & 16

Found - Brass Cap set by County Surveyor in 1956 (Ren. # 23)

56" Cedar BT, now windfall, bears S.89°W., 24.0 ft.
24" White Fir BT, face grown over, bears North 33.8 ft.
26" White Fir BT, face grown over, bears N.40°E., 34.0 ft.

New Accessories -

8" D.Fir, scribed "T24S, R7W, S16 BT" bears S.63°W. 24.3 ft.
14" D.Fir, scribed "T24S, R7W, S15 BT" bears S.32°E. 30.3 ft
6 foot steel fence post, I set, bears South 1.0 ft.

Note - End of U.S.B.L.M. road No. 24-7-9.0, bears N.30°W., 200 feet from corner.

180

$\frac{1}{4}$ Cor. Secs. 15 & 16

Set - By proportionate measurement, a 3" Alum. cap on a $2\frac{1}{2}$ "x30" alum. pipe, from which a;

40" Red Cedar, scribed " $\frac{1}{4}$ S15 BT" bears S.26°E., 32.4 ft.
36" Red Cedar, scribed " $\frac{1}{4}$ S15 BT" bears N.62°E., 45.6 ft.
12" Red Cedar, scribed " $\frac{1}{4}$ S16 BT" bears S.17°W., 24.6 ft.
6' steel fence post, bears S.40°W., 1.0 ft.
6' steel fence post, bears S.10°E., 1.4 ft.

Note - 6 foot wide stream flowing East is North 35.0 feet from $\frac{1}{4}$ S. (Nice hike downhill to this corner)

181

$\frac{1}{4}$ Corner Sec. 6

Mon. Fd.- 1979 BCIP marked PLS 1039 *Ren 5/26*
BT's Fd.- 22" Fir, N.15°E., 37.3' healed
12" (not 20" as in record) Fir, S.65°E., 34.3' part healed
New Bt's- 16" Fir, N.60°E., 25' "C $\frac{1}{4}$ BT"
10" W.Fir, S.26°E., 3.8' "C $\frac{1}{4}$ BT"

Mark Smalley
For: Scott Timber Co.
Sept. 1996
M - 125-67

182

$\frac{1}{4}$ Cor between 6 & 7

Mon. Fd.- 1960 Count BCIP & Stone, scribed "1" stone is crumbling
S

Bt's Fd.- 23" Hemlock, N.17°W., 9' healed
20" Cedar, S.23 $\frac{1}{2}$ °W., 25.7' healed
New BT's- 12" Hemlock, S.46°E., 45.3' " $\frac{1}{4}$ S BT"
25" Hemlock, S.6°W., 46.9', " $\frac{1}{4}$ S BT"