

**Douglas County Surveyor's Record of
Government Corners Renewed**

T. 24 S. T.S. R. 7 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Mark Smalley
For: Scott Timber Co.
Sept. 1996
M 125-67

¼ Corner between 5 & 6 183
Mon. Fd.- 1960 County BCIP
corner is 1' east of N-S fence
Bt's Fd.- 18" Cedar, N.75°W., 24.42' rotten down, OBT
30" Cedar, N.40°W., 46.86' part healed
14" Fir, N.62°E., 3.3' broken stauB
14" Fir, N.6¼°E., 50.82' healed
New BT's- 7" Fir, S.10°E., 10' "¼ S BT"
10" Fir, S.67°W., 8.2' "¼ S BT"

Section corner 5, 6, 7, & 8 184
Mon. Fd.- 1960 County BCIP
BT's Fd.- 20" Fir, N.35°W., 19.8' Stump, OBT
18" Hemlock, N.37½°W., 30.3' healed
50" Fir, N.85°E., 16.5' rotten, OBT
26" Hemlock, N.43½°E., 27' healed
40" Fir, S.20°E., 38.94' down, OBT
17" Chinquapin, S.20°E., 19.8' down
36" Fir, S.2°W., 66' down, OBT
10" Fir, S.53½°W., 37.3' down
13" Hemlock, S.14°W., 15.84' stump
New Bt's- 8" Hemlock, N.44°E., 18.9' "S 5 BT"
12" Fir, S.16°W., 35.7' "S 7 BT"

1/4 Cor. Secs. 20 & 21 185
Found - DCSO 1960 brass cap & IP. (REN. #56)
15" Oak, N.43°E., 26.2', healed. (1960)
20" Oak, N.85°E., 54.8', healed. (1960)
24" Oak, S.63°E., 90.4', healed. (Orig. BT)
New BT- 10" Fir, N.61°W., 18.0', scribed "¼ S BT"

Corner for sections 20, 21, 28, & 29 186
Found - DCSO 1960 brass cap & IP. (REN. #64)
44" Fir, N.22°E., 17.2', down. (Orig.)
48" Fir, S.51°E., 30.2', healed. (1960)
24" Fir, S.60°W., 35.6', healed. (1960)
New BTs-8" Fir, N.81°W., 19.7', scribed "S 20 BT"
8" Fir, N.79°E., 41.2', scribed "S 21 BT"

1/4 Corner Secs. 21 & 28 187
Found - DCSO 1960 brass cap & IP. (REN. #59)
38" Oak, N.47°E., 43.6', rotted face. (Orig. BT)
13" Oak, S.14°E., 15.2', healed. (1960)
New BTs-11" Fir, N.55°W., 32.2', scribed "¼ S BT"
12" Maple, S.47°W., 45.1', scribed "¼ S BT"

Corner for sections 21, 22, 27, & 28 188
Found - DCSO 1957 BCIP & 18"x12"x6" stone. (REN. #27 & 102)
18" Fir, N. 56°W., 12.0', healed. (1957)
24" Fir, N.15°E., 62.7', stump. (Orig. BT)
10" Fir, N.85°E., 53.2', healed. (1966)
7" Fir, S.60°E., 34.9', healed. (1966)
22" Fir, S.33°W., 54.4', stump. 9 1957)
New BT- 8" Fir, N.76°W., 21.3', scribed "S 21 BT"

1/4 Cor. Secs. 28 & 29 189
Found - DCSO 1960 brass cap & IP. (RENS. #5, 66, 146)
28" Fir, N.17°W., 19.0', stump. (1926)
20" Fir, N.57½°W., 110.0', snag. (1960)
18" ? (Rec. D.Fir), N.24°E., 27.0' healed. (1982)
8" Maple, S.66°E., 10.0', healed. (NO RECORD)

Mark Smalley
For: Scott Timber Co.
Sept. 1996
M 124-27