

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 25 S. T. S. R. 5 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21891

Don E. Garrett  
For B. Taylor  
9/24/65  
M 22 - 70

S. E. Corner D. L. C. No. 37.  
See Former Ren. #41. - Corner destroyed.  
Set - 5/8" Iron Rod at Corner, from which:  
New BT: 13" Ash bears S.53°W. 151.7 ft. scribed DLC #37 BT.  
Sept. 27, 1965

88

Vernon "Ray"  
Tracy &  
Crew  
C. S. File  
No. 49/123

Initial Point, Plat "I", S. L. & W. (IN SW 1/4 NE 1/4 Sec. 14)  
Found - 2" I. Pipe, 4" deep at Intersection of Plat "I" Road &  
Valley View Road.  
Mark BT - 12" Ash N. 8° E. 82.0 ft. Mkd: "CS BT". This BT lies  
3.0 feet west of East R/W Fence of Plat "I" Road.  
Corner lies 16.0 ft. West of same R/W, listed above.  
Jan. 24, 1966

89

Vernon "Ray"  
Tracy &  
Crew  
C.S. File  
No. 49/124

S. E. 1/16 Corner Section 9.  
Found -BT's. as follows:  
1962 Cadastral I.P. & Brass Cap pushed over & buried, good condition.  
13" D.Fir, now Snag, S. 89° E. 39.6 ft., shows "SE 1/16 S9 BT" scribe  
on unhealed blaze.  
SW. BT. pushed over & out of position, scribes visible.  
Reset Brass Cap in proper place & mark New BT's:  
11" D.Fir N. 19° E. 49.2 ft. mkd. SE 1/16 S9 CS BT.  
11" D.Fir S. 5° W. 47.6 ft. mkd. SE 1/16 S9 CS BT.  
Note - This corner lies in logged off unit on E. side of rolling  
spur ridge, course S.  
Feb. 9, 1967

90

2/9/67

MICROFILM TO HERE 10/67

Section Corner to Sections 15 - 16 - 21 - 22.  
Found - Orig.40" W.Oak, alive, S.24 1/2°E. 116.8 ft., blaze badly decayed.  
10", now 16" D.Fir, alive, S.56°W. 63.2 ft., healed blaze & tag.  
16", now 20" D.Fir, alive, S.12°E. 115.3 ft., healed blaze & tag.  
8", now 15" D.Fir, alive, N.22°E. 163.0 ft., healed blaze & tag.  
No trace of Iron Pipe & Brass Cap as recorded in Ren. #35.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T 25 S R 5 W  
(Set 6' Steel Fence Post) Office S 16 | S 15  
(alongside Brass Cap) 1968 S 21 | S 22  
This corner lies 150 ft. north of county road.

91

Vernon "Ray" Tracy  
Jack Heritage & V. Perron  
August 20 and 21, 1968  
C. S. File No. 49/124

1/4 Corner to Sections 27 and 28.  
Found - Orig.16", now 34" Fir Stump, N.34°W. 66.0 ft., scribe visible,  
we open higher & find scribe & reverse.  
No trace of 5/8" Iron Rod, as recorded in Ren. #36, or N.E. O.B.T.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T 25 S R 5 W  
(Set 6' Steel Fence Post) Office, 1968 1/4 S 28 | S 27  
Alongside B.C.)  
New BT: 20" D.Fir S. 74° E. 112.9 ft. mkd: "1/4 S27 CS BT".  
Note - Bearing Tree is on top of cut bank of log landing, E. of corner.  
No other trees available. Corner lies on very steep W. slope,  
clear cut all around except for seed trees to east.

92

1/4 Corner to Sections 29 and 28.  
Found - 1955 County Surveyor's Brass Cap & Stone as recorded in Ren. #37.  
Bearing Trees down.  
New BT's: 6" D.Fir N. 75° W. 19.3 ft. mkd: "1/4 S29 CS BT".  
5" D.Fir N. 48° E. 48.8 ft. mkd: "1/4 S28 CS BT".  
Note - This corner lies 4 ft. north of fence corner, fences south,  
and S.70°E. on top of ridge, course NW - SE.

93

Section Corner to Sections 26- 27 - 34 - 35.  
Found - 1960 C.S. Brass Cap, See Ren. #74.  
13" D.Fir S.66°W. 73.5 ft., alive, scribe visible on nearly hld.blaze  
New BT's: 8" D.Fir N. 23° W. 75.3 ft. mkd: T25S R5W S27 CS BT.  
8" D.Fir N. 12° E. 146.1 ft. mkd: T25S R5W S26 CS BT.  
No other trees close in Section 35.  
This corner lies 11 ft. E. of N-S fence in logged over area on S.slope of Mt.

94

Sept '68