

**Douglas County Surveyor's Record of
Government Corners Renewed**

T 25 T. S. R 5 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

(No Ren. #135)

136

1/4 Corner for Secs. 20 and 21
No trace of orig. corner post or 1 1/2" I.P. or 2" steel shaft. Ren #'s 13 and 24. Note: Considerable construction activity has taken place in this area.

Found - The only remaining orig. BT, an orig. 12" now 45" forked B. Oak dia. measured below the fork, alive with well healed orig. & rescribable blazes.

Set - An 18" now 18" W. Oak, alive with well healed single blaze. Ren. 24
At the corner point as determined by Cole in 1920 Ren. #13, and Elmer in 1947 Ren. #24, we set a 1" x 30" I.P. buried 4" below ground surface, with brass cap attached marked:

Douglas County Surveyor T 25 S
1977 S20|S21
1/4
R 5 W

*FD OK PER BAUGHMAN
VOL. 17 PG. 39 4-90*

BT's - An orig. BT, the 45" B. Oak bears S.49 3/4°E., 42.1 ft. (Rec. S.49°E. 42.9 ft.)
An 18" W. Oak bears S.42°W., 139.0 ft. (Rec. per Ren. #24, S.41°43' W., 137.94 ft.)

Corner located in level gravelled parking area, approx. 175 ft. east of a house and approx 13 ft. west of a white painted board fence.

10/18/77

137

Section Corner for Secs. 7, 8, 17 and 18.

Found - 1960 Douglas County Surveyors Office brass cap flush with ground as reset in Renewal #77.

A 36" Black Oak (24") bears N.84°W., (Rec. N.83°W.) 79.9 ft. (Rec. 81.5 ft.) with well healed double blaze. Ren. #20.

A 12" now 24" White Oak bears S.65°W., 140.4 ft. with well healed double blaze.

A 14" now 18" Madrone bears N.57°E., (Rec. N.58 1/2°E.) 38.5 ft. well healed double blaze. Ren. #65

No original BTs found. No other BTs from renewals found.

New Accessories:

An 8" Black Oak, bears S.18°E., 15.1 ft. scribed "T25S R5W S17 CS BT" in double blaze.

A fence corner bears S.8°E., 8.5 ft. Fence runs east-west and south. Corner lies in old road.

2/8/79

138

1/4 Corner for Secs. 4 and 3.

Found - A 4" x 5" Concrete block with a 3/4" bolt head set in fence line bearing S.14°E. and N.14°W. Concrete mon. set by Ecker Sept. 1947. Ecker fd. whiskey bottle and stake set by O. Thiel from original stump according to Harvey Brown, local resident. (See C.S. 40/68)

New Accessories:

A 5/8" I. Rod with alum. cap marked "B.O. 1/4 S3", bears East 25 ft. set flush with ground.

A 5/8" I. Rod with alum. cap marked "B.O. 1/4 S4" bears West 25 ft. set flush with ground.

A Fd. 5/8" I. Rod bears N.48°W., 127.2 ft. being 1.0 ft. South of a fence corner.

A 24" W. Oak bears S.21°E., 327.4 ft. scribed "1/4 S3 CS BT" in a double blaze.

Corner located in a fence line.

3/12/79

139

1/4 Corner to Secs. 10 and 15

Set - 5/8" x 30" iron rod.

BT's - 6" Fir bears S.29°W., 7.5 ft. scribed "1/4 S15 BT".

10" Fir bears N.84°W., 35.3 ft. scribed "1/4 S10 BT".

Note - The 1/4 corner was searched for but not found, and was set at its proportioned location.

Gary Langlitz
Larry Monrean
Stephen Flaue
Doug. Co. Surveyors
Office
Oct. 18, 1977
C.S. 59/40

1-79

Gary Langlitz
Karen Reed
Doug. Co. Surveyors
Office
Feb. 8, 1979
C.S. 60/24

Karen Reed
Douglas Co.
Surveyors Off.
S. J. Flaue
March 12, 1979
C.S. 60/24

*FD OK
6-91 M112-30*

Romanso E. Ware
LS# 1005
For: Revestco
June 1980
M 85 - 3