

Douglas County Surveyor's Record of
Government Corners Renewed

25 T. S. 6 R. W. W. M.

✓ SEC. COR. BET. 3-4 T. 25 S. R. 6 W and 33-34 T. 24 S., R. 6 W. **13**
Reset from one O.B.T. others down. Set 1 1/2" Iron Pipe. Remarks
12" Fir N. 14° E., 16.8 ft.
16" Fir N. 16° W., 9.2 ft.
36" Fir S. 37° E., 135.2 ft.
4" Fir S. 48° W., 46.8 ft.

✓ SEC. COR. COMMON TO SEC'S. 35, 36, 1 and 2 ON N. BDY. T. 25 S. R. 6 W. **14**
Reset from 2 original B.T.s and a stump which witnesses said bore scribe marks before a fire swept by it. Also found a third O.B.T. later. Set an Iron Pin in ground from which
A B. Oak 15" in dia. bears S. 1° E., 108 lks.
A B. Oak 14" in dia. bears N. 65° W., 177 lks. **119**
A B. Oak Stump 12" in dia. bears S. 59° W., 100.7 lks.
A B. Oak 14" in dia. bears N. 73 1/2° E., 285 lks.

✓ SEC. COR. BET. SEC. 1 and 2. **15**
Reset from 1 orig. B.T. and evidence of second B.T. Renewed cor. with an Iron Pipe 1 1/2" x 30" driven in ground from which
A B. Oak 16" in dia. bears S. 59° W., 58 lks. **117**
A B. Oak bears N. 28° E., 30 lks.

✓ S.W. COR. JOSEPH L. GILBERT CL. # 61. **16**
Reset this cor. from tie given to Sec. Cor. Put in Iron Pipe 1 1/2" x 30" and erected a mound of rock from which:
A B. Oak 6" dia. bears N. 51° E., 129 lks.
Slope distance.

✓ SEC. COR. COMMON TO SECS. 5-6-7-8. **17**
Reset from 3 B.T.s only one of which was alive and standing. Drove an Oak stake 3x3x36 in. ground and from which I marked new trees as follows:
12" Fir N. 16° E., 20.5 ft. **SEE ALSO # 50-A2**
48" Fir S. 16° E., 340 ft. **(PROBABLY OLDER THAN THIS ONE)**
10" Chingapin S. 8° 30' W., 232.2 ft. **Also see Vol 2, Page 266**
6" Oak Grub N. 71° W., 253.6 ft.

✓ SEC. COR. BET. SEC. 6 and 7. **18**
Orig. Cor. 60" Cedar, alive and standing but I marked two new B.T.s as follows:
10" W. Fir N. 36° 50' W., 21 ft.
18" W. Fir S. 56° 00' E., 52.5 ft.
One original still standing but chopped open S. 50° E. 33 ft. **148**

✓ SEC. COR. COMMON TO SECS. 23-24-25-26. **19**
One original B.T. standing in excellent shape. One Orig. B.T. chopped open; tree dying. One Orig. B.T. hollow and dying. Stump properly located for fourth B.T. badly rotted. Set 1" Iron Pipe 30" from which Original B.T.
24" B. Oak N. 41° W., 37.6 ft. **(This recorded orig. N. 45° W. 120° e N. 41° E)**
8" W. Oak S. 44° 44' W., 71.0 ft. which had apparently
30" B. Oak S. 18° 04' E., 81.7 ft. been reversed)
6" W. Oak N. 75° 40' E., 64.8 ft.

✓ S.W. CORNER D.L.C. # 58 **20**
Both original B.T.s standing and cut open one of which face is badly rotted. Other good shape. Three inch old Oak stake. Drove 3/4" Iron pipe and marked new B.T.
A 30" B.O. S. 44° 17' E., 23 ft.

✓ S.E. COR. C.L.C. # 58 and S.W. COR. D.L.C. # 59 **21**
Two Original B.T.s standing and in excellent shape. Also old oak stake. Drove 3/4" Iron Pipe.

G. G. Stewart
J. A. & Fay
Leatherwood
V. A. Baird
Geo. McGuffill
3/24/22
Mar. 9, 1912

C. W. Springer
Dep. C. S.
H. Bergh--chain
W. A. Davison
Feb. 1923

Springer
Wit.
Bergh
Davidson
F. A. Demis
Feb. 1923

G. W. Springer D. C. S.
June 28, 1923
C. A. Beeman chainman
Wit. M. F. De Costa
Robert Lehman
J. A. Cole

Ben. E. Irving Dep. Co. Sur.
Jan. 28, 1924
Witnesses
Emmett Hell
Jake Roth.
C. S. 2/25 7

RE-RENEWED, SEE CORNER NO. 105

RE-RENEWED, SEE CORNER NO. 119

RE-RENEWED, SEE CORNER NO. 117

RE-RENEWED, SEE CORNER NO. 118

RE-RENEWED, SEE CORNER NO. 91

RE-RENEWED, SEE CORNER NO. 148

RE-RENEWED, SEE CORNER NO. 120

C.S. Vol. 3 Page 138
C.S. Vol. 3 Page 139
C.S. Vol. 3 Page 139
C.S. Vol. 3 Page 139