

**Douglas County Surveyor's Record of  
Government Corners Renewed**

T. 26 S. T. S. R. 2 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Douglas Co. Surveyor's Office  
Randall Smith, Stephen Flause  
Oct. 20, 1994 - C.S. File 64/52

DOUGLAS COUNTY  
SURVEYORS OFFICE  
RANDALL SMITH &  
STEPHEN FLAUSE  
JULY, 22, 1997  
c.s. 64/75-30

Douglas County  
Surveyors Office  
Randall W. Smith  
Stephen J. Flause  
4/09/1998  
C.S. File 66/2-11

West 1/4 Corner for Section 22 only. *FD. OK, D. EDWARDS FEB. 22, 2004 148  
M 143-66*  
Found - GLO 2 1/2" Brass cap on a 1" O.D. iron pipe protruding 11"  
above a 2' dia. mound of stone. (1918 GLO) See Ren #52.

Accessories Found -

- 40" now 36" dia. 35' high D.Fir snag with a fully healed single blaze, bears N.79°E., 70.0 ft. (1918 GLO)
- 36" now 38" dia. D.Fir with a fully healed single blaze, bears S.85°E., 31.0 ft. (1918 GLO)
- 9" now 13" dia. W.Fir with a fully healed double blaze, bears N.52°E., 24.3 ft. (1967)
- 14" now 19" dia. R.Cedar with a fully healed single blaze, bears S.8°E., 13.8 ft. (1967)

New Accessories -

- 8" dia. Pine double blazed and scribed "1/4 S22 CS BT" Bears S.26°E., 25.7 ft.

Note - Corner lies approximately 400 ft. south of a gravel Rd. on a moderate north slope.

149

Closing corner Sec. 30 & 31 T26-R1

Mon. Fd.- 2 1/2" dia. brass cap on a 1 1/2" O.D. iron pipe protrudes 12" above ground. (1967)

Note: 1967 DCSO BC/IP set in error. 1967 DCSO used a 1916 resurvey BT and a brg. & dist. from 1910.

No corner stone found

Bt's Fd.- Brg's & Dist. taken from 1967 DCSO BC/IP

44" now 49" dia. D.Fir, with a fully healed single blaze, bears N.38°E., 29.4' (rec. N.40°E., 32') (1967)

14" now 13" dia. Hemlock, with a partially healed single blaze scribing visible "26S R1W S31 CS BT", bears S.34°E., 34.7' (rec. S.32°E., 34.7') 1967

12" now 17" dia. Hemlock, with a previously opened unhealed blaze scribing visible "Bt" facing N.70°W., bears S.30 1/2°E., 15.2' (rec. from 1967 S.27°E., 15.2')  
Note this is a BT marked in 1916 Mensch resurvey)

NOT A BT

8" now 10" dia. Hemlock, with a previously opened chopped out blaze, bears S.49 1/4°E., 30.9'. 1910 Bt scribing axed out in 1916.

Mon. Set- Brass cap from 1967 renewal is sawed off. I.P. now protrudes 8" above ground.

At a point determined from 1916 resurvey BT a 17" dia. Hemlock (S.70°E., 17.2') a 2 3/8" dia. brass cap on a 1 3/8" O.D. by 32" long iron pipe above ground. BC/IP is surrounded by a mound of stone.

New Accessories -

- 1967 1 1/2" O.D. iron pipe, bears N.49 1/4°E., 10.7'
- 1967 13" Hemlock, bears S.51 1/2°E., 35.1'
- 1967 49" D.Fir, bears N.41°E., 39.9'

Corner is at the bottom of a steep gully that courses west. Corner is in a old growth forrest.

see previous ren.#15

1/4 Cor. sec. 31; & S36, T26-3

150

Found - 2 1/2" dia., brass cap on a 1 1/2" O.D. iron pipe, protrudes 12" above ground, properly marked.

12" now 34" dia., down D.Fir, previously opened, rotted blaze, agrees with rec. "N.50°E., 15.8 ft." OBT

6" now 6" dia., 3 ft. high cedar staub with scribing visible S36 BT  
5" now 16" dia., D.Fir with a fully healed blaze, bears S.47°E., 24.5 ft. (Agrees with rec.) 1966 DCSO

12" now 22" dia., Cedar with a fully healed blaze, bears N.9°W., 29.6 ft. (Agrees with rec.) 1966 DCSO

New BTs - 9" dia., D.Fir, double blazed and scribed "1/4 S36 CS BT" bears S.45°W., 2.0 ft.

11" dia., D.Fir, double blazed and scribed "1/4 S31 CS BT" bears N.57°E., 9.5 ft.

*Bears  
S83°W  
5.3ft*