

Douglas County Surveyor's Record of
Government Corners Renewed

26 S T. S. 3 W R. W. W. M.

SEC. COR to 32,33 T 26 S & 4,5 T 27 S

46

Found four original B.T.s *Rev #17*

SEE 1958 G.L.O. SURVEY

- 40" B.O. N 15° W, 263.3 ft., dead & down, scribe marks visible
- 15" B.O. N 70° E, 156.4 ft., " " " " "
- 18" W. Oak, S 26° W, 158.0 ft. alive
- 24" Laurel (now 36") S 29° E, 52.1 ft. alive

$\frac{3}{4}$ " iron rod and mound of rock set for this corner and the following new B.T.s blazed and scribed.

- 24" Cedar, N 59° E 74.5 ft. T 26 S, R 3 W, S 33, C S B T
- 18" Cedar S 53° E, 21.0 ft. T 27 S, R 3 W, S 4, C S B T
- 18" Cedar, S 42° W, 46.0 ft. T 27 S, R 3 W, S 5, C S B T
- 18" Cedar, N 64° W, 89.2 ft. T 26 S, R 3 W, S 32 C S B T

$\frac{1}{4}$ COR. T 26 S, R 3 W, S 32 & T 27 S, R 3 W, S 5

47

Set by proportionate measurement

Set 1" I.P. with brass cap marked County Surveyor's Office

- T 26 S, R 3 W, $\frac{1}{2}$ S 32
- T 27 S, R 3 W, $\frac{1}{4}$ S 5

*SEARCHED FOR - NOT FOUND - FEB. 1966
CORNER FALLS IN CAT. CLEARED FIELD
VRT.*

Blazed and scribed 2 B.T.s

- 8" W. Oak, N 60° W, 19.1 ft.
- 8" W. Oak, S 53° E, 53.6 ft.

SEC. COR., T 26 S, R 3 W, S 31, 32 & T 27 S, R 3 W, S 5, 6

Gov't BRASS CAP SET AT THIS CORNER, 10-20-58 C.S. FILE 49/14

48

Found B.T. alive and standing

- 8" W. Oak (now 15") N 23° W 55 lks.

Set $\frac{3}{4}$ in. iron rod for cor. Blazed and scribed new B.T.s

- 20" Fir S 32° W 30.9 ft. Marked T 27 S, R 3 W, S 6, C S B T
- 30" B. Oak, N 45° W, 65.0 ft. Marked T 26 S, R 3 W, S 31

No other trees available.

~~Township Corner - S.W. Cor. Sec. 31, T26 3 W.~~

(DUPLICATE #94)

105

~~Reset from 3 Old B.T.s, badly deteriorated.~~

- ~~Set 1" Iron Pipe with Brass Cap 24" in ground Mkd: R4W T26S S36 S31
36" Fir bearing S 6° E. 543.8 feet T27S S1 S6 R3W
10" White Oak, bears S. 81° W. 195.8 feet.
30" White Oak, bears N. 15° W. 231.5 feet.~~

~~County Surveyor's Office~~

~~Jan. 7, 1947~~

*N. E. Richardson
Wit: Milo Godfrey & L. Kershner*

1/4 CORNER SECTIONS 10 and 15:

49

Set $\frac{1}{2}$ " Pipe for Corner by proper measurement, blaze and scribe two B. T.s

- 8" Fir S. 1 degree 38' W., 17.4 Ft. Marked $\frac{1}{4}$ s Sec. 15. B. T.

- 12" Fir N. 67 degrees 33' W., 15.6 Ft. Marked $\frac{1}{4}$ s Sec. 10 B. T.

Copper tags and tacks in roots marked RE 2741

SEE REN. #22

E 1/16 Corner SECTIONS 10 and 15:

49A

- 6" Fir S. 38 degrees W. 3.0 Ft., Marked E 1/16 Section 15.

S. W. Corner of the Thomas Shrum Donation Land Claim No. 42.

50

At point for corner a $\frac{3}{4}$ inch iron rod was found in 1951 by Ben B. Irving on a survey as filed in 38/164.

From which was found:

- An original B.T. 15 inch W. O. (now 42 inches), S. 55° W., 82.5 feet dist and in good condition.

- A new B.T. marked by Boyer, a 10 inch W. O., S. 65° W., 48.3 feet dist.

This corner is shown on a map of a survey made by Edwin Woodford around 1943 and filed in 32/10. It is shown as an I. P. on this map.

It is not known at this time if this I. P. is the same as the $\frac{3}{4}$ inch iron rod found by Mr. Irving in 1951.

SEE CORNER NO. 143

SEE C.S. FILE 38/164

*Oct. 14 1950
A. R. Evans
N.E. Richardson
D.C.S.*

*Oct. 19, 1950
BB Irving-C.S.S.
A.R. Evans-D.C.S.
R.G. Irving
E.B. Luther-Wit.*

*Oct. 19, 1950
A.R. Evans-D.C.S.
R.G. Irving-Wit.
C.S. FILE 44-61*

*A. R. Evans
Dec. 1951
C.S. FILE 41/26
M 13-31*