

Douglas County Surveyor's Record of
Government Corners Renewed

T. 26 S. T. S. R. 3 W. R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

1/4 Corner to Sections 14 and 23.

G.L.O. Survey Record 1882

Cedar Post Not found
18" Fir S. 20° E. 18 lks. Not found
30" Fir N. 60° W. 27 lks. Not found.

Set - 1" aluminum pipe by single proportionate method.
Referenced by Glen McChesney (plates & "W" nails only)

Bearing Trees: 52" Fir N. 28° E. 20.4 ft.
24" I, Cedar S. 35° W. 21.6 ft.

178

Harley E. Case & John Wilson
Weyerhaeuser Co.
May 1966
C. S. File No. 55/19

1/4 Corner to Sections 13 and 24.

G. L. O. Survey Record 1882

Post No trace
22" Fir N. 74° E. 6 lks. No trace
12" Chinq. N. 52° W. 88 lks. No trace

Set - 1" Monel Pipe for corner by single proportionate method.

Note - This supercedes the 1/4 corner set here by Curtis Price for
Weyerhaeuser Timber Co. in 1940-51 survey of section 24,
using staff compass and chain. See Ren. #88.

179

1/4 Corner to Sec. 1, T26-3W. & Sec. 6, T26-2W.

Found - 1963 Cadastral Brass Cap set in mound of stone.

Orig. 40" Fir, now sawed stump, S.88°E. 14.5 ft., shows bark scribe.

Ren.#38 - 50" Fir N.2°W. 31.0 ft., alive, shows bark scribe in poor condition.

18" Cedar S.53 1/2°E. 27.1 ft. (1963 BT.)

New BT: 9" Hemlock N. 53° W. 29.3 ft. mkd. 1/4 S 1 CS BT.

Note - This corner lies on top of ridge course N.E. & S.W. at N.E.
corner of cut-off unit.

August 11, 1967

180

V. "Ray"
Tracy &
Crew
8/11/67
C.S. File No.
64/40

1/4 Corner to Sec. 19, T26-3W. & Sec. 24, T26-4W.

Found - C. S. Brass Cap, 1959, & BT's. as recorded in Ren. #78.

9" R.Fir S. 63° E. 74.0 ft., alive, healed blaze.

4" R.Fir S. 50° W. 83.0 ft., alive, healed blaze.

Set - 6 ft. steel fence post alongside Brass Cap.

12/4/67

181

V. "Ray"
Tracy &
Crew
C.S. File
No. 54/7

Points on Range Line, T. 26 S., R's. 4 W. and 3 W.

Set - 5/8" Iron Rod on high bank of N. Umpqua River 705 ft. south
of section corner to secs. 13 & 24, R4W & Secs. 18 & 19.

Set - 5/8" Iron Rod on R/W Line old Co.Rd. #4, 50.87 ft. south of
corner on high bank, mentioned above.

Set - 5/8" Iron Rod, 525.59 ft. south of point on line mentioned
above, from which Power Pole No. 14-11 bears N. 25° W.,
3.0 ft.

See Map in Map File M 35 - 8 for points on line.

12/1967

182

Mames W.
Byron, Co.Surv.
For-Ore. St.
Game Comm.
C.S. 54/61
Map M 35 - 8

1/4 Corner to Sections 3 and 10.

Found - Remains of old scribed square post.

Orig. 36", now 44" Laurel, alive, north 17.2 ft., prev. opened &
shows frag. scribe on decayed blaze. Open lower & find "BT" scribe.

Rescribe "1/4 S 3 CS BT", below old blaze.

Orig. 8", now 24" Laurel, alive, S.65°W. 39.6 ft., we do not open.

Rescribe "1/4 S10 CS BT".

Set - Brass Cap at Cor.Mkd: County Surveyor's Office T 26 S. R 3 W.
1968 S 3
S 10

New BT's: 8" D.Fir N.12°W. 43.4 ft. mkd. "1/4 S 3 CS BT.

9" D.Fir S.19 1/2°W. 25.1 ft. mkd. "1/4 S10 CS BT.

Note - This corner lies on spur, sloping S.W. - Face measure on Orig. BT's.

6/19/68 - Set Steel Fence Post alongside Brass Cap & uncovered Brass Cap.

183

V. "Ray" Tracy
& V. Perron
April 2, 1968
C. S. File 54/7

Found OK
7/18/68 E. Bloom
M 29-12

SEPT. 68