

Douglas County Surveyor's Record of  
Government Corners Renewed

T 26

T. S. R 5

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

156

Cont. from prev. pg. (Sec. cor. for 16, 17, 20, 21)

Douglas County Surveyors  
Office  
Larry E. Monrean, Deputy  
Randall Smith  
Stephen J. Flause  
March 28, 1986  
C.S. 62/34

7" now 9" W. Oak with a fully healed double blaze bears N.16½°W.,  
23.2 ft. (Rec. N.18°W., 25.9 ft.)  
7" now 9" W. oak with a fully healed double blaze bears S.17½°E.,  
43.2 ft. (Rec. S.17°E., 40.5 ft.)  
9" now 11" W. oak with a fully healed double blaze bears S.1½°W.,  
33.7 ft. (Rec. S.3½°W., 31.5 ft.)

Note: Corner lies on the northeast slope of a knoll.  
1974 State Plane Coordinates apply to 1964 iron pipe corner  
position only.

3/28/86

SE Corner DLC #46

Found - DCSO brass cap, 1964, on a 1½" O.D. I.P. protrudes 8"  
above ground, properly mkd. BC/IP leans 0.3 ft. West.  
Ren. #100

157

Douglas County  
Surveyors office  
Randall Smith  
Stephen Flause  
August 3, 1988  
C.S. 62/55

12" now 22" dia. down and rotting Oak with rotted out blaze. No  
scribing visible. Root hole bears S.75°E., 55.7 ft. (agrees  
with record) Original BT.

13" now 15" dia. W.Oak with a fully healed single blaze bears  
N.80°W., 26.7 ft. (agrees with record. ) Ren. No. 100

9" now 11" dia. B. Oak with a fully healed double blaze bears  
N.23°E., 16.2 ft. (agrees with record) Ren. No. 100

No new monument set. 1964 Brass cap/iron pipe returned to plumb position.

New BT - 12" dia. double trunked Madrone, bark scribed "SE DLC 46 CS BT"  
scribing and dia. are on East trunk, root crown bears  
S.38½°W., 23.2 ft.

Corner lies 14 ft. North of intersection of an E-W and North running fence  
lines, in North fence line.

8/3/88

158

Southwest Corner for DLC #48

Found - 1964 2½" dia. Douglas Co. brass cap on a 1½" O.D. iron pipe  
protruding 8" above ground. Ren. #99

The center (top) of a 6" x 8" rock protrudes 3" above ground  
bears South 0.5 ft. from DCSO BC/IP. Source unknown.

(Bearings and distances taken to DCSO BC/IP:

6" now 34" dia. down dead W. oak with fully healed blazes, root  
hole bears N.66½°E., 58.1 ft. agrees well with previous renewal  
records. (possible orig. BT) We open blazes and find rescribe  
marks "SW DLC 48 CS BT" from Ren. #99. Old axe marks are found  
deep in tree near dia. of orig. scribed BT, no blazes or scribing  
found, these axe marks appear to have been made long ago by some  
one looking for scribing; center of tree is rotted out.

15" now 19" dia. W. oak with a fully healed double blaze, bears  
S.31°E., 67.6 ft. agrees with record. Ren. No. 99

Orig. 30" dia. B. oak, NOT found.

New BTs - 10" dia. W. oak double blazed and scribed "SW DLC 48 CS BT"  
bears S.3°E., 22.8 ft.

19" dia. W. oak double blazed and scribed "SW DLC 48 CS BT"  
bears S.58°E., 105.7 ft.

6/6/89

Section Corner for Secs. 1 and 12; and Secs. 6 & 7 of T.26-4

159

Found - A 2½" dia. 1964 DCSO brass cap on a 1½" O.D. iron pipe protruding  
14" above ground. BC/IP leans 6" north of plumb. Ren. #97

24" now 36" dia. B. Oak is down shows a previously opened blaze,  
no scribing visible. Root hole bears S.65°E., 372.9 ft. (Rec.  
S.63°E., 372.9 ft.) Orig. BT.

18" now 20" dia. W. Oak with a fully healed double blaze, bears  
S.50°E., 322.8 ft. (agrees with record) Ren. No. 97

20" now a double trunked 2 ft. high D. fir stump with a 20" east  
and a 13" west trunk, no blazes or scribing visible, bears  
N.81½°E., 320.0 ft. (agrees w/rec) Ren. No. 97.

New BTs - A triple trunked W. Oak double blazed and scribed "T26S R4W S7  
CS BT" on 14" northwest trunk, root crown bears S.64°E., 278.6'

14" W. Oak double blazed and scribed "T26S R4W S6 CS BT" bears  
N.88½°E., 335.5 ft.

7" W. Oak double blazed and scribed "T26S R4W S7 CS BT" bears  
S.78½°E., 396.6 ft.

Corner lies 4 ft. south of an east-west running fence lines, and approx.  
100 ft. east of a N'easterly-S'westerly bald grassy ridge.

6/26/90

Douglas County  
Surveyors Office  
Randall Smith  
Terrie Franssen  
June 26, 1990  
C.S. 64/9