

Douglas County Surveyor's Record of
Government Corners Renewed

T 26

T. S.

R 6

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97501

186

1/4 Corner for Secs. 13 and 14.

Found - Original monument not found.
1961 brass cap and iron pipe, properly mkd., set by Byron,
firmly set and protruding 16" above ground. Ren. #89

Original NE BT not found.

Orig. 15" W. oak is dead and down. Found stump shell 30" diam.
with decayed remains of trunk laying alongside (no scribing
found). Stump bears S. 62° W., 207.2 ft. (Rec. bearing
N. 59 1/4° E checks well from BT stump to cap. Agrees with
Byron's comments on local magnetic attraction near the
corner monument.)

10" now 14" W. oak with well healed double blaze bears
S. 37° E., 63.9 ft. BT situated along S.E. edge of dry
pond bed. Ren. #89

New Accessories:

SE corner of Del Rio Ranch Estates (per M33-74), a 3/4" iron rod
2 ft. southerly of fence intersection (fences running
northerly-westerly and southerly) bears S. 49 1/2° E., 139.6 ft.
Tied footing corner (not block stem wall) at south east corner
of barn bears N. 13 1/2° E., 115.3 ft. We mark southerly
face of footing "B0".

Bearings noted are based on magnetic north and observed from the corner.
The 18 1/2° declination was used, the noted local attraction should be
considered and applied if needed.

9/27/84

187

Meander Corner, Right bank, in Sections 33 and 34.

Monument position occasionally covered by high water of Umpqua River.
Monument from Ren. #104 apparently washed away. After reasonable search
of area, monument not found. No original bearing trees found.

Found - From Ren. #29, A triple white oak, 14" dia. now a 15" DBH (on
most southerly trunk) W. oak with a fully healed double
blaze bears N. 43 1/2° E., 29.4 ft. to center of most southerly
trunk at blaze height. (Rec. N. 43 1/2° E., 29.0 ft., a face
measurement.)

From Ren. #104, the brass cap monument for Sections 28, 27, 33, 34
bears North, 97.0 ft. (as per record)

Set - Using the found bearing tree, Northeast, and the found section
corner, S28 S27 S33 S34, bearing North, 97.0 ft.; the meander
corner position is reestablished. Remonumented with a DCSO
2 3/8" dia. brass cap marked "T26S R6W S33|S34 MC 1986"
on a 1 3/8" dia. 32" long galv. I.P. set protruding 5" above
ground and surrounded by a 2 ft. dia. mound of stone.

New BTs - A 4" DBH W. Oak scribed X BT bears S. 89 3/4° E., 28.7 ft.
A 9" DBH W. Oak scribed MC S33 CS BT on a double blaze bears
S. 89 1/2° W., 85.6 ft.

(See DCSO Geodetic Control Book for coordinates.)

188

Section Corner for Secs. 28, 27, 33 and 34.

Found - A 1961 DCSO 2 3/8" brass cap, properly mkd. on a 1" I.P.,
firmly set and protrudes 1" above ground. Ren. No. 91

An Orig. W. Oak 12" dia. now a 20" DBH W. Oak with a fully
healed single blaze bears S. 67 1/4° E., 175.5 ft. (Rec. S. 67 1/4° E.,
174.2 ft. possible face measure).

No other original BTs found.

A W. Oak, 10" now a 14" DBH W. Oak (called 16" in Ren. #91 when
rescribed) with a fully healed single blaze, bears N. 50° W.,
47.0 ft. (as per record) Ren. #17

A W. Oak, 10" now a 18" DBH W. Oak with a partially healed single
blaze with no scribing visible, bears S. 38° W., 54.0 ft. (per Rec)

A 10" W. Oak now a 14" DBH W. Oak with a fully healed double
blaze bears S. 50 1/2° W., 67.3 ft. (as per record. Ren. #91) No
other BTs from Ren. #91 found.

Tie to newly reset meander corner S.33 and S.34 on North bank of North
Umpqua River checked; bears South 97.0 ft. dist. as per record to position
as determined from bearing trees found.) (See Ren. #187)

New BT - A W. Oak 13" DBH scribed "T26S R6W S34 CS BT" on a double blaze
bears S. 30° E., 81.5 ft.

Monument is approx. 105 ft. North from North Bank of North Umpqua River and
approx. 35 ft. west from a north-south fenceline. See DCSO geodetic control
book for coordinates.

Douglas County Surveyor's Office
Deputies: Stephen J. Flause
R. W. Smith
December 5, 1986
C. S. 62/38

FIND. 1-91 1991-0006

Larry E. Monrean
Deputy, Doug. Co.
Surveyors Office
S. J. Flause
Sept. 27, 1984
C.S. 62/21